Form 3160-51 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**



FORM APROVED OMB NO 1004-0137 EXPIRES March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS	
not use this form for proposals to drill or to re enter an	

Lease Serial No NM 81953 Do not use this form for pre 6 If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals SUBMIT IN TRIPLICATE - Other instructions on page 2 7 Unit or CA Agreement Name and No. Type of Well Oil Well Gas Well Other SWD WELL 8 Well Name and No. Name of Operator P G 4 FEDERAL 1 **DEVON ENERGY PRODUCTION COMPANY, LP** 9 API Well No. 3a, Address 3b Phone No. (include area code) 30-015-26509 405-552-4615 20 North Broadway, Ste 1500, Oklahoma City, OK 73102 10 Field and Pool, or Exploratory Area Location of Well (Footage, Sec., T, R, M, or Survey Description) SAND DUNES WEST 900 FNL 1980 FWL 11. County or Parish, State 9 T23S R31E NM Eddy 12. CHECK APPROPRIATE BOX(es) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OS SUBMISSION TYPE OF ACTION Production (Start/Resume) Water Shut-Off Acıdize Deepen ✓ Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity Subsequent Report Casing Repair **New Construction** Recomplete Other Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Plug Back Water Disposal Convert to Injection Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work and approximate duration thereof. If the proposal pen directionally or recomplete horizontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection) RECEIVED PROPOSED PLUG & ABANDONMENT DEC 12 2011 1. MIRU. POOH w/rod string, rod pump, and 2-7/8" production tubing. NMOCD ARTESIA 2. Circulate wellbore w/9.5# mud. 3. TIH to CIBP @ 5000'. Spot 25 sx cmt. Calc. TOC @ 4847'. 4. Spot 75 sx cmt @ 4175'. WOC & Tag. (Calc. TOC @ 3715'. 9-5/8" shoe @ 4122, salt base @ 3892') 5. Perf and sgz 60 sx cmt, In/Out from 783' to 575'. (13-3/8" shoe @ 628', top of salt @ 783. Calc inside 7"=33 sx, 9-5/8" x 7" annulus=27 sx') 6. Perf and sgz 30 sx cmt, In/Out from 100' to surface. 7. Cut wellhead off 3' BGL. Set P&A marker. Accepted for Accord (proposed schemat attached) 12/12/2011 4 I hereby certify that the foregoing is true and correct Name. Ronnie Slack Title Operations Technician Date Signature THIS SPACE FOR FEDERAL OR'STATE OFFICE USE Approved by Conditions of approval, if any are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would

Office

entitle the applicant to conduct or operations thereon.



