

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N French Dr., Hobbs, NM 87240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S St Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103

June 19, 2008

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. <b>30-015-39400</b>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: <b>Nash Unit</b>
8. Well Number <b>53 SWD</b>
9. OGRID Number <b>005380</b>
10. Pool name or Wildcat <b>SWD; DELAWARE</b>

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <b>SWD</b>	7. Lease Name or Unit Agreement Name: <b>Nash Unit</b>
2. Name of Operator <b>XTO Energy, Inc.</b>	8. Well Number <b>53 SWD</b>
3. Address of Operator <b>200 N. Loraine, Ste. 800 Midland, TX 79701</b>	9. OGRID Number <b>005380</b>
4. Well Location Unit Letter <b>H</b> : <b>1620</b> feet from the <b>North</b> line and <b>1120</b> feet from the <b>East</b> line Section <b>13</b> Township <b>23S</b> Range <b>29E</b> NMPM County <b>Eddy</b>	10. Pool name or Wildcat <b>SWD; DELAWARE</b>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) <b>2999' GL</b>	

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☒ P AND A ☐  
CASING/CEMENT JOB ☒

OTHER: ☐

RECEIVED

JAN 27 2012

INMOCD ARTESIA

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

10/8/11 MIRU Pioneer Rig #33. Spud 26" hole @ 10:00 p.m. Drld to 220'. Run 20" 94# J-15 csg & cmt. w/700 sxs Cl C circ 437 sxs to surf. WOC 24 hrs.  
10/19/11 Drld to 3200' 17 1/2" hole w/13 3/8" csg 68#, K-55, cmt w/2075 sx Econo Chem, 555 sxs Halcem circ 210 bbls to surf. WOC 24 hrs.  
11/9/11 Drld to 11000' 12 1/4" hole 9 5/8" 47# csg, cmt stage 1 735 sxs Versa cmt tail 450 ss Halco Chem 'H' circ wait on Haliburton cmt. stage 2 lead 500 sxs Versa cmt tail 200 sxs Halcem 'H' stage 3 lead 730 sxs EconoCem tail w/150 sx Halcem 'C' test, WOC 24 hrs. Cut off 9 5/8" csg, install csg spool, test. RIH to 6466 tst casing. Drill DV tool, drill cmt., 5" form test csg.

Spud Date:

10/8/2011

Rig Release Date:

1/2/2012

Page 1 of 2

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Sharon Hindman TITLE Regulatory Analyst DATE 1/25/2012

sharon.hindman@xtoenergy.com

Type or print name Sharon Hindman E-mail address: sharon.hindman@xtoenergy.com PHONE 432-620-6741

For State Use Only

APPROVED BY RDade TITLE Dist #Sewiso DATE 02/22/2012

Conditions of Approval (if any):

C-103 #13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Continued

11/9/11 Csg shoe, circ mud.  
12/21/11 Drld to 14911 8 1/2" hole 7" 32# HCL-P-110 liner from 10630-14906, cmt. w/670 sxs Cl H. Set liner hanger rev out 35 bbls cmt, 167 sxs.  
12/31/11 Drld to 16500. RIH w/perm pkr on 4 1/2" tbg set @ 14810'. Run Ran GR/Neutron log.  
1/1/12 Lay down 4 1/2" pipe. Latch into packer, space out, nipple down, set B.O.P., install flange test 5K, clean pits.  
1/2/12 Clean pits, rig down gas buster rig.