

Submit 1 Copy To Appropriate District Office
District I – (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II – (575) 748-1283
811 S. First St., Artesia, NM 88210
District III – (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV – (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised August 1, 2011

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

| |
|---|
| WELL API NO. 30-015-10312 |
| 5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No. STATE 647 |
| 7. Lease Name or Unit Agreement Name STATE 647 |
| 8. Well Number 203 |
| 9. OGRID Number 274841 |
| 10. Pool name or Wildcat Artesia; Queen-Grayburg-San Andres |

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
Alamo Permian Resources, LLC

3. Address of Operator
415 W. Wall Street, Suite 500, Midland, TX 79701

4. Well Location
Unit Letter P : 330 feet from the S line and 330 feet from the E line
Section 25 Township 17S Range 28E NMPM County EDDY

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: RETURN TO PRODUCTION
☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

2-16-12

MIRU PU. POOH w/ rods and pump. Secure well and SDFN.

2-17-12

Open well up and NU BOP, pick up 2 3/8" pipe and tag bottom and tally out of the hole. First joint had a hole. RIH w/ bit and casing scraper and POOH with pipe. RIH with bailer and bail out 95 ft. of fill. Secure well and SDFN.

2-20-12

Open well up and hydro test tubing in the hole. ND BOP, NU WH, RIH with rods and new pump, and HWO. Turn well to TB and SDFN.

2-21-12

RD PU and clean location.

RECEIVED

FEB 28 2012

NMOCD ARTESIA

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Carie Stoker TITLE Regulatory Affairs Coordinator DATE 02/23/2012

Type or print name CARIE STOKER E-mail address: cstoker@alamoresources.com PHONE: 432.897.0673

APPROVED BY: [Signature] TITLE Asst. Reg. Sec. DATE 02/23/2012

Conditions of Approval (if any):