	State of New Mexico	Form C-103
<u>2.5</u>	y, Minerals and Natural Resources	October 13, 2009
1625 N. French Dr , Hobbs, NM 88240 District II		WELL API NO. 30-015-39112
1301 W Grand Ave., Artesia, NM 88210 OIL C	CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd , Aztec, NM 87410	220 South St. Francis Dr.	STATE 🛮 🦯 FEE 🗌
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		80-8096
SUNDRY NOTICES AND R		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRIL DIFFERENT RESERVOIR. USE "APPLICATION FOR P		Conoco 10 State
PROPOSALS.)	•	<u> </u>
1. Type of Well: Oil Well Gas Well 2. Name of Operator	Other	8. Well Number 2H 9. OGRID Number
OXY USA Inc.		9. OGRID Number 16696
3. Address of Operator		10. Pool name or Wildcat
P.O. Box 50250 Midland	d, TX 79710	Tunkey Track Bone Spring
4. Well Location		
Unit Letter M: 580 feet from the South line and 660 feet from the west line		
	ownship IS Range 29E	NMPM County FLLY
11. Elevati	on (Show whether DR, RKB, RT, GR, etc 3367 GR	.)
	776 GK	
12 Check Appropriate	Box to Indicate Nature of Notice,	Report or Other Data
		•
NOTICE OF INTENTION		SSEQUENT REPORT OF:
	ABANDON REMEDIAL WOR	
TEMPORARILY ABANDON ☐ CHANGE F PULL OR ALTER CASING ☐ MULTIPLE		RILLING OPNS. 🔼 PANDA 🗌
PULL OR ALTER CASING MULTIPLE DOWNHOLE COMMINGLE	COMPL CASING/CEMEN	IT JOB 💆
DOWN TOLL COMMINGLE		
OTHER:	OTHER:	
13. Describe proposed or completed operation	ons. (Clearly state all pertinent details, an	nd give pertinent dates, including estimated date
of starting any proposed work). SEE RU	JLE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.	ons. (Clearly state all pertinent details, ar JLE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
of starting any proposed work). SEÉ RU proposed completion or recompletion.	JLE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of
of starting any proposed work). SEÉ RU proposed completion or recompletion. Spud 17-1/2" hole 10/25/11, drill to 294'. RIF	JLE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of 294', cmt w/ 420sx (101bbl) PPC w/
of starting any proposed work). SEÉ RU proposed completion or recompletion.	JLE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of 294', cmt w/ 420sx (101bbl) PPC w/
of starting any proposed work). SEÉ RU proposed completion or recompletion. Spud 17-1/2" hole 10/25/11, drill to 294'. RII additives, circ 270sx (65bbl) cmt to surf. WC 10/28/11, Drill 12-1/4" hole to 3060' 11/1/11.	JLE 19.15.7.14 NMAC. For Multiple Co H & set 13-3/8" 48# H-40 STC csg @ DC. Test BOP's @ 250# low 5000# h RIH & set 9-5/8" 40# J55 LTC csg @	ompletions: Attach wellbore diagram of 294', cmt w/ 420sx (101bbl) PPC w/ high.
of starting any proposed work). SEÉ RU proposed completion or recompletion. Spud 17-1/2" hole 10/25/11, drill to 294'. RII additives, circ 270sx (65bbl) cmt to surf. WC 10/28/11, Drill 12-1/4" hole to 3060' 11/1/11. PPC w/ additives, followed by 200sx (48bbl)	JLE 19.15.7.14 NMAC. For Multiple Co H & set 13-3/8" 48# H-40 STC csg @ DC. Test BOP's @ 250# low 5000# h RIH & set 9-5/8" 40# J55 LTC csg @	ompletions: Attach wellbore diagram of 294', cmt w/ 420sx (101bbl) PPC w/ aigh. 3060', cmt w/ 960sx (317bbl) HLS by cmt to surf. WOC. Test BOP's to
of starting any proposed work). SEÉ RU proposed completion or recompletion. Spud 17-1/2" hole 10/25/11, drill to 294'. RII additives, circ 270sx (65bbl) cmt to surf. WC 10/28/11, Drill 12-1/4" hole to 3060' 11/1/11.	JLE 19.15.7.14 NMAC. For Multiple Co H & set 13-3/8" 48# H-40 STC csg @ DC. Test BOP's @ 250# low 5000# h RIH & set 9-5/8" 40# J55 LTC csg @	ompletions: Attach wellbore diagram of 294', cmt w/ 420sx (101bbl) PPC w/ high.
of starting any proposed work). SEÉ RU proposed completion or recompletion. Spud 17-1/2" hole 10/25/11, drill to 294'. RII additives, circ 270sx (65bbl) cmt to surf. WC 10/28/11, Drill 12-1/4" hole to 3060' 11/1/11. PPC w/ additives, followed by 200sx (48bbl) 250# low, 5000#.	JLE 19.15.7.14 NMAC. For Multiple Co H & set 13-3/8" 48# H-40 STC csg @ DC. Test BOP's @ 250# low 5000# h RIH & set 9-5/8" 40# J55 LTC csg @	294', cmt w/ 420sx (101bbl) PPC w/ nigh. 3060', cmt w/ 960sx (317bbl) HLS cmt to surf. WOC. Test BOP's to RECEIVED
of starting any proposed work). SEÉ RU proposed completion or recompletion. Spud 17-1/2" hole 10/25/11, drill to 294'. RII additives, circ 270sx (65bbl) cmt to surf. WC 10/28/11, Drill 12-1/4" hole to 3060' 11/1/11. PPC w/ additives, followed by 200sx (48bbl)	JLE 19.15.7.14 NMAC. For Multiple Co H & set 13-3/8" 48# H-40 STC csg @ DC. Test BOP's @ 250# low 5000# h RIH & set 9-5/8" 40# J55 LTC csg @	ompletions: Attach wellbore diagram of 294', cmt w/ 420sx (101bbl) PPC w/ aigh. 3060', cmt w/ 960sx (317bbl) HLS by cmt to surf. WOC. Test BOP's to
of starting any proposed work). SEÉ RU proposed completion or recompletion. Spud 17-1/2" hole 10/25/11, drill to 294'. RII additives, circ 270sx (65bbl) cmt to surf. WC 10/28/11, Drill 12-1/4" hole to 3060' 11/1/11. PPC w/ additives, followed by 200sx (48bbl) 250# low, 5000#.	JLE 19.15.7.14 NMAC. For Multiple Co H & set 13-3/8" 48# H-40 STC csg @ DC. Test BOP's @ 250# low 5000# h RIH & set 9-5/8" 40# J55 LTC csg @	294', cmt w/ 420sx (101bbl) PPC w/ high. 3060', cmt w/ 960sx (317bbl) HLS I) cmt to surf. WOC. Test BOP's to RECEIVED NOV 3 0 2011
of starting any proposed work). SEÉ RU proposed completion or recompletion. Spud 17-1/2" hole 10/25/11, drill to 294'. RII additives, circ 270sx (65bbl) cmt to surf. WC 10/28/11, Drill 12-1/4" hole to 3060' 11/1/11. PPC w/ additives, followed by 200sx (48bbl) 250# low, 5000#.	JLE 19.15.7.14 NMAC. For Multiple Co H & set 13-3/8" 48# H-40 STC csg @ DC. Test BOP's @ 250# low 5000# h RIH & set 9-5/8" 40# J55 LTC csg @	294', cmt w/ 420sx (101bbl) PPC w/ nigh. 3060', cmt w/ 960sx (317bbl) HLS cmt to surf. WOC. Test BOP's to RECEIVED
of starting any proposed work). SEÉ RU proposed completion or recompletion. Spud 17-1/2" hole 10/25/11, drill to 294'. RII additives, circ 270sx (65bbl) cmt to surf. WC 10/28/11, Drill 12-1/4" hole to 3060' 11/1/11. PPC w/ additives, followed by 200sx (48bbl) 250# low, 5000#.	JLE 19.15.7.14 NMAC. For Multiple Co H & set 13-3/8" 48# H-40 STC csg @ DC. Test BOP's @ 250# low 5000# h RIH & set 9-5/8" 40# J55 LTC csg @	294', cmt w/ 420sx (101bbl) PPC w/ high. 3060', cmt w/ 960sx (317bbl) HLS I) cmt to surf. WOC. Test BOP's to RECEIVED NOV 3 0 2011
of starting any proposed work). SEE RU proposed completion or recompletion. Spud 17-1/2" hole 10/25/11, drill to 294'. RII additives, circ 270sx (65bbl) cmt to surf. WC 10/28/11, Drill 12-1/4" hole to 3060' 11/1/11. PPC w/ additives, followed by 200sx (48bbl) 250# low, 5000#. 11/4/11, Drill 8-1/2" production hole.	JLE 19.15.7.14 NMAC. For Multiple Co H & set 13-3/8" 48# H-40 STC csg @ DC. Test BOP's @ 250# low 5000# h RIH & set 9-5/8" 40# J55 LTC csg @ PPC w/ additives, circ 318sx (105bb	294', cmt w/ 420sx (101bbl) PPC w/ high. 3060', cmt w/ 960sx (317bbl) HLS I) cmt to surf. WOC. Test BOP's to RECEIVED NOV 3 0 2011
of starting any proposed work). SEE RU proposed completion or recompletion. Spud 17-1/2" hole 10/25/11, drill to 294'. RII additives, circ 270sx (65bbl) cmt to surf. WC 10/28/11, Drill 12-1/4" hole to 3060' 11/1/11. PPC w/ additives, followed by 200sx (48bbl) 250# low, 5000#. 11/4/11, Drill 8-1/2" production hole.	JLE 19.15.7.14 NMAC. For Multiple Condition of the Policy	294', cmt w/ 420sx (101bbl) PPC w/ nigh. 3060', cmt w/ 960sx (317bbl) HLS I) cmt to surf. WOC. Test BOP's to RECEIVED NOV 3 0 2011 NMOCD ARTESIA
of starting any proposed work). SEE RU proposed completion or recompletion. Spud 17-1/2" hole 10/25/11, drill to 294'. RII additives, circ 270sx (65bbl) cmt to surf. WC 10/28/11, Drill 12-1/4" hole to 3060' 11/1/11. PPC w/ additives, followed by 200sx (48bbl) 250# low, 5000#. 11/4/11, Drill 8-1/2" production hole.	JLE 19.15.7.14 NMAC. For Multiple Condition of the Policy	294', cmt w/ 420sx (101bbl) PPC w/ nigh. 3060', cmt w/ 960sx (317bbl) HLS I) cmt to surf. WOC. Test BOP's to RECEIVED NOV 3 0 2011 NMOCD ARTESIA
of starting any proposed work). SEE RU proposed completion or recompletion. Spud 17-1/2" hole 10/25/11, drill to 294'. RII additives, circ 270sx (65bbl) cmt to surf. WC 10/28/11, Drill 12-1/4" hole to 3060' 11/1/11. PPC w/ additives, followed by 200sx (48bbl) 250# low, 5000#. 11/4/11, Drill 8-1/2" production hole.	JLE 19.15.7.14 NMAC. For Multiple Condition of the Policy	294', cmt w/ 420sx (101bbl) PPC w/ nigh. 3060', cmt w/ 960sx (317bbl) HLS I) cmt to surf. WOC. Test BOP's to RECEIVED NOV 3 0 2011 NMOCD ARTESIA
of starting any proposed work). SEE RU proposed completion or recompletion. Spud 17-1/2" hole 10/25/11, drill to 294'. RII additives, circ 270sx (65bbl) cmt to surf. WC 10/28/11, Drill 12-1/4" hole to 3060' 11/1/11. PPC w/ additives, followed by 200sx (48bbl) 250# low, 5000#. 11/4/11, Drill 8-1/2" production hole.	JLE 19.15.7.14 NMAC. For Multiple Condition of the Policy	294', cmt w/ 420sx (101bbl) PPC w/ high. 2 3060', cmt w/ 960sx (317bbl) HLS 3 cmt to surf. WOC. Test BOP's to RECEIVED NOV 3 0 2011 NMOCD ARTESIA
of starting any proposed work). SEE RU proposed completion or recompletion. Spud 17-1/2" hole 10/25/11, drill to 294'. RII additives, circ 270sx (65bbl) cmt to surf. WC 10/28/11, Drill 12-1/4" hole to 3060' 11/1/11. PPC w/ additives, followed by 200sx (48bbl) 250# low, 5000#. 11/4/11, Drill 8-1/2" production hole. Spud Date:	H & set 13-3/8" 48# H-40 STC csg @ DC. Test BOP's @ 250# low 5000# h RIH & set 9-5/8" 40# J55 LTC csg @ PPC w/ additives, circ 318sx (105bb) Rig Release Date:	294', cmt w/ 420sx (101bbl) PPC w/ sigh. 2 3060', cmt w/ 960sx (317bbl) HLS 1) cmt to surf. WOC. Test BOP's to RECEIVED NOV 3 0 2011 NMOCD ARTESIA ge and belief.
of starting any proposed work). SEE RU proposed completion or recompletion. Spud 17-1/2" hole 10/25/11, drill to 294'. Rlf additives, circ 270sx (65bbl) cmt to surf. WC 10/28/11, Drill 12-1/4" hole to 3060' 11/1/11. PPC w/ additives, followed by 200sx (48bbl) 250# low, 5000#. 11/4/11, Drill 8-1/2" production hole. Spud Date: I hereby certify that the information above is true SIGNATURE Type or print nameDavid Stewart	H & set 13-3/8" 48# H-40 STC csg @ DC. Test BOP's @ 250# low 5000# h RIH & set 9-5/8" 40# J55 LTC csg @ PPC w/ additives, circ 318sx (105bb) Rig Release Date:	294', cmt w/ 420sx (101bbl) PPC w/ high. 2 3060', cmt w/ 960sx (317bbl) HLS 3 cmt to surf. WOC. Test BOP's to RECEIVED NOV 3 0 2011 NMOCD ARTESIA
of starting any proposed work). SEE RU proposed completion or recompletion. Spud 17-1/2" hole 10/25/11, drill to 294'. Rlf additives, circ 270sx (65bbl) cmt to surf. WC 10/28/11, Drill 12-1/4" hole to 3060' 11/1/11. PPC w/ additives, followed by 200sx (48bbl) 250# low, 5000#. 11/4/11, Drill 8-1/2" production hole. Spud Date: I hereby certify that the information above is true SIGNATURE Type or print nameDavid Stewart For State Use Only	H & set 13-3/8" 48# H-40 STC csg @ DC. Test BOP's @ 250# low 5000# h RIH & set 9-5/8" 40# J55 LTC csg @ PPC w/ additives, circ 318sx (105bb) Rig Release Date:	294', cmt w/ 420sx (101bbl) PPC w/ sigh. 2 3060', cmt w/ 960sx (317bbl) HLS 1) cmt to surf. WOC. Test BOP's to RECEIVED NOV 3 0 2011 NMOCD ARTESIA ge and belief.
of starting any proposed work). SEE RU proposed completion or recompletion. Spud 17-1/2" hole 10/25/11, drill to 294'. Rlf additives, circ 270sx (65bbl) cmt to surf. WC 10/28/11, Drill 12-1/4" hole to 3060' 11/1/11. PPC w/ additives, followed by 200sx (48bbl) 250# low, 5000#. 11/4/11, Drill 8-1/2" production hole. Spud Date: I hereby certify that the information above is true SIGNATURE Type or print nameDavid Stewart	H & set 13-3/8" 48# H-40 STC csg @ DC. Test BOP's @ 250# low 5000# h RIH & set 9-5/8" 40# J55 LTC csg @ PPC w/ additives, circ 318sx (105bb) Rig Release Date:	294', cmt w/ 420sx (101bbl) PPC w/ sigh. 2 3060', cmt w/ 960sx (317bbl) HLS 1) cmt to surf. WOC. Test BOP's to RECEIVED NOV 3 0 2011 NMOCD ARTESIA ge and belief.