Office ,	State of New Me	XICO		Form C-103
District I	Energy, Minerals and Natur	ral Resources		June 19, 2008
1625 N French Dr , Hobbs, NM 88240 District II		•	WELL API NO.	20265
1301 W Grand Ave, Artesia, NM 88210 OIL CONSERVATION DIVISION		DIVISION	30-015-39365 5. Indicate Type of Lease	
<u>District III</u> 1220 South St. Francis Dr.		STATE FEE		
. 1000 Rio Brazos Rd , Aztec, NM 87410 District IV	Santa Fe, NM 87	505	6. State Oil & Gas L	
1220 S. St. Francis Dr., Santa Fe, NM	· · · · · · · · · · · · · · · · · · ·		o. State on a das E	sease ivo.
87505	270 1112 270 270 270 2111			
SUNDRY NOTIC (DO NOT USE THIS FORM FOR PROPOS	CES AND REPORTS ON WELLS	IC DACK TO A	7. Lease Name or U	nit Agreement Name
DIFFERENT RESERVOIR. USE "APPLIC			E a1	4 DWILL 20
PROPOSALS)		Emerald PWU 20 8. Well Number		
1. Type of Well: Oil Well	Gas Well Other		3H	1
2. Name of Operator		9. OGRID Number		
Devon Energy Production Co., LP		6137		
· 3. Address of Operator		10. Pool name or Wildcat		
20 North Broadway, OKC OK 73102-8260		Scanlon Draw; Bone Spring		
4. Well Location			<u> </u>	
!	2145 feet from the South	line and 330	feet from the West	line
	wnship 19S Range 29E	NMPM	Eddy County, NN	
Latina Carteria Carteria Carteria Carteria	11. Elevation (Show whether DR,			South the state of the state of
	3324' GL	RRD, RI, OR, etc.		
To any services A majority and part and a part, properly a standard particular and a service of a	1	····		and seek of the property of a seek of the seek of the seek
12 Chack A	ppropriate Box to Indicate Na	ature of Notice	Papart or Other De	oto
12. Check A	ppropriate box to indicate Na	ature of Notice,	Report of Other Da	ata
NOTICE OF IN	TENTION TO:	SUB	SEQUENT REPO	ORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR		LTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR	ILLING OPNS. P	AND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN		_
DOWNHOLE COMMINGLE				,
14. 1. A				
OTHER DIE	1	OTHER.		
OTHER: Drilling Operations		OTHER:		
13. Describe proposed or compl	eted operations. (Clearly state all p	ertinent details, an		
13. Describe proposed or compl of starting any proposed wo		ertinent details, an		
13. Describe proposed or compl	eted operations. (Clearly state all p	ertinent details, an		
13. Describe proposed or compl of starting any proposed wo	eted operations. (Clearly state all p	ertinent details, an		
13. Describe proposed or complor of starting any proposed wor or recompletion. 02/09/12 MIRU. TD 26" hole, set 20" I	eted operations. (Clearly state all prk). SEE RULE 1103. For Multiple-	ertinent details, an e Completions: At 23 sx redi-mix.	ttach wellbore diagram	of proposed completion
of starting any proposed work or recompletion. 02/09/12 MIRU. TD 26" hole, set 20" I 02/22/12: TD 17 1/2" hole @ 300'. Ran	eted operations. (Clearly state all prk). SEE RULE 1103. For Multiple-	ertinent details, an e Completions: At 23 sx redi-mix.	ttach wellbore diagram	of proposed completion
of starting any proposed work or recompletion. 02/09/12 MIRU. TD 26" hole, set 20" I 02/22/12: TD 17 1/2" hole @ 300'. Ran sx to surf. WOC 24 hrs.	eted operations. (Clearly state all prk). SEE RULE 1103. For Multiple-	ertinent details, an e Completions: At 23 sx redi-mix.	ttach wellbore diagram	of proposed completion
of starting any proposed or completion. 02/09/12 MIRU. TD 26" hole, set 20" I 02/22/12: TD 17 1/2" hole @ 300'. Ran sx to surf. WOC 24 hrs. 02/23/12 Test csg to 1200 psi - ok	eted operations. (Clearly state all prk). SEE RULE 1103. For Multiple H-40 ST&C conductor @ 90', cmt w/12 in 6 jts 13 3/8" 48# ST&C csg @ 300'.	ertinent details, an e Completions: At 23 sx redi-mix. Cmt w/500 sx Cl C.	ttach wellbore diagram Maintain circ throughou	of proposed completion ut job, full returns. Circ 187
of starting any proposed work or recompletion. 02/09/12 MIRU. TD 26" hole, set 20" I 02/22/12: TD 17 1/2" hole @ 300'. Ran sx to surf. WOC 24 hrs.	eted operations. (Clearly state all prk). SEE RULE 1103. For Multiple H-40 ST&C conductor @ 90', cmt w/12 in 6 jts 13 3/8" 48# ST&C csg @ 300'.	ertinent details, an e Completions: At 23 sx redi-mix. Cmt w/500 sx Cl C.	ttach wellbore diagram Maintain circ throughou	of proposed completion ut job, full returns. Circ 187
13. Describe proposed or completion of starting any proposed work or recompletion. 02/09/12 MIRU. TD 26" hole, set 20" I 02/22/12: TD 17 1/2" hole @ 300'. Ran sx to surf. WOC 24 hrs. 02/23/12 Test csg to 1200 psi - ok 02/27/12: TD 12 1/4" hole @ 2,500'. Rasurf. WOC 24 hrs 02/28/12: Tst csg to 1500 psi for 30 min	eted operations. (Clearly state all prk). SEE RULE 1103. For Multiple H-40 ST&C conductor @ 90', cmt w/12 in 6 jts 13 3/8" 48# ST&C csg @ 300'. an 55 jts 9 5/8" 40# J-55 LT&C csg set — ok; test good. Circ & perform F.I.T.to	ertinent details, an e Completions: At 23 sx redi-mix. Cmt w/500 sx Cl C. @ 2,500'. Cmt w/1'.	ttach wellbore diagram Maintain circ throughou 135 sx Cl C cmt Full retu st good, no leak off.	of proposed completion at job, full returns. Circ 187 arms thru out job, 380 sx to
13. Describe proposed or completion of starting any proposed work or recompletion. 02/09/12 MIRU. TD 26" hole, set 20" I 02/22/12: TD 17 1/2" hole @ 300'. Ran sx to surf. WOC 24 hrs. 02/23/12 Test csg to 1200 psi - ok 02/27/12: TD 12 1/4" hole @ 2,500'. Rasurf. WOC 24 hrs 02/28/12: Tst csg to 1500 psi for 30 min 03/18/12: TD 8 3/4" hole @ 12,303'. Ra	eted operations. (Clearly state all prk). SEE RULE 1103. For Multiple H-40 ST&C conductor @ 90', cmt w/12 in 6 jts 13 3/8" 48# ST&C csg @ 300'. An 55 jts 9 5/8" 40# J-55 LT&C csg set — ok; test good. Circ & perform F.I.T.ton 156 jts 5 ½" 17# P-110 LT&C csg &	ertinent details, an e Completions: At 23 sx redi-mix. Cmt w/500 sx Cl C. 2,500'. Cmt w/1' 9.0 ppg E.M.W, tes	Maintain circ throughousts sx Cl C cmt Full retust good, no leak off.	of proposed completion at job, full returns. Circ 187 arns thru out job, 380 sx to 3'. Cmt 1 st stage w/300 sx
13. Describe proposed or completion of starting any proposed work or recompletion. 02/09/12 MIRU. TD 26" hole, set 20" I 02/22/12: TD 17 1/2" hole @ 300'. Ran sx to surf. WOC 24 hrs. 02/23/12 Test csg to 1200 psi - ok 02/27/12: TD 12 1/4" hole @ 2,500'. Rasurf. WOC 24 hrs 02/28/12: Tst csg to 1500 psi for 30 min 03/18/12: TD 8 3/4" hole @ 12,303'. Ra Cl H, tail w/500 sx Cl H. Full	eted operations. (Clearly state all prk). SEE RULE 1103. For Multiple H-40 ST&C conductor @ 90', cmt w/12 in 6 jts 13 3/8" 48# ST&C csg @ 300'. an 55 jts 9 5/8" 40# J-55 LT&C csg set — ok; test good. Circ & perform F.I.T.ton 156 jts 5 ½" 17# P-110 LT&C csg & returns. Cmt Stage 2 lead w/1350 sx C	ertinent details, an e Completions: At 23 sx redi-mix. Cmt w/500 sx Cl C. 2,500'. Cmt w/1' 9.0 ppg E.M.W, tes	Maintain circ throughousts sx Cl C cmt Full retust good, no leak off.	of proposed completion at job, full returns. Circ 187 arns thru out job, 380 sx to 3'. Cmt 1 st stage w/300 sx
13. Describe proposed or completion of starting any proposed work or recompletion. 02/09/12 MIRU. TD 26" hole, set 20" I 02/22/12: TD 17 1/2" hole @ 300'. Ran sx to surf. WOC 24 hrs. 02/23/12 Test csg to 1200 psi - ok 02/27/12: TD 12 1/4" hole @ 2,500'. Rasurf. WOC 24 hrs 02/28/12: Tst csg to 1500 psi for 30 min 03/18/12: TD 8 3/4" hole @ 12,303'. Ra	eted operations. (Clearly state all prk). SEE RULE 1103. For Multiple H-40 ST&C conductor @ 90', cmt w/12 in 6 jts 13 3/8" 48# ST&C csg @ 300'. an 55 jts 9 5/8" 40# J-55 LT&C csg set — ok; test good. Circ & perform F.I.T.ton 156 jts 5 ½" 17# P-110 LT&C csg & returns. Cmt Stage 2 lead w/1350 sx C	ertinent details, an e Completions: At 23 sx redi-mix. Cmt w/500 sx Cl C. 2,500'. Cmt w/1' 9.0 ppg E.M.W, tes	Maintain circ throughousts sx Cl C cmt Full retust good, no leak off.	of proposed completion at job, full returns. Circ 187 arns thru out job, 380 sx to 3'. Cmt 1st stage w/300 sx lace w/fresh wtr, bmp plug,
13. Describe proposed or completion of starting any proposed work or recompletion. 02/09/12 MIRU. TD 26" hole, set 20" I 02/22/12: TD 17 1/2" hole @ 300'. Ran sx to surf. WOC 24 hrs. 02/23/12 Test csg to 1200 psi - ok 02/27/12: TD 12 1/4" hole @ 2,500'. Rasurf. WOC 24 hrs 02/28/12: Tst csg to 1500 psi for 30 min 03/18/12: TD 8 3/4" hole @ 12,303'. RaCl H, tail w/500 sx Cl H. Full bleed off, floats held. WOC 24	eted operations. (Clearly state all prk). SEE RULE 1103. For Multiple H-40 ST&C conductor @ 90', cmt w/12 in 6 jts 13 3/8" 48# ST&C csg @ 300'. an 55 jts 9 5/8" 40# J-55 LT&C csg set — ok; test good. Circ & perform F.I.T.ton 156 jts 5 ½" 17# P-110 LT&C csg & returns. Cmt Stage 2 lead w/1350 sx C	ertinent details, an e Completions: At 23 sx redi-mix. Cmt w/500 sx Cl C. 2,500'. Cmt w/1' 9.0 ppg E.M.W, tes	Maintain circ throughousts sx Cl C cmt Full retust good, no leak off.	of proposed completion at job, full returns. Circ 187 arns thru out job, 380 sx to 3'. Cmt 1st stage w/300 sx lace w/fresh wtr, bmp plug,
13. Describe proposed or completion of starting any proposed work or recompletion. 02/09/12 MIRU. TD 26" hole, set 20" I 02/22/12: TD 17 1/2" hole @ 300'. Ran sx to surf. WOC 24 hrs. 02/23/12 Test csg to 1200 psi - ok 02/27/12: TD 12 1/4" hole @ 2,500'. Rasurf. WOC 24 hrs 02/28/12: Tst csg to 1500 psi for 30 min 03/18/12: TD 8 3/4" hole @ 12,303'. RaCl H, tail w/500 sx Cl H. Full bleed off, floats held. WOC 24/03/19/11. Rig rlsd	eted operations. (Clearly state all prk). SEE RULE 1103. For Multiple H-40 ST&C conductor @ 90', cmt w/12 in 6 jts 13 3/8" 48# ST&C csg @ 300'. An 55 jts 9 5/8" 40# J-55 LT&C csg set — ok; test good. Circ & perform F.I.T.ton 156 jts 5 ½" 17# P-110 LT&C csg & returns. Cmt Stage 2 lead w/1350 sx C 4 hrs.	ertinent details, an e Completions: At 23 sx redi-mix. Cmt w/500 sx Cl C. 2,500'. Cmt w/1! 9.0 ppg E.M.W, tes 114 jts 5 ½" 17# P-1 C cmt, tail w/150 C	Maintain circ throughousts sx Cl C cmt Full retust good, no leak off.	of proposed completion at job, full returns. Circ 187 arms thru out job, 380 sx to 3'. Cmt 1st stage w/300 sx lace w/fresh wtr, bmp plug, RECEIVED
13. Describe proposed or completion of starting any proposed work or recompletion. 02/09/12 MIRU. TD 26" hole, set 20" I 02/22/12: TD 17 1/2" hole @ 300'. Ran sx to surf. WOC 24 hrs. 02/23/12 Test csg to 1200 psi - ok 02/27/12: TD 12 1/4" hole @ 2,500'. Rasurf. WOC 24 hrs 02/28/12: Tst csg to 1500 psi for 30 min 03/18/12: TD 8 3/4" hole @ 12,303'. RaCl H, tail w/500 sx Cl H. Full bleed off, floats held. WOC 24	eted operations. (Clearly state all prk). SEE RULE 1103. For Multiple H-40 ST&C conductor @ 90', cmt w/12 in 6 jts 13 3/8" 48# ST&C csg @ 300'. an 55 jts 9 5/8" 40# J-55 LT&C csg set — ok; test good. Circ & perform F.I.T.ton 156 jts 5 ½" 17# P-110 LT&C csg & returns. Cmt Stage 2 lead w/1350 sx C	ertinent details, an e Completions: At 23 sx redi-mix. Cmt w/500 sx Cl C. 2,500'. Cmt w/1! 9.0 ppg E.M.W, tes 114 jts 5 ½" 17# P-1 C cmt, tail w/150 C	Maintain circ throughousts sx Cl C cmt Full retust good, no leak off.	of proposed completion at job, full returns. Circ 187 arns thru out job, 380 sx to 3'. Cmt 1st stage w/300 sx lace w/fresh wtr, bmp plug,
13. Describe proposed or completion of starting any proposed work or recompletion. 02/09/12 MIRU. TD 26" hole, set 20" I 02/22/12: TD 17 1/2" hole @ 300'. Ran sx to surf. WOC 24 hrs. 02/23/12 Test csg to 1200 psi - ok 02/27/12: TD 12 1/4" hole @ 2,500'. Rasurf. WOC 24 hrs 02/28/12: Tst csg to 1500 psi for 30 min 03/18/12: TD 8 3/4" hole @ 12,303'. RaCl H, tail w/500 sx Cl H. Full bleed off, floats held. WOC 24/03/19/11. Rig rlsd	eted operations. (Clearly state all prk). SEE RULE 1103. For Multiple H-40 ST&C conductor @ 90', cmt w/12 in 6 jts 13 3/8" 48# ST&C csg @ 300'. An 55 jts 9 5/8" 40# J-55 LT&C csg set — ok; test good. Circ & perform F.I.T.ton 156 jts 5 ½" 17# P-110 LT&C csg & returns. Cmt Stage 2 lead w/1350 sx C 4 hrs.	ertinent details, an e Completions: At 23 sx redi-mix. Cmt w/500 sx Cl C. 2,500'. Cmt w/1! 9.0 ppg E.M.W, tes 114 jts 5 ½" 17# P-1 C cmt, tail w/150 C	Maintain circ throughousts sx Cl C cmt Full retust good, no leak off.	of proposed completion at job, full returns. Circ 187 arns thru out job, 380 sx to 3'. Cmt 1st stage w/300 sx lace w/fresh wtr, bmp plug, RECEIVED MAR 2 8 2012
13. Describe proposed or completion of starting any proposed work or recompletion. 02/09/12 MIRU. TD 26" hole, set 20" I 02/22/12: TD 17 1/2" hole @ 300'. Ran sx to surf. WOC 24 hrs. 02/23/12 Test csg to 1200 psi - ok 02/27/12: TD 12 1/4" hole @ 2,500'. Rasurf. WOC 24 hrs 02/28/12: Tst csg to 1500 psi for 30 min 03/18/12: TD 8 3/4" hole @ 12,303'. RaCl H, tail w/500 sx Cl H. Full bleed off, floats held. WOC 24/03/19/11. Rig rlsd	eted operations. (Clearly state all prk). SEE RULE 1103. For Multiple H-40 ST&C conductor @ 90', cmt w/12 in 6 jts 13 3/8" 48# ST&C csg @ 300'. An 55 jts 9 5/8" 40# J-55 LT&C csg set — ok; test good. Circ & perform F.I.T.ton 156 jts 5 ½" 17# P-110 LT&C csg & returns. Cmt Stage 2 lead w/1350 sx C 4 hrs.	ertinent details, an e Completions: At 23 sx redi-mix. Cmt w/500 sx Cl C. 2,500'. Cmt w/1! 9.0 ppg E.M.W, tes 114 jts 5 ½" 17# P-1 C cmt, tail w/150 C	Maintain circ throughousts sx Cl C cmt Full retust good, no leak off.	of proposed completion at job, full returns. Circ 187 arms thru out job, 380 sx to 3'. Cmt 1st stage w/300 sx lace w/fresh wtr, bmp plug, RECEIVED
of starting any proposed or complosed for completion. 02/09/12 MIRU. TD 26" hole, set 20" I 02/22/12: TD 17 1/2" hole @ 300'. Ran sx to surf. WOC 24 hrs. 02/23/12 Test csg to 1200 psi - ok 02/27/12: TD 12 1/4" hole @ 2,500'. Rasurf. WOC 24 hrs 02/28/12: Tst csg to 1500 psi for 30 min 03/18/12: TD 8 3/4" hole @ 12,303'. RaCl H, tail w/500 sx Cl H. Full bleed off, floats held. WOC 2-03/19/11. Rig rlsd Spud Date:	eted operations. (Clearly state all prk). SEE RULE 1103. For Multiple H-40 ST&C conductor @ 90', cmt w/12 in 6 jts 13 3/8" 48# ST&C csg @ 300'. an 55 jts 9 5/8" 40# J-55 LT&C csg set — ok; test good. Circ & perform F.I.T.ton 156 jts 5 ½" 17# P-110 LT&C csg & returns. Cmt Stage 2 lead w/1350 sx C 4 hrs. Rig Release Da	ertinent details, an e Completions: At e Completions: At 23 sx redi-mix. Cmt w/500 sx Cl C. 2,500'. Cmt w/1' 0 9.0 ppg E.M.W, tes 114 jts 5 ½" 17# P-1 C cmt, tail w/150 C	ttach wellbore diagram Maintain circ throughou St good, no leak off. 110 BT&C csg @ 12,303 1 C cmt. Drop plug, displ	of proposed completion at job, full returns. Circ 187 arns thru out job, 380 sx to 3'. Cmt 1st stage w/300 sx lace w/fresh wtr, bmp plug, RECEIVED MAR 2 8 2012
13. Describe proposed or completion of starting any proposed work or recompletion. 02/09/12 MIRU. TD 26" hole, set 20" I 02/22/12: TD 17 1/2" hole @ 300'. Ran sx to surf. WOC 24 hrs. 02/23/12 Test csg to 1200 psi - ok 02/27/12: TD 12 1/4" hole @ 2,500'. Rasurf. WOC 24 hrs 02/28/12: Tst csg to 1500 psi for 30 min 03/18/12: TD 8 3/4" hole @ 12,303'. RaCl H, tail w/500 sx Cl H. Full bleed off, floats held. WOC 24/03/19/11. Rig rlsd	eted operations. (Clearly state all prk). SEE RULE 1103. For Multiple H-40 ST&C conductor @ 90', cmt w/12 in 6 jts 13 3/8" 48# ST&C csg @ 300'. an 55 jts 9 5/8" 40# J-55 LT&C csg set — ok; test good. Circ & perform F.I.T.ton 156 jts 5 ½" 17# P-110 LT&C csg & returns. Cmt Stage 2 lead w/1350 sx C 4 hrs. Rig Release Da	ertinent details, an e Completions: At e Completions: At 23 sx redi-mix. Cmt w/500 sx Cl C. 2,500'. Cmt w/1' 0 9.0 ppg E.M.W, tes 114 jts 5 ½" 17# P-1 C cmt, tail w/150 C	ttach wellbore diagram Maintain circ throughou St good, no leak off. 110 BT&C csg @ 12,303 1 C cmt. Drop plug, displ	of proposed completion at job, full returns. Circ 187 arns thru out job, 380 sx to 3'. Cmt 1st stage w/300 sx lace w/fresh wtr, bmp plug, RECEIVED MAR 2 8 2012
of starting any proposed or completion. 02/09/12 MIRU. TD 26" hole, set 20" I 02/22/12: TD 17 1/2" hole @ 300'. Ran sx to surf. WOC 24 hrs. 02/23/12 Test csg to 1200 psi - ok 02/27/12: TD 12 1/4" hole @ 2,500'. Rasurf. WOC 24 hrs 02/28/12: Tst csg to 1500 psi for 30 min 03/18/12: TD 8 3/4" hole @ 12,303'. RaCl H, tail w/500 sx Cl H. Full bleed off, floats held. WOC 2-03/19/11. Rig rlsd Spud Date:	eted operations. (Clearly state all prk). SEE RULE 1103. For Multiple H-40 ST&C conductor @ 90', cmt w/12 in 6 jts 13 3/8" 48# ST&C csg @ 300'. In 55 jts 9 5/8" 40# J-55 LT&C csg set — ok; test good. Circ & perform F.I.T.ton 156 jts 5 ½" 17# P-110 LT&C csg & returns. Cmt Stage 2 lead w/1350 sx C 4 hrs. Rig Release Da	ertinent details, an e Completions: At 23 sx redi-mix. Cmt w/500 sx Cl C. @ 2,500'. Cmt w/12 0 9.0 ppg E.M.W, tes 114 jts 5 ½" 17# P-1 C cmt, tail w/150 C	Maintain circ throughounds sx Cl C cmt Full returns good, no leak off. 110 BT&C csg @ 12,303 l C cmt. Drop plug, displayed and belief.	of proposed completion at job, full returns. Circ 187 arns thru out job, 380 sx to 3'. Cmt 1 st stage w/300 sx lace w/fresh wtr, bmp plug, RECEIVED MAR 2 8 2012 NMOCD ARTESIA
of starting any proposed or complosed for completion. 02/09/12 MIRU. TD 26" hole, set 20" I 02/22/12: TD 17 1/2" hole @ 300'. Ran sx to surf. WOC 24 hrs. 02/23/12 Test csg to 1200 psi - ok 02/27/12: TD 12 1/4" hole @ 2,500'. Rasurf. WOC 24 hrs 02/28/12: Tst csg to 1500 psi for 30 min 03/18/12: TD 8 3/4" hole @ 12,303'. RaCl H, tail w/500 sx Cl H. Full bleed off, floats held. WOC 2-03/19/11. Rig rlsd Spud Date:	eted operations. (Clearly state all prk). SEE RULE 1103. For Multiple H-40 ST&C conductor @ 90', cmt w/12 in 6 jts 13 3/8" 48# ST&C csg @ 300'. In 55 jts 9 5/8" 40# J-55 LT&C csg set — ok; test good. Circ & perform F.I.T.ton 156 jts 5 ½" 17# P-110 LT&C csg & returns. Cmt Stage 2 lead w/1350 sx C 4 hrs. Rig Release Da	ertinent details, an e Completions: At e Completions: At 23 sx redi-mix. Cmt w/500 sx Cl C. 2,500'. Cmt w/1' 0 9.0 ppg E.M.W, tes 114 jts 5 ½" 17# P-1 C cmt, tail w/150 C	tach wellbore diagram Maintain circ throughou 135 sx Cl C cmt Full retu st good, no leak off. 110 BT&C csg @ 12,303 I C cmt. Drop plug, displ	of proposed completion at job, full returns. Circ 187 arns thru out job, 380 sx to 3'. Cmt 1st stage w/300 sx lace w/fresh wtr, bmp plug, RECEIVED MAR 2 8 2012
of starting any proposed or completion. 02/09/12 MIRU. TD 26" hole, set 20" I 02/22/12: TD 17 1/2" hole @ 300'. Ran sx to surf. WOC 24 hrs. 02/23/12 Test csg to 1200 psi - ok 02/27/12: TD 12 1/4" hole @ 2,500'. Rasurf. WOC 24 hrs. 02/28/12: Tst csg to 1500 psi for 30 min 03/18/12: TD 8 3/4" hole @ 12,303'. RaCl H, tail w/500 sx Cl H. Full bleed off, floats held. WOC 24 03/19/11. Rig rlsd Spud Date:	eted operations. (Clearly state all prk). SEE RULE 1103. For Multiple 1-40 ST&C conductor @ 90', cmt w/12 in 6 jts 13 3/8" 48# ST&C csg @ 300'. an 55 jts 9 5/8" 40# J-55 LT&C csg set - ok; test good. Circ & perform F.I.T.ton 156 jts 5 ½" 17# P-110 LT&C csg & returns. Cmt Stage 2 lead w/1350 sx C 4 hrs. Rig Release Da TITLE Sr. Staff I	ertinent details, an e Completions: At 23 sx redi-mix. Cmt w/500 sx Cl C. 2,500'. Cmt w/1' 2,900 ppg E.M.W, tes 114 jts 5 ½" 17# P-1 C cmt, tail w/150 C	tach wellbore diagram Maintain circ throughou St good, no leak off. 110 BT&C csg @ 12,303 1 C cmt. Drop plug, displ	of proposed completion at job, full returns. Circ 187 arns thru out job, 380 sx to 3'. Cmt 1 st stage w/300 sx lace w/fresh wtr, bmp plug, RECEIVED MAR 2 8 2012 NMOCD ARTESIA 03/25/2012
of starting any proposed or completion. 02/09/12 MIRU. TD 26" hole, set 20" I 02/22/12: TD 17 1/2" hole @ 300'. Ran sx to surf. WOC 24 hrs. 02/23/12: TD 12 1/4" hole @ 2,500'. Rasurf. WOC 24 hrs. 02/28/12: TS t csg to 1200 psi - ok. 02/28/12: TS t csg to 1500 psi for 30 min. 03/18/12: TD 8 3/4" hole @ 12,303'. RaCl H, tail w/500 sx Cl H. Full bleed off, floats held. WOC 24. 03/19/11. Rig rlsd Spud Date: Type or print name _Stephanie A. Ys.	eted operations. (Clearly state all prk). SEE RULE 1103. For Multiple 1-40 ST&C conductor @ 90', cmt w/12 in 6 jts 13 3/8" 48# ST&C csg @ 300'. an 55 jts 9 5/8" 40# J-55 LT&C csg set - ok; test good. Circ & perform F.I.T.ton 156 jts 5 ½" 17# P-110 LT&C csg & returns. Cmt Stage 2 lead w/1350 sx C 4 hrs. Rig Release Da TITLE Sr. Staff I	ertinent details, an e Completions: At 23 sx redi-mix. Cmt w/500 sx Cl C. 2,500'. Cmt w/1' 2,900 ppg E.M.W, tes 114 jts 5 ½" 17# P-1 C cmt, tail w/150 C	tach wellbore diagram Maintain circ throughou St good, no leak off. 110 BT&C csg @ 12,303 1 C cmt. Drop plug, displ	of proposed completion at job, full returns. Circ 187 arns thru out job, 380 sx to 3'. Cmt 1 st stage w/300 sx lace w/fresh wtr, bmp plug, RECEIVED MAR 2 8 2012 NMOCD ARTESIA
of starting any proposed or completion. 02/09/12 MIRU. TD 26" hole, set 20" I 02/22/12: TD 17 1/2" hole @ 300'. Ran sx to surf. WOC 24 hrs. 02/23/12: TEST csg to 1200 psi - ok 02/27/12: TD 12 1/4" hole @ 2,500'. Rasurf. WOC 24 hrs. 02/28/12: Tst csg to 1500 psi for 30 min 03/18/12: TD 8 3/4" hole @ 12,303'. RaCl H, tail w/500 sx Cl H. Full bleed off, floats held. WOC 24 hrs. 03/19/11. Rig rlsd Spud Date: Type or print name _Stephanie A. Ys For State Use Only	eted operations. (Clearly state all prk). SEE RULE 1103. For Multiple 1-40 ST&C conductor @ 90', cmt w/12 in 6 jts 13 3/8" 48# ST&C csg @ 300'. an 55 jts 9 5/8" 40# J-55 LT&C csg set — ok; test good. Circ & perform F.I.T.ton 156 jts 5 ½" 17# P-110 LT&C csg & returns. Cmt Stage 2 lead w/1350 sx C 4 hrs. Rig Release Da TITLE Sr. Staff I asaga E-mail address: Step	ertinent details, an e Completions: At 23 sx redi-mix. Cmt w/500 sx Cl C. 2,500'. Cmt w/1' 2,900 ppg E.M.W, tes 114 jts 5 ½" 17# P-1 C cmt, tail w/150 C	tach wellbore diagram Maintain circ throughou St good, no leak off. 110 BT&C csg @ 12,303 1 C cmt. Drop plug, displ	of proposed completion at job, full returns. Circ 187 arns thru out job, 380 sx to 3'. Cmt 1 st stage w/300 sx lace w/fresh wtr, bmp plug, RECEIVED MAR 2 8 2012 NMOCD ARTESIA 03/25/2012
of starting any proposed or completion. 02/09/12 MIRU. TD 26" hole, set 20" I 02/22/12: TD 17 1/2" hole @ 300'. Ran sx to surf. WOC 24 hrs. 02/23/12: TD 12 1/4" hole @ 2,500'. Rasurf. WOC 24 hrs. 02/28/12: TS t csg to 1200 psi - ok. 02/28/12: TS t csg to 1500 psi for 30 min. 03/18/12: TD 8 3/4" hole @ 12,303'. RaCl H, tail w/500 sx Cl H. Full bleed off, floats held. WOC 24. 03/19/11. Rig rlsd Spud Date: Type or print name _Stephanie A. Ys.	eted operations. (Clearly state all prk). SEE RULE 1103. For Multiple 1-40 ST&C conductor @ 90', cmt w/12 in 6 jts 13 3/8" 48# ST&C csg @ 300'. an 55 jts 9 5/8" 40# J-55 LT&C csg set - ok; test good. Circ & perform F.I.T.ton 156 jts 5 ½" 17# P-110 LT&C csg & returns. Cmt Stage 2 lead w/1350 sx C 4 hrs. Rig Release Da TITLE Sr. Staff I	ertinent details, an e Completions: At 23 sx redi-mix. Cmt w/500 sx Cl C. 2,500'. Cmt w/1' 2,900 ppg E.M.W, tes 114 jts 5 ½" 17# P-1 C cmt, tail w/150 C	tach wellbore diagram Maintain circ throughou St good, no leak off. 110 BT&C csg @ 12,303 1 C cmt. Drop plug, displ	of proposed completion at job, full returns. Circ 187 arms thru out job, 380 sx to 3'. Cmt 1 st stage w/300 sx lace w/fresh wtr, bmp plug, RECEIVED MAR 2 8 2012 NMOCD ARTESIA 03/25/2012 (405)-552-7802