
Form 3160-5 (August 2007)


## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135

	Expires:		
ease	Serial No.		

Do not use thi abandoned wel	6 If I	6 If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well			8 We	8 Well Name and No. WARREN ANW FEDERAL 3	
Oil Well Gas Well Oth					
2. Name of Operator  YATES PETROLEUM CORPO	Contact DRATIONE-Mail: tinah@yate	TINA HUERTA espetroleum.com		9. API Well No. 30-015-28598 🗸	
3a. Address 105 SOUTH FOURTH STREE ARTESIA; NM 88210	ΞΤ	3b. Phone No (include area code) Ph: 575-748-4168 Fx: 575-748-4585		10. Field and Pool, or Exploratory PENASCO DRAW; SA-YESO	
4. Location of Well (Footage, Sec., T	)	11. C	11. County or Parish, and State		
Sec 9 T19S R25E SWSE 660	EC	EDDY COUNTY, NM			
12. CHECK APPR	COPRIATE BOX(ES) TO	INDICATE NATURE	OF NOTICE, REPORT	, OR OTHE	R DATA
TYPE OF SUBMISSION	,	. TY	PE OF ACTION		
Notice of Intent	Acidize	Deepen	Production (Sta	art/Resume)	☐ Water Shut-Off
Notice of Intent	☐ Alter Casing	Fracture Treat	Reclamation		☐ Well Integrity
☐ Subsequent Report	Casing Repair	New Construction	on Recomplete		Other
.     Final Abandonment Notice	Change Plans	Plug and Aband	on   Temporarily A	porarily Abandon	
	Convert to Injection	Plug Back	■ Water Disposa	l	
Attach the Bond under which the worfollowing completion of the involved testing has been completed. Final At determined that the site is ready for final Attach Part of the involved testing has been completed. Final Attach Part of the involved testing has been completed. Final Attach Part of the involved that the site is ready for final Attach Part of the involved that the site is ready for final Attach Part of the involved that the site is ready for final Attach Part of the involved that the site is ready for final Attach Part of the involved that the involved tha	operations. If the operation repandonment Notices shall be fill inal inspection.)  plans to plugback and recommendation with production equipmend p. Spot a 30 sx Class "C" x) Class "C" cement plugplug across Bone Spring 0'-2364'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400'(15), 2368'-2400	sults in a multiple completioned only after all requirements complete this well as follows. RIH with GR/JB to +1 cement plug across DN across Wolfcamp from 3337'-3507'. Press (33), 2412'-2425'(14), 24 mulate as needed. Flowensure that the perforating equipment and turn wo	or recompletion in a new int, including reclamation, have buss: MIRU any safety 1/-7710'. Set a 7" CIBP tool from 5462'-5632'. Spot a sure test casing to 40'-2450'(11), we well back and allow ons are not	RE  NMC  CD FOR	CEIVED  AY 07 2012  OCD ARTESIA
14. I hereby certify that the foregoing is  Name (Printed/Typed) TINA HUE	For YATES PETRO	129509 verified by the BL DLEUM CORPORATION, OF TO THE RE	sent to the Carlsbad		
Signature (Electronic S	(ubmission)	MOCD TOSSIUM Date 01	/30/2012		
	THIS SPACE FO	R FEDERAL OR ST	(国外国科科 377	/ED	
Approved By		Title			Date
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conditions.	itable title to those rights in the	not warrant or	MAY 3	2012	
Title 18 U S C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U S.C. Section 1212, make it a statements or representations as	crime for any person knowing to any matter within its jurise	sly and wWww.bub.make.to'a action PETROLEUM EN	GINEER ent o	r agency of the United





- 8. TIH with packer and tubing. Set the packer at 2,100'. MI RU WSC to pump a 3,000 gallon acid job with 20% gelled HCl, drop 150 ball sealers spaced out evenly throughout the acid. Flush to the bottom perforation with 2% KCl water. Swab test and evaluate.
- 9. If the decision is made to fracture MI RU pumping company to pump a fracture treatment at 70-80 BPM down the 7" casing limiting the surface treating pressure to 3,400 psig. Set a pop off valve at 3,700 psi.

Treating Schedule 3000

				1b	Proppant	
Stage			Conc			-
Number	Type gal	.lb/ga		Stage	Cumulative	Proppant Type
1 .	water	2100.	0.00	0.		
2 .	slk-water	42000.	0.00	0.		
3	slk-water	4200.	0.20	840.		100 mesh
4	slk-water	4500.	0.00	0.		5555
5	slk-water	4200.	0.30	1260.		100 mesh
6	slk-water	4500.	0.00	0.		- <b></b>
7	slk-water	4200.	0.40	1680.		100 mesh
8	slk-water	4500.	0.00	0.		
9	slk-water	4200.	0.50	2100.	5880.	100 mesh
10	slk-water	4500.	0.00	0.	5880.	
1.1	slk-water	4200.	0.60	2520.	8400.	100 mesh
12	slk-water	4500.	0.00	0.	8400.	
13	slk-water	4200.	0.70	2940.	11340.	100 mesh
14	slk-water	4500.	0.00	0.	11340.	
15	slk-water	4200.	0.80	3360.	14700.	100 mesh
16	slk-water	4500.	0.00	0.	14700.	
17	slk-water	4200.	0.90	3780.	18480.	100 mesh
18	slk-water	4500.	0.00	0.	18480.	<del>.</del>
19	slk-water	4200.	1.00	4200.	22680.	100 mesh
20	slk-water	8000.	0.00	0.	22680.	
21	slk-water	8000.	0.20	1600.	24280.	40/70 brown
22	slk-water	4400.	0.00	0.	24280.	<del>;</del>
23	slk-water	8000.	0.30	2400.	26680.	40/70 brown
24	slk-water	4400.	0.00	0.	26680.	
25	slk-water	8000.	0.40	3200.	29880.	40/70 brown
26	slk-water	4400.	0.00	0.	29880.	
27	slk-water	8000.	0.50	4000.	33880.	40/70 brown
28	slk-water	4400.	0.00	0.	33880.	·
29	slk-water	8000.	0.60	4800.	38680.	40/70 brown
30	slk-water	4400.	0.00	0.	38680	,
31	slk-water	8000.	0.70_	5600.	44280.	40/70 brown
32	slk-water	4400.	-0.00-	0.	44280	
33	slk-water	8000.	0.80	6400.	50680.	40/70 brown
34	slk-water	4400.	0:00	0.		
35	slk-water	8000.	0.90 _	7200.		40/70 brown
36	slk-water	4400.	0.00	0.	57880.	
37	slk-water	5600.	1.00	5600.		40/70 brown
38	slk-water	12500.	0.00	0.		
39	slk-water	12500.	1.00	12500.	75980.	16/30 Brown
40	slk-water	17500.	2.00	35000.		16/30 Brown
41	slk-water	17500.	3.00	52500.		16/30 Brown
42	slk-water	3770.	0.00	0.	163480.	

Estimated Surface Treating Pressure = 1,904 psig. Maximum Surface Treating Pressure = 3,400 psig.

-11

## **Conditions of Approval**

## Yates Petroleum Corporation Warren ANW Fed 3 API 3001528598

May 02, 2012

- 1. A new "Well Location and Acreage Dedication Plat" (NMOCD Form C-102) is required with the notice of intent package when opening another pay zone.
- 2. Notify BLM 575-361-2822 before commencing plug back procedures. The plug back procedures shall be witnessed. Note the contact, time, & date in your subsequent report.
- 3. Surface disturbance beyond the existing pad shall have prior approval.
- 4. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 5. Functional H<sub>2</sub>S monitoring equipment shall be on location.
- 6. A minimum of 3000 (3M) BOPE is to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M) Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 7. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 8. Minimum requirement for mud placed between plugs is 25 sacks of salt water gel per 100 barrels in 9 lb/gal brine.
- 9. CIBP at 7702' shall be capped with a 25 sack Class "H" cement plug mixed 15.6lb/gal, 1.18ft<sup>3</sup>/sx, and 5.2g/sx. Tag CIBP to verify depth prior to pumping cement.
- 10. The BLM PET witness shall run tubing tally and agree to all cement placement. Sample each Class "C" plug mixed 14.8lb/gal, 1.32 ft<sup>3</sup>/sx, and 6.3gal/sx water for cement curing time and tag and/or pressure test (WOC time of 4 hours recommended) as requested by BLM PET witness.
- 11. DV tool plug shall be tagged at 5905' or shallower.

- 12. After setting the top plug and before perforating, operator proposes to test the casing to 3000 psi. Operator shall chart this test to confirm casing integrity. This pressure is just below the 70% test pressure permitted in Onshore Order 2. Pressure leak off may require remediation or modification of the remaining procedure. Include a copy of the chart in the subsequent sundry for this work over. If operator does perform a fracture treatment, operator shall perform a similar pressure test after completing that treatment.
- 13. Fracture stimulation pressure shall be limited to 2750 psi with the pop off set at 3000 psi. Operator expecting actual fracture pressure to be 2000 psi.
- 14. File a **subsequent sundry** Form 3160-5 within 30 days of the plug back and acid treatment. Include an updated wellbore diagram.
- 15. Submit the BLM Form 3160-4 Recompletion Report within 30 days of the date all BLM approved procedures are complete.
- 16. Workover approval is good for 90 days (completion to be within 90 days of approval). A legitimate request is necessary for extension of that date.

PRS 050212 / WWI 050312

NM Fed Regs & Forms - <a href="http://www.blm.gov/nm/st/en/prog/energy/oil">http://www.blm.gov/nm/st/en/prog/energy/oil</a> and gas.html

Use of Form 3160-5 "Sundry Notices and Reports on Wells"

§ 43 CFR 3162.3-2 Subsequent Well Operations.

§ 43 CFR 3160.0-9 (c)(1) Information collection.

§ 3162.4-1 (c) Well records and reports.