


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003

**Release Notification and Corrective Action**

*nmlb12/503/855*

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating	269324	Contact: Joe Hernandez
Address: 2130 W. Bender Hobbs, NM 88240.		Telephone No.: 575-738-1739
Facility Name: Foster #4		Facility Type: Oil

Surface Owner: Federal	Mineral Owner: Federal	API No.: 3001505203
------------------------	------------------------	---------------------

**LOCATION OF RELEASE**

Unit Letter J	Section 17	Township 17S	Range 31E	Feet from the 1650	North/South Line South	Feet from the 1650	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

**Latitude:** 32.8318352193832 **Longitude:** -103.888755956835

**NATURE OF RELEASE**

Type of Release: Produced water	Volume of Release: 25gal	Volume Recovered: 0
Source of Release: Poly-Pipeline	Date and Hour of Occurrence: 04/17/2012 1pm	Date and Hour of Discovery: 04/17/2012 1:30pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M.Bratcher-NM OCD / Terry Gregston-BLM	
By Whom? Joe Hernandez	Date and Hour 04/19/2012 10am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*:

Describe Cause of Problem and Remedial Action Taken.\*: 3" poly was cut and removed beside road. COG company cut polyline while building new pad. They never fuse line together. Unit is not in service, but still leaked 1/2 barrel of water that was left in line.

Describe Area Affected and Cleanup Action Taken.\* : Remedial action pending...

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Joe Hernandez	Signed By <i>[Signature]</i> Approved by District Supervisor:	
Title: Production Foreman	Approval Date: <b>MAY 29 2012</b>	Expiration Date:
E-mail Address: jhernandez@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 04/29/2012 Phone: 575-942-9492	Remediation per OCD Rules & Guidelines. <b>SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:</b>	

\* Attach Additional Sheets If Necessary

**6/29/2012**

*2RP-1129*