Office Office	State of New Mexico	Form C-103
District 1 – (575) 393-6161	Energy, Minerals and Natural Resources	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
<u>District II</u> - (575) 748-1283 811 S First St, Artesia, NM 88210	OIL CONSERVATION DIVISION	30-015-02053
<u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa PC, NWI 67505	6. State Oil & Gas Lease No.
87505		647
	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	State 647 AC 711
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		8. Well Number
	Gas Well Other Injection	93
2. Name of Operator	ous wen 62 outer injection	9. OGRID Number
Quantum Resources Management, LLC		184860
3. Address of Operator		10. Pool name or Wildcat
1401 McKinney Street, Suite 2400, Houston, TX 77010		Artesia (Q-G-SA)
4. Well Location	<u> </u>	
	220 food from the North Line and	2620 fact from the Fact line
	330 feet from theNorth line and	
Section 27	Township 18S Range 28E	NMPM Eddy County
A PART OF THE PART	11 Fl	A CONTRACTOR OF THE CONTRACTOR
	11. Elevation (Show whether DR, RKB, RT, GR, e 3586' GR	ic.)
- VS-pre Comment of Comment of Comment	3380 UK	
10 01 1 4	THE CALC DATE	D 4
12. Check Appropriate Box to	Indicate Nature of Notice, Report or Other	Data
NOTICE OF IN	TENTION TO:	JBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK		
<u> </u>		DRILLING OPNS. □ P AND A □
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE D MULTIPLE COMPL CASING/CEMB	
PULL OR ALTER CASING	MIDETIPLE COMPL CASING/CEME	ENT JOB
DOWNHOLE COMMINGLE		
_	□ OTHER:	. П
OTHER:	OTHER:	and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or comp	leted operations. (Clearly state all pertinent details,	
OTHER: 13. Describe proposed or comp of starting any proposed wo	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple (
OTHER: 13. Describe proposed or comp	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple (
OTHER: 13. Describe proposed or comp of starting any proposed wo	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple (ompletion.	
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or rec 5 Year Mechanical Integrity	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. y Test failed 06/13/12.	Completions: Attach wellbore diagram of
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or rec 5 Year Mechanical Integrity Quantum Resources Manage	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. y Test failed 06/13/12. gement, LLC, intends to MIRU PU & bleed-down we	Completions: Attach wellbore diagram of
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or rec 5 Year Mechanical Integrity	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. y Test failed 06/13/12. gement, LLC, intends to MIRU PU & bleed-down we	Completions: Attach wellbore diagram of
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or rec 5 Year Mechanical Integrity Quantum Resources Manag tbg or pkr leak. Re-test casi	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. y Test failed 06/13/12. gement, LLC, intends to MIRU PU & bleed-down wing.	Completions: Attach wellbore diagram of ell. Unseat packer. POOH w/tbg & pkr. Check for
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or rec 5 Year Mechanical Integrity Quantum Resources Manag tbg or pkr leak. Re-test casi	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. y Test failed 06/13/12. gement, LLC, intends to MIRU PU & bleed-down we	Completions: Attach wellbore diagram of ell. Unseat packer. POOH w/tbg & pkr. Check for
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or rec 5 Year Mechanical Integrity Quantum Resources Manag tbg or pkr leak. Re-test casi	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. y Test failed 06/13/12. gement, LLC, intends to MIRU PU & bleed-down wing.	Completions: Attach wellbore diagram of ell. Unseat packer. POOH w/tbg & pkr. Check for
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or rec 5 Year Mechanical Integrity Quantum Resources Manag tbg or pkr leak. Re-test casi	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. y Test failed 06/13/12. gement, LLC, intends to MIRU PU & bleed-down wing.	Completions: Attach wellbore diagram of ell. Unseat packer. POOH w/tbg & pkr. Check for
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or rec 5 Year Mechanical Integrity Quantum Resources Manag tbg or pkr leak. Re-test casi	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. y Test failed 06/13/12. gement, LLC, intends to MIRU PU & bleed-down wing.	Completions: Attach wellbore diagram of ell. Unseat packer. POOH w/tbg & pkr. Check for
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or rec 5 Year Mechanical Integrity Quantum Resources Manag tbg or pkr leak. Re-test casi	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. y Test failed 06/13/12. gement, LLC, intends to MIRU PU & bleed-down wing.	Completions: Attach wellbore diagram of ell. Unseat packer. POOH w/tbg & pkr. Check for
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or rec 5 Year Mechanical Integrity Quantum Resources Manag tbg or pkr leak. Re-test casi	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. y Test failed 06/13/12. gement, LLC, intends to MIRU PU & bleed-down wing.	Completions: Attach wellbore diagram of ell. Unseat packer. POOH w/tbg & pkr. Check for
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or rec 5 Year Mechanical Integrity Quantum Resources Manag tbg or pkr leak. Re-test casi	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. y Test failed 06/13/12. gement, LLC, intends to MIRU PU & bleed-down wing.	Completions: Attach wellbore diagram of ell. Unseat packer. POOH w/tbg & pkr. Check for
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or rec 5 Year Mechanical Integrity Quantum Resources Manag tbg or pkr leak. Re-test casi	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. y Test failed 06/13/12. gement, LLC, intends to MIRU PU & bleed-down wing.	Completions: Attach wellbore diagram of ell. Unseat packer. POOH w/tbg & pkr. Check for
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or rec 5 Year Mechanical Integrity Quantum Resources Manag tbg or pkr leak. Re-test casi NMOCD Artesia office wil	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. y Test failed 06/13/12. gement, LLC, intends to MIRU PU & bleed-down wing. I be notified 48 hrs prior to coordinate scheduling re	Completions: Attach wellbore diagram of ell. Unseat packer. POOH w/tbg & pkr. Check for
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or rec 5 Year Mechanical Integrity Quantum Resources Manag tbg or pkr leak. Re-test casi NMOCD Artesia office wil	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. y Test failed 06/13/12. gement, LLC, intends to MIRU PU & bleed-down wing. I be notified 48 hrs prior to coordinate scheduling re	Completions: Attach wellbore diagram of ell. Unseat packer. POOH w/tbg & pkr. Check for
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or rec 5 Year Mechanical Integrity Quantum Resources Manag tbg or pkr leak. Re-test casi NMOCD Artesia office will	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. y Test failed 06/13/12. gement, LLC, intends to MIRU PU & bleed-down wing. I be notified 48 hrs prior to coordinate scheduling re	Completions: Attach wellbore diagram of ell. Unseat packer. POOH w/tbg & pkr. Check for etest.
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or rec 5 Year Mechanical Integrity Quantum Resources Manag tbg or pkr leak. Re-test casi NMOCD Artesia office will	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. y Test failed 06/13/12. gement, LLC, intends to MIRU PU & bleed-down wing. I be notified 48 hrs prior to coordinate scheduling re	Completions: Attach wellbore diagram of ell. Unseat packer. POOH w/tbg & pkr. Check for etest.
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or rec 5 Year Mechanical Integrity Quantum Resources Manag tbg or pkr leak. Re-test casi NMOCD Artesia office will	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. y Test failed 06/13/12. gement, LLC, intends to MIRU PU & bleed-down wing. I be notified 48 hrs prior to coordinate scheduling re Rig Release Date:	Completions: Attach wellbore diagram of ell. Unseat packer. POOH w/tbg & pkr. Check for test.
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or rec 5 Year Mechanical Integrity Quantum Resources Manag tbg or pkr leak. Re-test casi NMOCD Artesia office will	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. y Test failed 06/13/12. gement, LLC, intends to MIRU PU & bleed-down wing. I be notified 48 hrs prior to coordinate scheduling re Rig Release Date:	Completions: Attach wellbore diagram of ell. Unseat packer. POOH w/tbg & pkr. Check for test.
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or recompletion or recompletion or recompletion or proposed completion or recompletion or recompletion or recompletion or recompletion or recompletion or proposed completion or recompletion or recompl	Rig Release Date: Rig Release Date: Rigulatory Ana TITLE Regulatory Ana	Completions: Attach wellbore diagram of ell. Unseat packer. POOH w/tbg & pkr. Check for etest.
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or rec. 5 Year Mechanical Integrity Quantum Resources Manage the or pkr leak. Re-test casis NMOCD Artesia office will Spud Date:	Rig Release Date: Rig Release Date: Rigulatory Ana TITLE Regulatory Ana	Completions: Attach wellbore diagram of ell. Unseat packer. POOH w/tbg & pkr. Check for test.
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or recompletion or recompletion or recompletion or proposed completion or recompletion or recompletion or recompletion or recompletion or recompletion or proposed completion or recompletion or recompl	Rig Release Date: Rig Release Date: Rigulatory Ana TITLE Regulatory Ana	Completions: Attach wellbore diagram of ell. Unseat packer. POOH w/tbg & pkr. Check for etest.
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or rec 5 Year Mechanical Integrity Quantum Resources Manage the or pkr leak. Re-test casis NMOCD Artesia office will Spud Date: I hereby certify that the information SIGNATURE Type or print name Erick A. Refor State Use Only	Rig Release Date: Rig Release Date: TITLERegulatory Anager and address:	Completions: Attach wellbore diagram of ell. Unseat packer. POOH w/tbg & pkr. Check for test. cdge and belief. cdge and belief. physt DATE7/5/12 cq.com PHONE:(713) 634-4612
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or rec 5 Year Mechanical Integrity Quantum Resources Managetbg or pkr leak. Re-test casis NMOCD Artesia office will Spud Date: I hereby certify that the information SIGNATURE Type or print nameErick A. Re-	Rig Release Date: Rig Release Date: Rigulatory Ana TITLE Regulatory Ana	Completions: Attach wellbore diagram of ell. Unseat packer. POOH w/tbg & pkr. Check for test. cdge and belief. cdge and belief. physt DATE7/5/12 cq.com PHONE:(713) 634-4612