UNITED STATES | MEULIVE
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMEN AUG 0 1 2012

FORM APPROVED

	Expires	March	-0137 31, 200
nago Com	d Ma		

OCD Artesia

	NOTICES AND REI	PORTS ADVINE	LESTERNA	NMNM	01510
OCD ARTES AND REPORTS ON WELLS ESIA OCD ARTES AND REPORTS ON WELLS ESIA abandoned well. Use Form 3160-3 (APD) for such proposals.			6. If Indian, Allottee or Tribe Name		
abandoned we	%II. Use Form 3160-3 (. 	APD) for such pro	posais.		
SUBMIT IN TRIPLICATE- Other instructions on re			se side.	7. If Unit or	CA/Agreement, Name and/or No.
1 Type of Well ☐ ☐	Gas Well C Other			9 Well New	no and No
2 Name of Operator F1-RO Corporation/ NMOCD				8. Well Name and No. Malco Federal 1	
·····	ration/ NMOCD	T		9. API We	
3a Address 811 South First Artesia, NM 88210		3b. Phone No (include area code) 575-748-1283		300150	1 Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		<u> </u>	Red Lake		
1980 FSL 1980 FWL (NESW) SEC23,T17S,R28E				11. County or Parish, State	
				Eddy county, New Mexico	
12. CHECK AF	PPROPRIATE BOX(ES) TO	INDICATE NATUR	E OF NOTICE, I	REPORT, OR	OTHER DATA
TYPE OF SUBMISSION		TYI	PE OF ACTION		
	Acidize	Deepen	Production (S	art/Resume)	Water Shut-Off
Notice of Intent	Alter Casing	Fracture Treat	Reclamation		Well Integrity
Subsequent Report	Casing Repair Change Plans	New Construction Plug and Abandon	Recomplete Temporarily A	handon	Other
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal		
SD for weekend. 09/14/09 Tag TOC @ 1675 09/15/09 TTOOH, perforat 09/16/09 Tag TOC @ 280'. 09/17/09 TTIH tagged TOC 09/18/09 M&P 25sx Class 0 09/21/09 Tag TOC @ 65'. I Class C, WOC. 09/22/09 Tag TOC @ 65'. I	'. Perforate csg @ 1255', M&. te csg @ 540', TTIH M&P, W TTOOH, Perforate csg @ 60 C @ 114'. M&P 25sx Class C C WOC 4 hours. Tag TOC @ M&P 25 sx Class C, WOC 4 h	P 25sx Class C,WOC 4 /OC. ', M&P 315sx Class C WOC 4 hours. Tag TO 280'. M&P 25sx Class nours. Tag TOC @ 65'	hours. Tagged TO WOC. PC @ 280'. C WOC. SD for we	Clectosted as Liability ur Surface res ekend.	s to plugging of the well der bond is retained unti toration is completed.
Tag TOC @ 03 . Mich 30 :	sx Class C, 5sx Class C circula		0 sx Class C, WOC.	•	-
9/23/09 Rigged down move Dug out cellar. Cut off wel	ox Class C, 5sx Class C circulard off plugging rig.	ated to surface.	er.Cut off dead men	Tag TOC @ 6	5'. M&P 25 sx Class C, WOC.
9/23/09 Rigged down move Dug out cellar. Cut off wel	ox Class C, 5sx Class C circulard off plugging rig. Ilhead. Welded on Dry Hole M	ated to surface.	er.Cut off dead men	Tag TOC @ 6	5'. M&P 25 sx Class C, WOC.
9/23/09 Rigged down move Dug out cellar. Cut off wel 14. I hereby certify that the foreg Name (Printed/Typed)	ox Class C, 5sx Class C circulard off plugging rig. Ilhead. Welded on Dry Hole M	ated to surface.	er.Cut off dead men	Tag TOC @ 6	5'. M&P 25 sx Class C, WOC.
9/23/09 Rigged down move Dug out cellar. Cut off wel Well Plugged 5+ 14. I hereby certify that the foreg	ox Class C, 5sx Class C circulard off plugging rig. Ilhead. Welded on Dry Hole M	ated to surface. For the following surface of the following surface $9/23$	er.Cut off dead men	Tag TOC @ 6	5'. M&P 25 sx Class C, WOC.
9/23/09 Rigged down move Dug out cellar. Cut off wel 14. I hereby certify that the foreg Name (Printed/Typed)	ox Class C, 5sx Class C circulard off plugging rig. Ilhead. Welded on Dry Hole M	ated to surface. For the following surface of the following surface $9/23$	7.Cut off dead men	Tag TOC @ 6	5'. M&P 25 sx Class C, WOC. noved off. On LOCATION
9/23/09 Rigged down move Dug out cellar. Cut off wel Well Plugged 5+ 14. I hereby certify that the foreg Name (Printed/Typed) Lewis K.	ox Class C, 5sx Class C circulard off plugging rig. Ilhead. Welded on Dry Hole M	ted to surface. Iarker. Backfilled cells 9 > 9/23 Title Ag Date	ir.Cut off dead men	Tag TOC @ 6 Cleaned loc. 1 days c	5'. M&P 25 sx Class C, WOC. noved off. On LOCATION
9/23/09 Rigged down move Dug out cellar. Cut off wel Well Plugged 5+ 14. I hereby certify that the foreg Name (Printed/Typed) Lewis K.	ex Class C, 5sx Class C circular d off plugging rig. Welded on Dry Hole Medical welded on Dry Hole Medical Soung is true and correct	Title Ag	TATE OFFICE	Tag TOC @ 6 Cleaned loc. 1 days c	5'. M&P 25 sx Class C, WOC. noved off. Do Location Dist of Sylen ED FOR KECUF
9/23/09 Rigged down move Dug out cellar. Cut off well Plugged 5+ 14. I hereby certify that the foreg Name (Printed/Typed) Signature Approved by	ax Class C, 5sx Class C circular d off plugging rig. Ulhead. Welded on Dry Hole Marking 9/10/2009 Soing is true and correct Coll THIS SPACE FOR F	Title Ag Date Title Ag Title Ag	TATE OFFICE	Tag TOC @ 6 Cleaned loc. 1 days c	5'. M&P 25 sx Class C, WOC. noved off. On LOCATION
9/23/09 Rigged down move Dug out cellar. Cut off wel 14. I hereby certify that the foreg Name (Printed/Typed) Signature Signature	ax Class C, 5sx Class C circular d off plugging rig. Ilhead. Welded on Dry Hole Marking 9/10/2009 going is true and correct College THIS SPACE FOR Formulation of this notice dor equitable title to those rights in	Title Ag Date Tederal or surface. Title Ag Date Title Ag Date Title Ag Date Title Ag Date Section of warrant or	TATE OFFICE	Tag TOC @ 6 Cleaned loc. 1 days c	5'. M&P 25 sx Class C, WOC. noved off. Do Location Dist of Sylen ED FOR KECUF