Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103		
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources obbs, NM 88240		Revised May 08, 2003 WELL API NO.		
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-015-32070 5. Indicate Type of Lease		
District III 1220 South St. Francis Dr.		STATE X FEE			
District IV 1220 S. St. Francis Dr., Santa Fe, NM		6. State Oil & Gas Lease No.			
87505			B-7244		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name of C	7. Lease Name or Unit Agreement Name	
DIFFERENT RESERVOIR. USE "APPLICA" PROPOSALS.)	ATION FOR PERMIT" (FORM C-	101) FOR SUCH	BB STATE	COM	
1. Type of Well: Oil Well Gas Well X	Other	RECEIVED	8. Well Number		
2. Name of Operator	Onlei	···	9. OGRID Number	•	
MARBOB ENERGY CORPORAT	ION	JUN 0 9 2005		14049	
1		20DEARTE SIN	10. Pool name or Wildcat SCOGGIN DRAW; MORROW		
PO BOX 227, ARTESIA, 1 4. Well Location	NM 00211-0221		1 SCOGGIN DR	AW; MURRUW	
Unit Letter M :	660 feet from theS	SOUTH line and	990 feet from	the WEST line	
Unit Letter 11 .	leet from the	me and	1eet Hom	the <u>west</u> line	
Section 2	Township 189			County EDDY	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3522 GL					
	ppropriate Box to Indica	ate Nature of Notice			
NOTICE OF INT PERFORM REMEDIAL WORK	ENTION TO: PLUG AND ABANDON 🔲	SUE REMEDIAL WOI	BSEQUENT REP RK □ A	ORT OF: ALTERING CASING []	
FERFORM REMEDIAL WORK				LIERING CASING []	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DF		PLUG AND ABANDONMENT	
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST A CEMENT JOB			
OTHER: ' ADD ADDITIONAL	L PAY 🗓	OTHER:		. 🗆	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
PRODUCTION HAS	FALLEN OFF. WE WILI	. ATTEMPT TO RE-	ESTARLISH PRODU	ICTION IN	
	RFS. IF UNSUCCESSFU				
PERF THE MIDDLE MORROW @ 9703' - 9740' (32 SHOTS). SWAB/FLOW TEST.					
ACIDIZE W/ 1000 GAL CLAY SAFE H ACID. SWAB/FLOW TEST.					
i					
· · · · · ·					
I hereby certify that the information ab	ove is true and complete to	the best of my knowled	ge and belief.		
SIGNATURE AND A	Drugp TITL	E PRODUCTION	ANALYST I	DATE 6/8/05	
Type or print name DIANA J	BRIGGS		Telephor	ne No. (505) 748-3303	
(This space for State ase)	NW. Deen	e e		55 ta v	
APPPROVED BY Conditions of approval, 17 any.	WW. Gren LIE Segiler	visor		DATE UN 1 3 2005	