

## NEW MEXICO ENERGY, MINERAL

NATURAL RESOURCES DEPARTMEN

## **BILL RICHARDSON**

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

09-Feb-05

YATES PETROLEUM CORPORATION

105 S 4TH ST

ARTESIA NM 88210-0000

Completed

RECEIVED

NOTICE OF VIOLATION - Inactive Well(s)

## Dear Operator:

A review of our records and recent inspection(s) indicate that the subject well(s) has been shut-in for an extended period of time. Rule 201 of the Rules and Regulation of the Oil Conservation Division provides that a well may be shut-in no longer than sixty days after suspension of drilling operations, upon determining that ther well is no longer usable (e.g., a dry hole), or one year after last production. To comply with guidelines as established in the Rules and Regulations, corrective actions must be taken immediately and the well(s) brought into compliance.

The detail section below indicates preliminary findings and/or probable nature of the violation.

The following options are available:

- 1. Immediately restore the well(s) to production, injection or disposal as applicable.
- 2. Request 'Temporary Abandoned' status pursuant to Rule 203, which requires that you set a plug and conduct a mechanical integrity test.
- 3. Submit a proposal to 'Plug and Abandon' the well(s) pursuant to Rule 202, proceed with plugging procedures on a timely basis after the proposal has been evaluated, amended and/or approved.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

## IDLE WELL INSPECTION DETAIL SECTION

CREEK AL FEDERAL 003

C-25-18S-30E

30-015-20234-00-00

Inspection No. iMLB0503951091

**Inspection Date:** 

2/8/2005 2:11:26 PM

shore Conv. Violation?

Corrective Action Due by: 5/14/2005 \*Significant Non-Compliance?

Type Inspection

No

Comments on Inspection:

Mike Bratcher 2-11-05 Records indicate last production for this well was

May 2002. Well is in violation of Rule 201.

CREEK AL FEDERAL 005

N-24-18S-30E

Inspection No. iMLB0503951280

anore as Inspector

Corrective Action Due by: 5/14/2005 60 day 944.

ation? \*Significant Non-Compliance? due 7-14.05

**Inspection Date:** 

Violation?

Type Inspection

Inspector

Routine/Periodic

Mike Bratcher

Yes

Pumpjack dismantled. Flowline valves as closed. Last reported production for this well was July 2001.

Comments on Inspection:

Well is in violation of Rule 201.