

NEW MEXICO ENERGY, MINERALS NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

15-Aug-05

HANSON ENERGY

PO BOX 1348 ARTESIA NM 88210-

NOTICE OF VIOLATION - Inactive Well(s)

Dear Operator:

A review of our records and recent inspection(s) indicate that the subject well(s) has been shut-in for an extended period of time. Rule 201 of the Rules and Regulation of the Oil Conservation Division provides that a well may be shut-in no longer than sixty days after suspension of drilling operations, upon determining that ther well is no longer usable (e.g., a dry hole), or one year after last production. To comply with guidelines as established in the Rules and Regulations, corrective actions must be taken immediately and the well(s) brought into compliance.

The detail section below indicates preliminary findings and/or probable nature of the violation.

The following options are available:

- 1. Immediately restore the well(s) to production, injection or disposal as applicable.
- 2. Request 'Temporary Abandoned' status pursuant to Rule 203, which requires that you set a plug and conduct a mechanical integrity test.
- 3. Submit a proposal to 'Plug and Abandon' the well(s) pursuant to Rule 202, proceed with plugging procedures on a timely basis after the proposal has been evaluated, amended and/or approved.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

IDLE WELL INSPECTION DETAIL SECTION

WEST ARTESIA GRAYBURG **UNIT 016**

M-8-18S-28E

30-015-02641-00-00

Inspection No. iCLB0520339019

7/22/2005 10:50:17 AM

Corrective Action Due by: 10/21/2005

Inspection Date: Type Inspection

Inspector

Violation? *Significant Non-Compliance?

Routine/Periodic

Yes

No

Comments on Inspection:

Chris Beadle

No flowline, pumping equipment or other production equipment on site. OCD records show current

production being reported as late as May 2005.

Inspection No. iCLB0520337713

WEST ARTESIA GRAYBURG **UNIT 022**

L-8-18S-28E

30-015-23639-00-00

Inspection Date:

7/22/2005 10:28:31 AM

Corrective Action Due by: 10/21/2005

Type Inspection

Inspector

Violation? Yes

No flowline, pumping equipment or other production equipment on site. OCD records show current

*Significant Non-Compliance?

Routine/Periodic

Chris Beadle

Comments on Inspection:

production being reported as late as May 2005. Area just north of wellhead contaminated.

WEST-ARTESIA GRAYBURG

2 M-8-18S-28F

(30-015-23724-00-00=

Inspection No. iCLB0520340960

Inspection Date:

7/22/2005 11:22:38 AM

Corrective Action Due by: 10/21/2005

Type Inspection

11.22.36 AUI

Violation?

*Significant Non-Compliance?

Routine/Periodic

Chris Beadle

Inspector

Yes

No -

Comments on Inspection:

Idle Well (Rule 201). No flowline, pumping equipment or other production equipment on site. OCD records show current production being reported as late as May 2005. Road into wellhead inaccessible by motor vehicle except by driving over pasture grown over well area. No well sign present as required by Rule 102

by Rule 103.

Thank you for your prompt attention to this matter and your efforts in helping to protect our environment and the infrastructure of the oil and gas industry.

Sincerely.

Artesia OCD District Office

^{*} Significant Non-Compliance events are reported directly to the U.S. Environmental Protection Agency, Region VI, Dallas, Texas.