Form 3160-5 (April 2004)

1. Type of Well

X Oil Well

TYPE OF SUBMISSION

Final Abandonment Notice

Notice of Intent

X Subsequent Report

2. Name of Operator

3a. Address

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Box 10340, Midladn, 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Alter Casing

Change Plans

Casing Repair

Convert to Injection

•		RI	50-				
	UNITED STATES DEPARTMENT OF THE BUREAU OF LAND MAN	INTERIOR JUL AGEMENT SON	ECEIVE	FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007 5. Lease Serial No. NIM-93477			
Do not use th	NOTICES AND REF his form for proposals to ell. Use Form 3160-3 (A	PORTS ON WELLS to drill or to re-enter an APD) for such proposals.	MITEO	Expires: March 31, 2007 5. Lease Serial No. NM-93477 If Indian, Allottee or Tribe Name			
SUBMIT IN TRI	IPLICATE- Other instr	7. If Unit or CA/Agreement, Name and/or No.					
ype of Well Cil Well	Gas Well Other	8. Well Name and No. River Bend 23 Federal #16 9. API Well No.					
ame of Operator Pogo	Producing Compan						
Address P.O. Box 10340		3b. Phone No. (include area code) 432-685-8100)	30-015-33598 10. Field and Pool, or Exploratory Area			
	T., R., M., or Survey Description)	Pierce Crossing Bone Spring 11 County or Parish, State					
1830' FSL & 198	30' FEL, Section	Eddy County, NM					
12. CHECK AF	PPROPRIATE BOX(ES) TO	INDICATE NATURE OF NO	OTICE, R	EPORT, OR OTHER DATA			
YPE OF SUBMISSION		TYPE OF ACTION					
	Acidize Deepen Production (Start/Resume) Water Shut-Off						

Well Integrity

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filled once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Plug Back

Fracture Treat

New Construction

Plug and Abandon

Reclamation

Water Disposal

Temporarily Abandon

X Recomplete

06/22/05 POOH w/ rods, pump & tbg. Perf Bone Spring 7227-7323 - total 16 holes. 06/23/05 Test CIBP @ 7850' to 3000# ok. Acdz 7227-7323 w/ 2500 gals 15% NeFe 06/25/05 Frac w/ 48,100# 30/50 Ottawa sd. 06/29/05 Set pkr @ 7136'. Producing Bone Spring only.

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)	 							
Cathy Wright	Title Si	. Eng Tec	h					
Signature Cashy Myst	Date 0	7/14/05						
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved by	Title		Date					
Conditions of approval, if any, are attached. Approval of this notice does not warrar certify that the applicant holds legal or equitable title to those rights in the subject lewhich would entitle the applicant to conduct operations thereon.		Office						
TO 1 10 110 C C C C C C C C C C C C C C C								

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.