

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-005-60982
5. Indicate Type of Lease
STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name:
Twin Lakes San Andres Unit
8. Well No.
79
9. Pool name or Wildcat
Twin Lake, San Andres (Assoc)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well:	
Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator	
Tipton Oil & Gas Acquisitions, Inc.	
3. Address of Operator	
P.O. Box 1234, Lovington, NM 88260	
4. Well Location	
Unit Letter <u>J</u> feet from the _____ line and _____ feet from the _____ line	
Section <u>6</u> Township <u>9S</u> Range <u>29E</u> NMPM Chaves, County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: ADD ADDITIONAL PERFS <input checked="" type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

MIRU PU. POOH w/ pump and rods. NDWH. NUBOP. RIH and tag. TOOH with tbg. PU bit and csg. scraper w/bailer and bail to TD. POOH w/ tbg. RU wireline truck. RIH. Perforate 15 shots from 2760-2774' with 1 SPF. POOH w/ wireline. PU AD-1 pkr. RIH w/tbg. to 2774'. Spot 150 gals. 15% NeFe acid. Reverse up tbg. PUH w/ packer; set packer @2740'±. Test tbg. in hole with pkr. 5000# psi below slips. RU acid trucks. Establish injection rate with 15 bbls. Go to acid pump 1000 gals. w/500# salt block followed with 3rd stage acid - 1000 gals. acid. Go to flush with 20 bbls. 2% KCl. SI 24 hrs. Get tbg. psi. RIH with bottom hole pumping assembly. ND BOP. NUWH. PU pump. RIH w/rods. Hang on. Space out. Return to production followed by 24-hr. test.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dellie McKelzy TITLE Agent, For Clay Tipton (Sec-Treas.), Principal DATE 8/18/05

Type or print name for Clay Tipton Telephone No. 505-631-4121

(This space for State use)

APPROVED BY FOR RECORDS ONLY TITLE _____ DATE AUG 23 2005
Conditions of approval, if any: