Submit 3 Copies To Appropriate District Office State of New Mexico	Form C-103
District 1 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-015-26413 5. Indicate Type of Lease
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410	STATE STEE
District IV Santa Fe, NIVI 8/303	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name Artesia State Com
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other	8. Well Number # 3
Name of Operator Devon Louisiana Corporation	9. OGRID Number 169355
3. Address of Operator	10. Pool name or Wildcat
20 North Broadway Oklahoma City, Oklahoma 73102-8260 (405) 552-8198	Travis Upper Penn
4. Well Location	
	100feet from the _Westline
Section 23 18S Township 28E Range 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	NMPM Eddy County
3509' GR	
Pit or Below-grade Tank Application or Closure	
	stance from nearest surface water
	onstruction Material
12. Check Appropriate Box to Indicate Nature of Notice	Report or Other Data
NOTICE OF INTENTION TO: SUE	SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	-
	ILLING OPNS. PAND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	IT JOB 🔲
i	_
OTHER: Re-complete to the Wolfcamp	
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar	
 Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A 	
13. Describe proposed or completed operations. (Clearly state all pertiment details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.	ttach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertiment details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Devon Energy Production Company, L.P. requests approval to re-complete to the Western Company.	ttach wellbore diagram of proposed completion
 13. Describe proposed or completed operations. (Clearly state all pertiment details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Devon Energy Production Company, L.P. requests approval to re-complete to the West. 1. MIRU Pulling unit 	ttach wellbore diagram of proposed completion blfcamp zone as follows:
13. Describe proposed or completed operations. (Clearly state all pertiment details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Devon Energy Production Company, L.P. requests approval to re-complete to the Western Company.	ttach wellbore diagram of proposed completion olicamp zone as follows:
 Describe proposed or completed operations. (Clearly state all pertiment details, are of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Devon Energy Production Company, L.P. requests approval to re-complete to the West. MIRU Pulling unit Set CIBP @ 9600' above all Cisco perforations Perforate Wolfcamp from 8922-8927, 8934-8942, 8944-8949, 8596-8610, 8511-4. Acidize perforation and swab test same 	ttach wellbore diagram of proposed completion olicamp zone as follows:
 Describe proposed or completed operations. (Clearly state all pertiment details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Devon Energy Production Company, L.P. requests approval to re-complete to the West. MIRU Pulling unit Set CIBP @ 9600' above all Cisco perforations Perforate Wolfcamp from 8922-8927, 8934-8942, 8944-8949, 8596-8610, 8511- 	ttach wellbore diagram of proposed completion olifcamp zone as follows: RECEIVED AUG 1 7 2005
 Describe proposed or completed operations. (Clearly state all pertiment details, are of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Devon Energy Production Company, L.P. requests approval to re-complete to the West. MIRU Pulling unit Set CIBP @ 9600' above all Cisco perforations Perforate Wolfcamp from 8922-8927, 8934-8942, 8944-8949, 8596-8610, 8511-4. Acidize perforation and swab test same 	ettach wellbore diagram of proposed completion olificamp zone as follows: RECEIVED
 Describe proposed or completed operations. (Clearly state all pertiment details, are of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Devon Energy Production Company, L.P. requests approval to re-complete to the West. MIRU Pulling unit Set CIBP @ 9600' above all Cisco perforations Perforate Wolfcamp from 8922-8927, 8934-8942, 8944-8949, 8596-8610, 8511-4. Acidize perforation and swab test same 	ttach wellbore diagram of proposed completion olifcamp zone as follows: RECEIVED AUG 1 7 2005
 Describe proposed or completed operations. (Clearly state all pertiment details, are of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Devon Energy Production Company, L.P. requests approval to re-complete to the West. MIRU Pulling unit Set CIBP @ 9600' above all Cisco perforations Perforate Wolfcamp from 8922-8927, 8934-8942, 8944-8949, 8596-8610, 8511-4. Acidize perforation and swab test same 	ttach wellbore diagram of proposed completion olifcamp zone as follows: RECEIVED AUG 1 7 2005
13. Describe proposed or completed operations. (Clearly state all pertiment details, are of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Devon Energy Production Company, L.P. requests approval to re-complete to the West. MIRU Pulling unit 2. Set CIBP @ 9600' above all Cisco perforations 3. Perforate Wolfcamp from 8922-8927, 8934-8942, 8944-8949, 8596-8610, 8511-4. Acidize perforation and swab test same 5. Turn well over to production.	RECEIVED AUG 1 7 2005 Ge and belief. I further certify that any pit or below-
 Describe proposed or completed operations. (Clearly state all pertiment details, are of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Devon Energy Production Company, L.P. requests approval to re-complete to the World MIRU Pulling unit Set CIBP @ 9600' above all Cisco perforations Perforate Wolfcamp from 8922-8927, 8934-8942, 8944-8949, 8596-8610, 8511-4. Acidize perforation and swab test same Turn well over to production. 	RECEIVED AUG 1 7 2005 Ge and belief. I further certify that any pit or below-
13. Describe proposed or completed operations. (Clearly state all pertiment details, are of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Devon Energy Production Company, L.P. requests approval to re-complete to the West. MIRU Pulling unit 2. Set CIBP @ 9600' above all Cisco perforations 3. Perforate Wolfcamp from 8922-8927, 8934-8942, 8944-8949, 8596-8610, 8511-4. Acidize perforation and swab test same 5. Turn well over to production.	RECEIVED AUG 1 7 2005 Que and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
13. Describe proposed or completed operations. (Clearly state all pertinent details, are of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Devon Energy Production Company, L.P. requests approval to re-complete to the West. MIRU Pulling unit 2. Set CIBP @ 9600' above all Cisco perforations 3. Perforate Wolfcamp from 8922-8927, 8934-8942, 8944-8949, 8596-8610, 8511-4. Acidize perforation and swab test same 5. Turn well over to production. I hereby certify that the information above is true and complete to the best of my knowledgrade tank has been/will be constructed or classed according to NMOCD guidelines □, a general permit □ SIGNATURE □ TITLE Sr. Staff Engineering	RECEIVED AUG 1 7 2005 Que and belief. I further certify that any pit or below- for an (attached) alternative OCD-approved plan DATE 8/17/05
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Devon Energy Production Company, L.P. requests approval to re-complete to the World Pulling unit 1. MIRU Pulling unit 2. Set CIBP @ 9600' above all Cisco perforations 3. Perforate Wolfcamp from 8922-8927, 8934-8942, 8944-8949, 8596-8610, 8511-4. Acidize perforation and swab test same 5. Turn well over to production. I hereby certify that the information above is true and complete to the best of my knowledgrade tank has been/will be constructed or clearly according to NMOCD guidelines □, a general permit □	RECEIVED AUG 1 7 2005 Que and belief. I further certify that any pit or below- lor an (attached) alternative OCD-approved plan Telephome No. (405) 552-8198
13. Describe proposed or completed operations. (Clearly state all pertiment details, are of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Devon Energy Production Company, L.P. requests approval to re-complete to the World MIRU Pulling unit 2. Set CIBP @ 9600' above all Cisco perforations 3. Perforate Wolfcamp from 8922-8927, 8934-8942, 8944-8949, 8596-8610, 8511-4. Acidize perforation and swab test same 5. Turn well over to production. I hereby certify that the information above is true and complete to the best of my knowledgrade tank has been/will be constructed or classed according to NMOCD guidelines, a general permit SIGNATURE	RECEIVED AUG 1 7 2005 Aug 1 7 2005
13. Describe proposed or completed operations. (Clearly state all pertinent details, are of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Devon Energy Production Company, L.P. requests approval to re-complete to the World MIRU Pulling unit 2. Set CIBP @ 9600' above all Cisco perforations 3. Perforate Wolfcamp from 8922-8927, 8934-8942, 8944-8949, 8596-8610, 8511- 4. Acidize perforation and swab test same 5. Turn well over to production. I hereby certify that the information above is true and complete to the best of my knowledgrade tank has been/will be constructed or classed according to NMOCD guidelines , a general permit SIGNATURE TITLE Sr. Staff Engineering Type or print name Norvella dams	RECEIVED AUG 1 7 2005 ge and belief. I further certify that any pit or below- for an (attached) alternative OCD-approved plan Telephome No. (405) 552-8198 AUG 1 7 2005 DATE DATE AUG 1 7 2005 DATE
13. Describe proposed or completed operations. (Clearly state all pertinent details, are of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Devon Energy Production Company, L.P. requests approval to re-complete to the World MIRU Pulling unit 2. Set CIBP @ 9600' above all Cisco perforations 3. Perforate Wolfcamp from 8922-8927, 8934-8942, 8944-8949, 8596-8610, 8511-4. Acidize perforation and swab test same 5. Turn well over to production. I hereby certify that the information above is true and complete to the best of my knowledgrade tank has been/will/be constructed or classed according to NMOCD guidelines , a general permit SIGNATURE TITLE Sr. Staff Engineering Type or print name Norvella dams	RECEIVED AUG 1 7 2005 Ge and belief. I further certify that any pit or below- lor an (attached) alternative OCD-approved plan Telephome No. (405) 552-8198 AUG 1 7 2005 DATE a C C I C I C C I C C .
13. Describe proposed or completed operations. (Clearly state all pertinent details, are of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Devon Energy Production Company, L.P. requests approval to re-complete to the World Mire Production Company, L.P. requests approval to re-complete to the World Mire Production Company, L.P. requests approval to re-complete to the World Mire Productions approval to re-complete to the World Mire Production approval to re-complete to the World Mire Production Company, L.P. requests approval to re-complete to the World Mire Productions approval to re-complete to the World Mire Production Complete to the best of my knowledgrade tank has been/will be constructed or cleased according to NMOCD guidelines approval to reproduction Company Production Company P	RECEIVED AUG 1 7 2005 Ge and belief. I further certify that any pit or below- lor an (attached) alternative OCD-approved plan Telephome No. (405) 552-8198 AUG 1 7 2005 DATE a C C I C I C C I C C .
13. Describe proposed or completed operations. (Clearly state all pertinent details, are of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Devon Energy Production Company, L.P. requests approval to re-complete to the World MIRU Pulling unit 2. Set CIBP @ 9600' above all Cisco perforations 3. Perforate Wolfcamp from 8922-8927, 8934-8942, 8944-8949, 8596-8610, 8511- 4. Acidize perforation and swab test same 5. Turn well over to production. I hereby certify that the information above is true and complete to the best of my knowledgrade tank has been/will be constructed or classed according to NMOCD guidelines , a general permit SIGNATURE TITLE Sr. Staff Engineering Type or print name Norvella dams	RECEIVED AUG 1 7 2005 Ge and belief. I further certify that any pit or below- lor an (attached) alternative OCD-approved plan Telephome No. (405) 552-8198 AUG 1 7 2005 DATE a C C I C I C C I C C .