

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

0JMW1232052348

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Devon Energy <u>6137</u>	Contact: Roy White
Address: 6488 Seven Rivers Highway, Artesia, N.M. 88210	Telephone No. 575-513-1741
Facility Name: Dickens 29 Fed 3H	Facility Type: Oil Well/API # 30-015-37220

Surface Owner	Mineral Owner	Lease No. NMNM-54856
---------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	29	16S	28E	2310'	North	330'	East	Eddy

NATURE OF RELEASE

Type of Release: produced water spill	Volume of Release: 285 bbls	Volume Recovered: 285 bbls
Source of Release: flow line separated from tank	Date and Hour of Occurrence: 11/6/2012, 6PM	Date and Hour of Discovery: 11/6/2012, 6PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brooke Owens, Lease Operator	
By Whom? Basic Energy Services	Date and Hour: 11/6/2012, 6:15PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RECEIVED
NOV 14 2012
NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A vacuum truck driver from Basic Energy Services was backing up to a load line when he hit it and caused it to separate from the tank. 285 bbls of produced water spilled rapidly into containment with 285 bbls recovered.

Describe Area Affected and Cleanup Action Taken.*
The 285 bbl spill occurred at the Dickens 29 Fed 3H location. Vacuum trucks were called to clean it up and the line was repaired to resume service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Rebecca Raga</u>	OIL CONSERVATION DIVISION	
Printed Name: Rebecca Raga	Approved by District Supervisor:	Signed By <u>M. H. [Signature]</u>
Title: Field Admin Tech	Approval Date: NOV 15 2012	Expiration Date:
E-mail Address: Rebecca.raga@dv.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/8/2012 Phone: 575-746-5564		

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION**

PROPOSAL NOT LATER THAN:

Dec. 15th 2012

2RP-1406