						FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 5: Lease Serial No.		
SUNDRY NOTICES AND REPORTS ON WELLS					NMLC064488E			
					If Indian, Allottee	or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side. 7 If						ement, Name and/or No.		
1. Type of Well ☐ Gas Well ☐ Other				•	8. Well Name and No. OTTAWA AOW FEDERAL 3			
2. Name of Operator Contact: TINA HUERTA YATES PETROLEUM CORPORATIONE-Mail: tinah@yatespetroleum.com					9. API Well No. 30-015-28897			
3a. Address 105 SOUTH FOURTH STREE ARTESIA, NM 88210	3b. Phone No. (include area code) Ph: 575-748-4168 Fx: 575-748-4585			0., Field and Pool, or Exploratory PENASCO; WOLFCAMP				
4. Location of Well (Footage, Sec., 7		11	11. County or Parish, and State					
Sec 10 T19S R25E NWNE 66			EDDY COUNT	Υ, NM				
12. CHECK APP	ROPRIATE BOX(ES) TO	) INDICATI	E NATURE OF I	NOTICE, REPC	ORT, OR OTHE	R DATA		
TYPE OF SUBMISSION	TYPE OF ACTION							
Notice of Intent	□ <sup>Acidize</sup>			□ Production		U Water Shut-Off		
Subsequent Report	□ Alter Casing		cture Treat					
-	Casing Repair		v Construction	Recomplete		□ <sup>Other</sup>		
□ Final Abandonment Notice	Change Plans	land.	g and Abandon g Back	Temporarily		•		
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Yates Petroleum Corporation plans to plugback and recomplete this well as follows: 1. MIRU all safety equipment as needed. NU BOP. 2. Make a GR/JB run down to 7768'; then set a 7" CIBP at 7758' with 25 sx cement on top. 3. Perforate Wolfcamp 6010'-6198'(22). 4. Acidize with 5000g 15% HCL with 2g/M gelling agent, cationic surfactant, corrosion inhibitor and iron control additives. Drop 40 1.3 SG RCN ball sealers spaced out evenly throughout the acid. Flush to bottom perf and over flush by 75 bbls. 5. Swab test and evaluate and consider combining lower zone and this zone and turning well over to production. If the zone is wet set a CIBP at 5960' with 35' cement on top. 6. Perforate Wolfcamp 5836'-5894'(17). 7. Acidize with 5000g 20% HCL with 2g/M gelling agent, cationic surfactant, corrosion inhibitor and iron control additives. Flush to bottom perf and over flush by 75 bbls. 6. Perforate Wolfcamp 5836'-5894'(17). 7. Acidize with 5000g 20% HCL with 2g/M gelling agent, cationic surfactant, corrosion inhibitor and iron control additives. Flush to bottom perf and over flush by 75 bbls. 6. Perforate Wolfcamp 5836'-5894'(17). 7. Acidize with 5000g 20% HCL with 2g/M gelling agent, cationic surfactant, corrosion inhibitor and iron control additives. Flush to bottom perf and over flush by 75 bbl								
14. Thereby certify that the foregoing is	true and correct.		PROVIDE CI			-DEC- <b>\$1</b> -2012		
14. Thereby certify that the foregoing is true and correct. Electronic Submission #160696 verified by the BLM Well Information System For YATES PETROLEUM CORPORATION, sent to the Carlsbad Committed to AFMSS for processing by KURT SIMMONS on 11/20/2012 ()								
Name(Printed/Typed) TINA HUE		or processing	-	EPORTING SUF		NOOD AITESIA		
	· · · .	· · ·			Λ			
Signature (Electronic S		0	Date 11/19/2		<u> </u>	PPROVED		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved By Conditions of approval, if any, are attached. Approval of this notice does not warrant o certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Title Office			DEC 2.7 2012 <u>J Date</u> J OF LAND MANAGEMENT RLSBAD FIELD OFFICE		
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a statements or representations as	crime for any p to any matter v	erson knowingly and within its jurisdiction	i willfully to make t				


\*\* OPERATOR-SUBMITTED \*\* OPERATOR-SUBMITTED \*\* OPERATOR-SUBMITTED \*\*


## Additional data for EC transaction #160696 that would not fit on the form

32. Additional remarks, continued

8. Swab test and evaluate and combine with lower zones, if they were productive.
9. TIH with tubing. RIH with pump and rods and hang well off. Turn well over to production.

Wellbore schematics attached





## **Conditions of Approval**

Yates Petroleum Corporation Ottawa AOW Federal 3 API 30-015-28897 T19S-R25E, Sec 10 December 27, 2012

Notify BLM at 575-393-3612 a minimum of 24 hours prior to commencing work.

Work to be completed by April 1, 2013. An extension can be submitted if necessary.

- 1. CIBP shall be set at 7758' (50' above the top perforation). A minimum of 35' of Class H cement shall be placed on top of the CIBP. Tag required.
- 2. CIBP shall be set at 5960' (50' above the top perforation). A minimum of 35' of Class C cement shall be placed on top of the CIBP. Tag required.
- 3. Functional  $H_2S$  monitoring equipment shall be on location.
- 4. Subject to like approval by the New Mexico Oil Conservation Division.
- Notify BLM 575-200-7902 before plug back procedures. The procedures are to be witnessed. If no answer, leave a voice mail with the API#, workover purpose, and a call back phone number. If there is no response, 575-361-2822. Note the contact, time, & date in your subsequent report.
- 6. Surface disturbance beyond the originally approved pad must have prior approval.
- 7. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 8. A minimum of 3,000 (3M) BOPE shall be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M) Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 9. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.

- 10. The BLM PET witness is to run tbg tally and agree to cement placement. Sample each plug for cement curing time and tag and/or pressure test (WOC time of 4 hours recommended) as requested by BLM PET witness.
- 11. Class H > 7,500' & Class C < 7,500') cement plugs(s) will be necessary. The minimum pumped volume of 25 sacks of cement slurry is to exceed a 100' cement plug across the drilled wellbore. Add 10% to the 100' slurry volume for each 1,000' of plug depth when calculations indicate the need. For any plug that requires a tag or pressure test a minimum WOC\_time of 4 hours(C) & 8 hours(H) is recommended. Formation isolation plugs of Class "C" to be mixed 14.8#/gal, 1.32 ft<sup>3</sup>/sx, 6.3gal/sx water and "H" to be mixed 15.6#/gal, 1.18ft<sup>3</sup>/sx, 5.2gal/sx water.
- 12. Minimum requirement for mud placed between plugs is 25 sacks of salt water gel per 100 barrels in 9 lb/gal brine.
- 13. File intermediate **subsequent sundry** Form 3160-**5** within 30 days of any interrupted workover procedures and a complete workover subsequent sundry. File the subsequent sundry for the frac separately if it is delayed as much as 20 days.
- **14.** Submit the BLM Form 3160-4 **Completion Report** within 30 days of the date all BLM approved procedures are complete. **Include all formation tops.**
- 15. Workover approval is good for 90 days (completion to be within 90 days of approval). A detailed justification is necessary for extension of that date.
- 16. Submit evidence to support your determination that the well has been returned to active "beneficial use" for BLM approval on the Sundry Notice Form 3160-5 (the original and 3 copies).
- 17. Should "beneficial use" not be achieved submit for BLM approval a plan for plug and abandonment.

JAM 122712

Access information for use of Form 3160-5 "Sundry Notices and Reports on Wells"

NM Fed Regs & Forms - http://www.blm.gov/nm/st/en/prog/energy/oil\_and\_gas.html

§ 43 CFR 3162.3-2 Subsequent Well Operations.

§ 43 CFR 3160.0-9 (c)(1) Information collection.

§ 3162.4-1 (c) Well records and reports.