

Submit 3 Copies To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 1301 W. Grand Ave., Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 May 27, 2004

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-015-10182
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 243874
7. Lease Name or Unit Agreement Name: State 647 AC 713
8. Well No. 200
9. OGRID Number
10. Pool name or Wildcat Artesia; Queen-Grybg-San Andres

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well Other

2. Name of Operator
Quantum Resources Management, LLC

3. Address of Operator
1401 McKinney St. Ste, 2400, Houston, TX 77010

4. Well Location
 Unit Letter **M** : **660** feet from the **South** line and **330** feet from the **West** line
 Section **23** Township **18-S** Range **28-E** NMPM County **Eddy**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3537

Pit or Below-grade Tank Application or Closure


Pit type: _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____
 Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- MIRU plugging equipment. ND well head, NUBOP.
- RIH and set 4 1/2 CIBP @ 2500'. Circulate hole with mud laden fluid. Spot 15 sx cement on top of CIBP.
- Perf 4 1/2 casing and Sqz. 75 sx cement @ 550'. WOC and Tag.
- Perf 4 1/2 casing and Sqz. 75 sx cement @ 60'. Circulate to surface.
- Cut off wellhead and weld on Dry Hole Marker.



**Notify OCD 24 hrs. prior
 To any work done.**

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan .

SIGNATURE *Roger D. Brooks* TITLE Agent DATE 01/28/13

Type or print name For State Use Only E-mail address: _____ Telephone No. _____
 APPROVED BY *R. H. Hankin* TITLE _____ DATE 1/31/2013
 Conditions of Approval (if any): _____
 Approval Granted providing work is complete by 5/1/2013

4 1/2" @ 2850' w/ 100 SX

CIR @ 2500

15 SX @ 2400 - 2500

8 5/8" @ 500' 75 SX

PAGES 2533-2539
2829-2834
2838-2864

Quantum Resources
30-015-10182
STATE 647 AC 713 # 200
M-23-18.5-28-E

Quantum Resources Management, LLC

State 647 AC 713 #200

Unit M Sec. 23, T-18S, R-28E

Eddy Co., NM

API #: 30-015-10182

Equipment & Design:

Lone Star Oil & Gas, Inc. will use a closed loop system in the plug and abandonment of this well. The following equipment will be on location:

- (1) 250 bbl steel reverse tank

Operations & Maintenance:

During each day of operation, the rig's crew will inspect and closely monitor the fluids contained within the steel tank and visually monitor any release that may occur. Should a release, spill or leak occur, the NMOCD District 1 office Hobbs (575-393-6161) will be notified, as required in NMOCD's rule 19.15.29.8.

Closure:

After plugging operations, fluids and solids will be hauled and disposed at Gandy-Marley Disposal's location, permit number NM 01-0019. Secondary site will be Sundance Disposal, permit number NM 01-0003.

NEW MEXICO OIL CONSERVATION DIVISION
DISTRICT 2 OFFICE
811 S. FIRST STREET
ARTESIA, NM 88210
(575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: Quantum Resources Management, LLC

Well Name & Number: Stete 647 AC 713 #200

API #: 30-015-10182

1. Produced water will not be used during any part of the plugging & abandonment operation.
2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
4. Trucking companies being used to haul oilfield waste fluids to a disposal – commercial or private – shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
5. A subsequent C-103 will serve as notification that the well bore has been plugged **ONLY**. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
6. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
7. Every attempt must be made to clean the well bore out to below the perms, before any plugs can be set, by whatever means possible.

8. Cement Retainers may not be used.
9. Squeeze pressures not to exceed 500 psi., unless approval is given by NMOCD Plugging Supervisor.
10. Plugs may be combined after consulting with NMOCD P & A Supervisor.
11. Minimum WOC time for tag plugs will be 4 hrs.

DG

Date: 1/31/2013