Form 3160-5 (September 2001)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

HECEIVEL SEP 2 3 2005 OCD-AFTERIA

FORM APPROVED OMB No. 1004-0135

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or re enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

Expires January 31, 2004 5. Lease Serial No.

NM-025614

abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allotte	6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side				7. If Unit or CA/Ac	7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well X Oil Well Gas Well Other				8. Well Name and	8. Well Name and No.	
2. Name of Operator				WLH G4S T	WLH G4S Tract 21A #2	
Yates Petroleum Corporation				9. API Well No.	-	
3a. Address	3b. Phone No. (include	,		30-015-04524		
105 S. 4th Str., Artesia, NM	505-748-	505-748-1471		10. Field and Pool, or Exploratory Area Loco Hills Queen Grayburg San Andres		
4. Location of Well (Footage, Sec.,T.,R.,M., OR Survey Description)				11. County or Parish, State		
660'FNL & 660'FWL of Section 18-T18S-R30E (Unit D, NWNW)					Eddy County, New Mexico	
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, RI						
TYPE OF SUBMISSION	TYPE OF ACTION					
	Acidize	Deepen	Production	on (Start/Resume)	Water Shut-Off	
X Notice of Intent	Alter Casing	Fracture Treat	Reclamati	on	Well Integrity	
Subsequent Report	Casing Repair	New Construc	ion Recomple	ete	Other	
	Change Plans	X Plug and Aban	don Tempora	rily Abandon		
Final Abandonment Notice	Convert to Injection	Plug Back	Water Dis	sposal		
following completed of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Yates Petroleum Corporation plans to plug and abandon this well as follows: 1. Rig up all safety equipment as needed. No casing recovery will be attempted. 2. Set a 7" CIBP at 2711' with 35' cement on top. 3. Perforate 7" casing at 1175'. Spot 75 sx cement plug from 1175'-1075'. Tag plug. 4. Perforate 7" casing at 484'. Spot 135 sx cement plug from 484'-384'. Tag plug. 5. Spot 15 sx Class "C" cement plug at surface. 6. Install dry hole marker, clean and restore location as per regulated. NOTE: Yates Petroleum Corporation will use steel pits and no earth pits						
14. I hereby certify that the foregoing is true Name (Printed/Typed)	and correct		The state of the s			
Tina Huerta	Title	Title Regulatory Compliance Supervisor				
Signature (Jina) Lunta Date September 20, 2005						
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved by			Title	Dat	e	
Conditions of approval, if any, are attached certify that the applicant holds legal or equi which would entitle the applicant to conduct or	Office	Accepted for record NMOCD				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willbully to make to any department or agency of the United

States any false, fictitious or <u>fraudulent</u> statements or representations as to any matter within its jurisdiction



