

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

JMW 134127699

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: BOPCO, L.P. 260737		Contact: Tony Savoie	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 575-887-7329	
Facility Name: James Ranch Unit #17 Tank Battery		Facility Type: Exploration and Production	
Tank Battery is on the same pad as the Well #17			

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-27784
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter E	Section 6	Township 23S	Range 31E	Feet from the 2080	North/South Line North	Feet from the 1980	East/West Line West	County: Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	--------------

Latitude N 32.335180 Longitude W 103.819280

NATURE OF RELEASE

Type of Release: Crude oil and produced water	Volume of Release: 5 Bbls. oil and 15 Bbls. produced water	Volume Recovered: 5 Bbls. oil
Source of Release: 2" circulating line	Date and Hour of Occurrence: 4/26/13 Time unknown	Date and Hour of Discovery: 4/26/13 at 10:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

MAY 17 2013

NMOCD ARTESIA

Describe Cause of Problem and Remedial Action Taken.*

The circulating line on the 500 Bbl. oil production tank failed due to corrosion. The line and the tank were replaced.

Describe Area Affected and Cleanup Action Taken.* The entire surface area of the earthen containment around the production tanks was affected by the release. The area measures approximately 3000 sq. ft. No remediation activities have taken place, new gravel was placed over the spill area inside the containment area. The affected area will be remediated in accordance to the NMOCD guidelines, the tank battery will be evaluated for re-construction inside impervious containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist: Signed By <i>Mike Brannan</i>	
Title: Waste Management and Remediation Specialist		Approval Date: MAY 21 2013	Expiration Date:
E-mail Address: tasavoie@basspet.com		Conditions of Approval:	
Date: 5/16/13 Phone: 432-556-8730		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

Remediation per OCD Rule &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NO LATER THAN:**

June 21, 2013

2RP-1657