

District I – (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II – (575) 748-1283
811 S. First St., Artesia, NM 88210
District III – (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV – (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87501

RECEIVED

013 OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-005-62887	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. V-5961 & VB-0402	
7. Lease Name or Unit Agreement Name Conestoga State	
8. Well Number 1	
9. OGRID Number 001092	
10. Pool name or Wildcat Palma Mesa ; <i>WCamp</i>	
_____ feet from the _____ East _____ line NMPM Chaves County	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

Armstrong Energy Corporation

3. Address of Operator

P.O. Box 1973, Roswell, NM 88202-1973

4. Well Location

Unit Letter P : 330 feet from the South line and 990 feet from the East line
 Section 14 Township 8S Range 27E NMPM Chaves County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>	PLUG AND ABANDON	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	MULTIPLE COMPL	<input type="checkbox"/>
DOWNHOLE COMMINGLE	<input type="checkbox"/>		

OTHER:

1

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
 COMMENCE DRILLING OPNS. ☐ P AND A ☐
 CASING/CEMENT JOB ☐

OTHER:

Perf & acidize

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

08-23-13 RIH w/ 4-1/2" CIBP, set @ 6186', POH. RIH w/ Dump Bailer, dump 35' of cement on top of CIBP, test CIBP @ 1000 psi, OK. POH. SDON.

08-27-13 Spot 200 gals 15% NEFE acid @ 5614', Perf 5608'-5614', 8', 4 JSPF, 33 holes, POH. TIH w/ pkr and tbq, reverse acid, set pkr, break down @ 2460 psi, Est. Rate of 3.2 BPM @ 1600 psi, displace acid. ISIP 1054 psi, 5 min 569 psi, 10 min 129 psi, 15 min, vacuum.

08-28-13 Unseat pkr and POH w/ tbg and pkr, lay down tbg. RU, RIH w/ 5-1/2" CIBP, set @ 5575', POH. RIH w/ Dump Bailer, dump 35' cement on top of CIBP (top of liner hanger @ 6071'), POH, RD. Secure WH, RD pulling unit and release equipment. SD pending further evaluation.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE Vice President - Operations DATE 8-28-2013

Type or print name Bruce Stubbs E-mail address: bastubbs@armstrongenergycorp.com PHONE: 575-625-2222

For State Use Only

APPROVED BY: [Signature] TITLE Dist H Supervisor DATE 8/29/2013

Conditions of Approval (if any):