

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

SEP 10 2013

NMOCD ARTESIA

Form C-141  
Revised October 10, 2003

Submit a Copy to appropriate District Office in accordance with 19.15.29 NMAC

Release Notification and Corrective Action

nJMW 1326252893

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating 269324	Contact: Brian Wall
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: McClay Federal # 7	Facility Type: Oil Producer

Surface Owner: Federal	Mineral Owner:	API No.: 3001510370
------------------------	----------------	---------------------

LOCATION OF RELEASE

Unit Letter C	Section 33	Township 18S	Range 30E	Feet from the 330	North/South Line North	Feet from the 1650	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: 32.7103208597655 Longitude: -103.980175130974

NATURE OF RELEASE



Type of Release: Produced Water / Oil	Volume of Release: 4bbls/ 1bbl	Volume Recovered: 4 bbls / 1 bbl
Source of Release: Heater	Date and Hour of Occurrence: 09/08/2013 12:00am	Date and Hour of Discovery: 09/08/2013
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Burton- BLM Mike Bratcher-NM OCD	
By Whom? Brian Wall	Date and Hour 09/10/2013	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*:

Describe Cause of Problem and Remedial Action Taken.\*: Hole in bottom of heater in side base ring.

Describe Area Affected and Cleanup Action Taken.\* : All fluid in dike area picked up with vacuum truck emptied heater. Cause degradation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Brian Wall	Approved by District Supervisor:	Signed By: 
Title: Construction Foreman II	Approval Date: SEP 19 2013	Expiration Date:
E-mail Address: bwall@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 09/10/2013 Phone: 806-367-0645	Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	

\* Attach Additional Sheets If Necessary

Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:

October 19, 2013

2RP-1914