


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011
Submit 1 Copy to appropriate District Office in NMOC D ARTESIA with 19.15.29 NMAC.

Release Notification and Corrective Action

NJMW1334052817

OPERATOR

Initial Report Final Report

Name of Company	Oxy Permian Ltd. <i>16696</i>	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Federal 12 #1 South CTB	Facility Type	Gathering

Surface Owner	BLM	Mineral Owner	API No.30-015-26742(nearest well)
---------------	-----	---------------	-----------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	12	22S	31E					Eddy County, NM

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	45 bbls	Volume Recovered	40 bbls
Source of Release	Pump failure caused tank overflow	Date and Hour of Occurrence	11/17/2013	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOC D; James Amos- BLM		
By Whom?	Chancey Summers	Date and Hour	11/19/13 @ 9:04am and 11/18/13 @ 2:07pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A bearing on the water transfer pump went out causing the pump to fail and the water production tank to overflow. The overflow caused 45 bbls of produced water to leak onto the ground. A vacuum truck recovered 40 bbls of the leaked fluids and the pump was replaced.

Describe Area Affected and Cleanup Action Taken.*
The affected area is approximately 30' x 30' on location. Remediation will be completed in accordance with a remediation plan approved by NMOC D and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:
Printed Name: Chancey Summers
Title: HES Specialist
E-mail Address: Chancey.Summers@oxy.com
Date: *12/2/13* Phone: (575) 397-8216

Approved by Environmental Specialist:
Signed By:

Approval Date: *DEC 04 2013* Expiration Date:

Conditions of Approval:
Remediation per OCD Rule & Guidelines, & like approval by BLM. **SUBMIT REMEDIATION**

Attached

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:
January 6, 2014

2RP-2097