Form 3 (60-5 (August 2007)

1. Type of Well

2. Name of Operator

Oil Well

Gas Well

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

5. Lease Serial No.

East Shugart Unit

8. Well Name and No. ESU # 17

9. API Well No.

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

Other

SUBMIT IN TRIPLICATE - Other instructions on page 2.

6. If Indian, Allottee or Tribe Name

7. If Unit of CA/Agreement, Name and/or No.

Americo Energy Resources, LLC		30-015-05686	30-015-05686		
3a. Address		3b. Phone No. (include area c	ode) 10. Field and Pool or	10. Field and Pool or Exploratory Area	
7575 San Filpie, Ste. 200 ,Houston, TX 77063		713-984-9700	Shugart: Yates- 7Rs	Shugart: Yates- 7Rs-Queens- Grayburg	
4. Location of Well (Footage, Sec., T. 1650' FSL & 2310' FWL of Sec. 34, T-18S, R 3		n) 11. Country or Par Eddy. NM		State	
12. CHE	CK THE APPROPRIATE BO	X(ES) TO INDICATE NATUR	RE OF NOTICE, REPORT OR OTH	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
✓ Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Production (Start/Resume) Reclamation	Water Shut-Off Well Integrity	
Subsequent Report	Casing Repair Change Plans	New Construction Plug and Abandon	Recomplete Temporarily Abandon	Other	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal		

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has

- 1- MIRU workover rig, ND wealhead NU BOP
- 2- Pull the well, Scan out and pressure test tubings.

determined that the site is ready for final inspection.)

3- Replace tbgs as needed.

(Instructions on page 2)

- 4- Tag bottom to make sure perfs are not covered.
- 5 RIH w/ SN and tbgs and put well back on pump.

Accepted for record
NMSCD

MAR 1 4 2014
NMOCD ARTESIA

fictitious or fraudulent statements or representations as to any matter within its jurisdiction

SEE ATTACHED FOR CONDITIONS OF APPROVAL

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Mehdi Sadeghi Title	Petroleum Engineer	
Signature Weber she Land	9 01/06/2014	APPROVED
THIS SPACE FOR FEDERAL	OR STATE OF	FICE USE
Approved by	Title	MAR 1 1 2014
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office 3	BUDAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person	knowingly and willfully to	

East Shugart Unit 17 30-015-05686 Americo Energy Resources, LLC. March 11, 2014 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by June 11, 2014.

- 1. Must conduct a casing integrity test to a minimum of 500 psi. Submit results to BLM. The CIT is to be performed on the production casing per Onshore Oil and Gas Order 2.III.B.1.h.
- 2. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 3. Surface disturbance beyond the originally approved pad must have prior approval.
- 4. Closed loop system required.
- 5. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 6. Operator to have H2S monitoring equipment on location.
- 7. A minimum of a **2000** (**2M**) **BOP** to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 8. Subsequent sundry required detailing work done. Operator to include well bore schematic of current well condition when work is complete.

JAM 031114