Form 3160-5 (August 2007)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					5. Lease Serial No. NMLC029392B  6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No SRM1403		
1. Type of Well ☐ Oth ☐	**************************************	8. Well Name and No. GREENWOOD FEDERAL COM 2					
2. Name of Operator CHEVRON USA INCORPORA	RILLO CHEVRON.COM	·	9. API Well No. 30-015-30680-00-S1				
3a. Address 15 SMITH ROAD MIDLAND, TX 79705		3b. Phone No. (include area code) Ph: 575-263-0431 , Fx: 575-391-6679		W	10. Field and Pool, or Exploratory SHUGART		_
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			-		11. County or Parish,	and State	_
Sec 27 T18S R31E NWNW 1202FNL 660FWL				Y	EDDY COUNTY	Y, NM	
12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE	NATURE OF N	OTICE, RI	EPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION		TYPE OF	ACTION		•		
Notice of Intent	¹ ☐ Acidize	☐ Dee	oen `	☐ Product	ion (Start/Resume)	☐ Water Shut-Off	_
M Notice of Intent	☐ Alter Casing .	☐ Frac	ture Treat	☐ Reclam	ation *	■ Well Integrity	
☐ Subsequent Report	☐ Casing Repair	· New	Construction	Recomp	olete	Other	
Final Abandonment Notice	☐ Change Plans ☐ Plug		g and Abandon Tempo		arily Abandon	•	
☐ Convert to Injection ☐ Plug Back		Back	☐ Water D	☐ Water Disposal			
If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final Abdetermined that the site is ready for fill the procedure of t	rk will be performed or provide operations. If the operation re	the Bond No. or sults in a multiple ad only after all	file with BLM/BIA. completion or recon	Required sul apletion in a r	bsequent reports shall be new interval, a Form 316 in, have been completed.  ACCEDIED INMORATIONS OF ATTACHED STATIONS OF ATTACHED STAT	filed within 30 days 0-4 shall be filed once and the operator has  FOR PROVAL APPROVAL	
14. I hereby certify that the foregoing is	Electronic Submission #	231922 verifie	by the BLM Well	Information	System M	DCD ARTES A	
Comi	mitted to AFMSS for proce	ssing by JEN	IFER MASON on C	2/04/2014 (	14JAM0061SE)	CD API	
Name(Printed/Typed) CINDY H I	MURILLO		Title PERMIT	TING SPEC	CIALIST		_
Signature (Electronic S	lubmission)		Date 01/13/20	14	APPROVI		
	THIS SPACE FO	OR FEDERA	L OR STATE O	FFICE U	SE NAR 2 6/26	TARK	_
Approved By			Title		( monden !	1/and	=
onditions of approval, if any, are attached. Approval of this notice does not warrant or partify that the applicant holds legal or equitable title to those rights in the subject lease hich would entitle the applicant to conduct operations thereon.			Office	BU	CARLSBYD FIELD C	OFFICE	_

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

#### Additional data for EC transaction #231922 that would not fit on the form

#### 32. Additional remarks, continued

RESULT FOR SQUEEZE RECOMMENDATION.

8. TOH W/PKR AND WORKSTRING. IF NECESSARY, PERF SQZ HOLES TO OBTAIN RATE. TIH
W/CICR AND SET @ +/- 100' ABOVE TOP, HOLE.

9. ESTABLISH RATE/PRESSURE. RIG UP CMT COMPANY, SQZ HIC ACCORDING TO RECOMMENDATION.
SQUEEZE TO 2000#. STING OUT & SPOT CMT TO TOP, TOH W/WORKSTRING. SHUT DOWN FOR 48 HRS.

10. P/U 4 3/4' BIT, SUB, AND DC'S. TIH AND DO CICR AND CEMENT. TO RBP. L/D'
SWIVEL AND TEST CSG TO 500#. POOH AND L/D DC'S.


11. RIH W/PERF GUN & PERF 4 SPF F/11, 204-209 AND 11,212-226 (76 HOLES). NOTE
ANY GAS OR FLUID FLOW. RD WIRELINE.

12. P/U 1 JT TAILPIPE, PKR, SN AND REMAINDER OF STRING. SET PKR @ +/= 11,050'.
MIRU ACID TRUCKS, TEST LINES, PRESSURE UP ON CSG TO 500#, ESTABLISH RATE/
PRESSURE W/ 2% KCL.

13. ACDZ ATOKA W/3000 GALS 7.5% HC1 AND 50 BALL SEALERS. FLUSH ACID TO PERFS
W/2% KC1. MAX PRESSURE= 7000#. RECORD 1SIP; 5,10,15 MIN. SDFN.

14. OPEN WELL UP AND FLOW BACK LOAD. RECORD VOLUMES/RATES. UNSET PKR AND TOH.
RIH W/SN AND OPEN ENDED PRODUCTION STRING. SET EOT @ =/- 11,175.

15. SWAB WELL TO DETERMINE GAS INFLOW. DROP BUMPER SPRING, INSTALL PLUNGER LIFT
ASSEMBLY. TURN TO PRODUCTION. OBTAIN WELL TEST AND INPUT INTO E VIN.
ATTACHED COPY OF WELLBORE DIAGRAM.



## Greenwood Federal Com 2 30-015-30680 Chevron U.S.A Inc. March 26, 2014 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by June 26, 2014.

- 1. Operator shall set a CIBP at 11,650'and test casing as described by operator.
  - a. If no leak is discovered operator shall place 25 sx of Class C cement on top of the CIBP. Tag required.
  - b. If a leak is discovered operator shall submit a plan of remediation to the BLM (No squeeze jobs will be done without BLM approval).
- 2. Must conduct a casing integrity test before perforating and fracturing. Submit results to BLM. The CIT is to be performed on the production casing to <u>max</u> <u>treating pressure</u>. Notify BLM if test fails.
- 3. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 4. Surface disturbance beyond the originally approved pad must have prior approval.
- 5. Closed loop system required.
- 6. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 7. Operator to have H2S monitoring equipment on location.
- 8. A minimum of a **3000** (**3M**) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.

- 9. Subsequent sundry required detailing work done, a C-102 form, and completion report for the new formations. Operator to include well bore schematic of current well condition when work is complete.
- 10. See attached general requirements

JAM 032614

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

### **General Requirements for Plug Backs**

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from this approval.

If you are unable to plug back the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat** Class "C", for up to 7,500 feet of depth or **Neat** Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Subsequent Plug back Reporting:</u> Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed.</u>
- 7. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.