

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

nHMP14175-34282 OPERATOR  Initial Report  Final Report

Name of Company: Clayton Williams 257.06	Contact: Luis Gonzales
Address: 6-Desta Drive Suite 6700 Midland, TX 79705	Telephone No: (432) 682-6324
Facility Name: Philips 19 Fed #3	Facility Type: Well
Surface Owner: BLM	Mineral Owner: BLM
API No. 30-015-31445	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	19	17S	29E					Eddy

Latitude 32.82595 Longitude 104.108499

**NATURE OF RELEASE**

Type of Release: Oil/PW	Volume of Release: 9	Volume Recovered: 2
Source of Release: Flowline Leak	Date and Hour of Occurrence: 6/11/2014	Date and Hour of Discovery: 6/11/2014 @9:40 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Emailed Jim Amos with BLM	
By Whom? Dave Dunlap	Date and Hour: 6/11/2014 @ 10:00 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

**NM OIL CONSERVATION**  
ARTESIA DISTRICT

JUN 20 2014

RECEIVED

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
The cause of the release was a leak on the flowline. On 6/11/2014 a crew repaired the leak on the flowline, and a vacuum truck picked up approx. 2 barrels from the site. A one call was called in and further remedial action will take place once the one call is cleared.

Describe Area Affected and Cleanup Action Taken.\*  
The area affected is approximately 90' X 75' pasture which is made up of sand dunes and mesquites. This area is located 520' south of the location by the lease road. Will perform the following tasks: Call in one call for the area affected. Then delineate the spill. Once the results of the samples are known we will get with BLM to take the appropriate steps to clean up the site.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature: <i>Dave Dunlap</i>	Approved by Environmental Specialist: <i>[Signature]</i>	
Printed Name: DAVE DUNLAP	Approval Date: 6/24/14	Expiration Date: NA
Title: Prod. Foreman	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	
E-mail Address: ddunlap@claytonwilliams.com	Attached <input type="checkbox"/>	
Date: 6-12-14	Phone: 575-390-2062	

PROPOSAL NO LATER THAN:

7/24/14

2RP-2349