

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*nHMP1419937403*

**OPERATOR**  Initial Report  Final Report

Name of Company: BOPCO, L.P. <i>240 737</i>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Poker Lake Unit 303 Tank Battery	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-37646	

**LOCATION OF RELEASE**

Unit Letter N	Section 4	Township 25S	Range 31E	Feet from the 1264	North/South Line South	Feet from the 2310	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude N 32.155387 Longitude W 103.784570

**NATURE OF RELEASE**

Type of Release: Crude Oil	Volume of Release: 28 bbls crude oil	Volume Recovered: 5 bbls
Source of Release: Facility sump	Date and Hour of Occurrence: 7/8/14 time unknown	Date and Hour of Discovery: 7/8/14 at approximately 3:00 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher NMOCD	
By Whom? Tony Savoie	Date and Hour: 7/9/14 at 9:00 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

**NM OIL CONSERVATION**

ARTESIA DISTRICT

JUL 10 2014

**RECEIVED**

Describe Cause of Problem and Remedial Action Taken.\*  
A valve was left open on the circulating pump to the sump suction line causing the sump to overflow. Valves were aligned in the correct position.

Describe Area Affected and Cleanup Action Taken.\*  
The spill impacted approximately 1355 sq.ft. of mostly pasture area. The free standing fluid was recovered, the stained soil was left as is pending remediation. The impacted area will be cleaned up in accordance to the NMOCD and BLM guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tony Savoie	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Waste Management and Remediation Specialist	Approval Date: <i>7/18/14</i>	Expiration Date: <i>NA</i>
E-mail Address: <i>tasavoie@basspet.com</i>	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. <b>SUBMIT REMEDIATION</b>	
Date: 7/10/14	Phone: 432-556-8730	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

**PROPOSAL NO LATER THAN:**

*8/18/14*

*ZRP-2374*