										CEIVI	1			
<u>)istrict 1</u> 625 N. French Dr., Hobbs, NM 88240 <u>)istrict 11</u> 301 W. Grand Avenue, Artesia, NM 88210									Form C- Revised October 10,					
histrict III	,	,			Oil	Conse	rvation Div	vision L		ibmit Copy	Si A i	riate District Offi		
000 Rio Brazos Road, Aztec, NM 87410 <u>District IV</u> 220 S. St. Francis Dr., Santa Fe, NM 87505				1220 South St. Francis Dr.						with 19.15.29 M				
220 S. St. Francis	s Dr., Santa	Fe, NM 87505				Santa F	e, NM 875	05						
			Re	lease	Notific	cation	and Co	rrective A	ction	l				
<u>1 AB147</u>	2095	54722	2.	- 0 /	000	.	OPERAT			🛛 Initia	Report	🔲 Final Re		
Name of Com Address: 213				<u> </u>	432	7-	Contact: Bri	ian Wall No.: 575-738-	1739			_		
Facility Name			, , , , , , , , , , , , , , , , , , , ,	00210			Facility Typ		1105					
Surface Owner: Federal				Mineral	Ówner	,			APIN	o.: 30-015	-26024			
		ui						EASE			5 50 015			
Unit Letter	Section	Township	Rang	e Fe	EUCA et from the		N OF REL h/South Line	EASE Feet from the	e East	/West Line	County			
D	10	175	31E		560		North	660		West		Eddy		
I	l		Lati	tude: 3	2.854783	757378	1 Longitude	e: -103.86406)735174	1	1			
					<u>NA</u>	TURE	OF RELE							
Type of Releas								f Release: 22 bt			Recovered			
Source of Release: fiberglass pipeline						Date and Hour of Occurrence:Date and Hour of Discovery:07/19/201407/19/20142:45pm								
Was Immediate	e Notice C		Yes	□ No	Not	Required	If YES, To Jeff Rober	Whom? tson- BLM / N	/like Bra	tcher-NMO	CD			
By Whom? Bri	ian Wall							Hour 07/21/201	4 0900					
Was a Waterco	ourse Reac		Vac	Was a Watercourse Reached?					If YES, Volume Impacting the Watercourse.					
							1 ·							
If a Watercours	se was Im	pacted, Descri												
Describe Cause	e of Proble k on trunk	em and Reme line,upon dri	ibe Ful dial Ac	lly.*: ction Ta n west E	<pre>ken.*: At 2 #40 looki</pre>	ng east o						ow pressure. Wer . At 3:15 P.M. ca		
Describe Cause looking for lea for a truck to p	e of Proble k on trunk vickup wate	em and Reme line,upon dri er.Notified Ri	ibe Ful dial Ac iving o ick Ric	lly.*: ction Ta n west E kman at	Ken.*: At 2 #40 looki 3:30 P.M.	ng east o of leak.	f location at 3:	P.M. found wa	ter comi	ng out of no	rth tinhorn	. At 3:15 P.M. ca		
Describe Cause looking for lea for a truck to p Describe Area looking bigger trunk line. Afte water off of gro Directions to s	e of Proble k on trunk vickup wat than area er empying ound. Wil vite: From	em and Reme line,upon dri er.Notified Ri actually was g tinhorn, dete l have to do o Loco Hills N.	dial Action to due ermine ne call M. go	lly.*: ction Ta n west E kman af Taken.* rain in a d that le before l east on	ken.*: At 2 #40 looki 3:30 P.M. : Area of y rea.) At 4: ak was on ine can be Hwy 82 3.5	ng east o of leak. water on 30 P.M. lateral lin repaired. 5 miles,tu	f location at 3: ground was 22 truck on locati ne. was able to irn left on CR2	P.M. found wa 2feet long X 21 ion, went to em isolate lateral,	feet wid ptying ti to get fic to dirt r	ng out of no le by 2in dee nhorn to see eld back goir oad on right	rth tinhorn p. (picture if leak wa ng. Picked ,turn right			
Describe Cause looking for lea for a truck to p Describe Area looking bigger trunk line. Afte water off of gro Directions to s go .6 mile turn	e of Proble k on trunk vickup wat than area er empying ound. Wil vite: From h left, go .5	em and Reme line,upon dri er.Notified Ri actually was g tinhorn, deta l have to do o Loco Hills N.	dial Action to due ermine ne call M. go	Taken.* rain in a d that le before east on 2.0 mile	xen.*: At 2 #40 looki 3:30 P.M. : Area of y rea.) At 4: ak was on ine can be Hwy 82 3.5 s to West E	ng east o of leak. water on 30 P.M. lateral lin repaired. 5 miles,tu 8#40 spil	f location at 3: ground was 22 truck on locati ne. was able to irm left on CR2 l is 25 yds east	P.M. found wa 2feet long X 21 ion, went to em isolate lateral, 221 gol.4 miles t of location in	feet wid ptying ti to get fie to dirt r pasture,	ng out of no be by 2in dee nhorn to see eld back goir oad on right at the tinhor	rth tinhorn p. (picture if leak wa ng. Picked turn right ns.	. At 3:15 P.M. ca s make the spill s on lateral line of up about 7 barrell go .5 mile,turn rig		
Describe Cause looking for lea for a truck to p Describe Area looking bigger trunk line. Afte water off of gro Directions to s go .6 mile turn I hereby certify regulations all public health o should their op	e of Proble k on trunk bickup wat than area er empying ound. Wil- ite: From h left, go .5 y that the i operators or the envin perations h ment. In a	em and Reme tine,upon dri er.Notified Ri and Cleanup 4 actually was t g tinhorn, dete l have to do o Loco Hills N. i mile turn rigi information gi are required to ronment. The tave failed to a ddition, NMC	dial Ac iving o ick Ric Action to due ermine ne call M. go ht, go iven ab o repor	Taken.* rain at before l east on 2.0 mile	xen.*: At 2 #40 looki 3:30 P.M. : Area of y rea.) At 4: ak was on ine can be Hwy 82 3.5 s to West E ue and con file certain a C-141 re estigate and	ng east o of leak. water on 30 P.M. lateral lin repaired. 5 miles,tu 8#40 spil	f location at 3 ground was 22 truck on locati ne. was able to irrn left on CR2 l is 25 yds east the best of my notifications a he NMOCD m ate contaminat	P.M. found wa 2feet long X 21 ion, went to em isolate lateral, 221 gol.4 miles t of location in whether the set of	feet wid ptying ti to get fie to dirt r pasture, i d unders rective a l Report threat to of respon	ng out of nor be by 2in dee nhorn to see eld back goir oad on right, at the tinhor tand that pur ctions for re ground wate nsibility for	p. (picture if leak wa ng. Picked turn right ns. rsuant to N leases whi lieve the o er, surface compliance	At 3:15 P.M. ca s make the spill s on lateral line of up about 7 barrell go .5 mile,turn rig MOCD rules and ch may endanger perator of liability water, human hea e with any other		
Describe Cause looking for lea for a truck to p Describe Area looking bigger trunk line. Afte water off of gro Directions to s go .6 mile turn I hereby certify regulations all public health o should their op or the environr	e of Proble k on trunk bickup wat than area er empying ound. Wil- ite: From h left, go .5 y that the i operators or the envin perations h ment. In a	em and Reme tine,upon dri er.Notified Ri and Cleanup 4 actually was t g tinhorn, dete l have to do o Loco Hills N. i mile turn rigi information gi are required to ronment. The tave failed to a ddition, NMC	dial Ac iving o ick Ric Action to due ermine ne call M. go ht, go iven ab o repor	Taken.* rain at before l east on 2.0 mile	xen.*: At 2 #40 looki 3:30 P.M. : Area of y rea.) At 4: ak was on ine can be Hwy 82 3.5 s to West E ue and con file certain a C-141 re estigate and	ng east o of leak. water on 30 P.M. lateral lin repaired. 5 miles,tu 8#40 spil	f location at 3 ground was 22 truck on locati ne. was able to irrn left on CR2 l is 25 yds east the best of my notifications a he NMOCD m ate contaminat	P.M. found wa 2feet long X 21 ion, went to em isolate lateral, 221 gol.4 miles t of location in whether the set of	feet wid ptying ti to get fie to dirt r pasture, i d unders rective a l Report threat to of respon	ng out of no be by 2in dee nhorn to see eld back goir oad on right, at the tinhor tand that pur ctions for re ground wate	p. (picture if leak wa ng. Picked turn right ns. rsuant to N leases whi lieve the o er, surface compliance	At 3:15 P.M. ca s make the spill s on lateral line of up about 7 barrell go .5 mile,turn rig MOCD rules and ch may endanger perator of liability water, human hea e with any other		
Describe Cause looking for lea for a truck to p Describe Area looking bigger trunk line. Afte water off of gr Directions to s go .6 mile turn I hereby certify regulations all public health o should their op or the environr federal, state, c	e of Proble k on trunk bickup wat Affected a than area er empying ound. Wil ite: From b left, go .5 y that the i operators or the envin berations h ment. In a bor local law	em and Remet line,upon dri er.Notified Ri and Cleanup / actually was i g tinhorn, det l have to do o Loco Hills N. i mile turn rigi information gi are required to ronment. The ave failed to a ddition, NMC ws and/or regu	dial Ac iving o ick Ric Action to due ermine ne call M. go ht, go iven ab o repor	Taken.* rain at before l east on 2.0 mile	xen.*: At 2 #40 looki 3:30 P.M. : Area of y rea.) At 4: ak was on ine can be Hwy 82 3.5 s to West E ue and con file certain a C-141 re estigate and	ng east o of leak. water on 30 P.M. lateral lin repaired. 5 miles,tu 8#40 spil	f location at 3: ground was 22 truck on locati ne. was able to irn left on CR2 l is 25 yds east the best of my notifications a he NMOCD m ate contaminat does not reliev	P.M. found wa 2feet long X 21 ion, went to em isolate lateral, 221 gol.4 miles t of location in whether the set of	feet wid ptying ti to get fie to dirt r pasture, : d unders rective a l Report threat to of respon	ng out of nor be by 2in dee nhorn to see eld back goir oad on right, at the tinhor tand that pur ctions for re ground wate nsibility for	p. (picture if leak wa ng. Picked turn right ns. rsuant to N leases whi lieve the o er, surface compliance	At 3:15 P.M. ca s make the spill s on lateral line of up about 7 barrell go .5 mile,turn rig MOCD rules and ch may endanger perator of liability water, human hea e with any other		
Describe Cause looking for lea for a truck to p Describe Area looking bigger trunk line. Afte water off of gr Directions to s go .6 mile turn I hereby certify regulations all public health o should their op or the environr federal, state, o	e of Proble k on trunk bickup wat than area er empying ound. Wil- ite: From b left, go .5 y that the i operators or the envin berations h ment. In a bor local law	em and Remet line,upon dri er.Notified Ri and Cleanup / actually was f g tinhorn, deta l have to do o Loco Hills N. i mile turn right information gi are required to ronment. The ave failed to a ddition, NMC ws and/or regu	dial Ac iving o ick Ric Action to due ermine ne call M. go ht, go iven ab o repor	Taken.* rain at before l east on 2.0 mile	xen.*: At 2 #40 looki 3:30 P.M. : Area of y rea.) At 4: ak was on ine can be Hwy 82 3.5 s to West E ue and con file certain a C-141 re estigate and	ng east o of leak. water on 30 P.M. lateral lin repaired. 5 miles,tu 8#40 spil	f location at 3: ground was 22 truck on locati ne. was able to irn left on CR2 l is 25 yds east the best of my notifications a he NMOCD m ate contaminat does not reliev	P.M. found wa 2feet long X 21 ion, went to em isolate lateral, 221 gol.4 miles t of location in whether the as "Fina ion that pose a we the operator OIL CO District Super	feet wid ptying ti to get fie to dirt r pasture, : d unders rective a l Report threat to of respon	ng out of nor be by 2in dee nhorn to see eld back goir oad on right, at the tinhor tand that pur ctions for re ground wate nsibility for	p. (picture if leak wa ng. Picked turn right ns. rsuant to N leases whi lieve the o er, surface compliance	At 3:15 P.M. ca s make the spill s on lateral line of up about 7 barrell go .5 mile,turn rig MOCD rules and ch may endanger perator of liability water, human hea e with any other		
Describe Cause looking for lea for a truck to p Describe Area looking bigger trunk line. Afte water off of gr Directions to s go .6 mile turn I hereby certify regulations all public health o should their op or the environr federal, state, o Signature:	e of Proble k on trunk bickup wat Affected a than area er empying ound. Wil ite: From o left, go .5 y that the i operators or the envin perators h ment. In a pr local law Brian Wa	em and Remet line,upon dri er.Notified Ri and Cleanup / actually was f g tinhorn, deta l have to do o Loco Hills N. i mile turn right information gi are required to ronment. The lave failed to a ddition, NMC ws and/or regu	dial Action ick Ric Action to due ermine ne call M. go ht, go accep adequa DCD ac	Taken.* rain at before l east on 2.0 mile	xen.*: At 2 #40 looki 3:30 P.M. : Area of y rea.) At 4: ak was on ine can be Hwy 82 3.5 s to West E ue and con file certain a C-141 re estigate and	ng east o of leak. water on 30 P.M. lateral lin repaired. 5 miles,tu 8#40 spil	f location at 3: ground was 22 truck on locati ne. was able to irm left on CR2 l is 25 yds east the best of my notifications a he NMOCD m ate contaminat does not reliev Approved by Approval Da Conditions o	P.M. found wa 2feet long X 21 ion, went to em isolate lateral, 221 gol 4 miles t of location in whether the operator OIL CO District Super te: $7/29/$	feet wid ptying ti to get fie to dirt r pasture, i d unders rective a l Report threat to of respon NSER visor:	e by 2in dee nhorn to see eld back goir oad on right, at the tinhor tand that pun ctions for re ground wate nsibility for VATION	p. (picture if leak wa ng. Picked turn right ns. rsuant to N leases whi lieve the o er, surface compliance	At 3:15 P.M. ca s make the spill s on lateral line of up about 7 barrell go .5 mile,turn rig MOCD rules and ch may endanger perator of liability water, human hea e with any other <u>ION</u>		
Describe Cause looking for lea for a truck to p Describe Area looking bigger trunk line. Afte water off of gr Directions to s go .6 mile turn I hereby certify regulations all public health o should their op or the environr federal, state, o Signature: Printed Name: Title: Construct	e of Proble k on trunk bickup wat Affected a than area er empying ound. Wil ite: From o left, go .5 y that the i operators or the envin perators h ment. In a pr local law Brian Wa	em and Remet line,upon dri er.Notified Ri and Cleanup / actually was f g tinhorn, deta l have to do o Loco Hills N. i mile turn right information gi are required to ronment. The lave failed to a ddition, NMC ws and/or regu	dial Action ick Ric Action to due ermine ne call M. go ht, go accep adequa DCD ac	Taken.* rain at before l east on 2.0 mile	xen.*: At 2 #40 looki 3:30 P.M. : Area of y rea.) At 4: ak was on ine can be Hwy 82 3.5 s to West E ue and con file certain a C-141 re estigate and	ng east o of leak. water on 30 P.M. lateral lin repaired. 5 miles,tu 8#40 spil mplete to n release to renediate 1 remodiate 1 remodiate 1 report	f location at 3: ground was 22 truck on locati ne. was able to irn left on CR2 l is 25 yds east the best of my notifications a he NMOCD m ate contaminat does not reliev Approved by Approval Da Conditions o Remediati	P.M. found wa 2feet long X 21 ion, went to em isolate lateral, 221 gol 4 miles t of location in whether the operator OIL CO District Super ite: $7/29/$	feet wid ptying ti to get fie to dirt r pasture, : d unders rective a l Report threat to of respon <u>NSER</u> visor:	ng out of nor le by 2in dee nhorn to see eld back goir oad on right, at the tinhor tand that pur ctions for re ground wate nsibility for VATION Expiration &	p. (picture if leak wa ng. Picked turn right ns. rsuant to N leases whi lieve the o er, surface compliance	At 3:15 P.M. ca s make the spill s on lateral line of up about 7 barrell go .5 mile,turn rig MOCD rules and ch may endanger perator of liability water, human hea e with any other <u>ION</u>		

r

 Date: 07/21/2014
 Pho

 * Attach Additional Sheets If Necessary
 Phone: 806-367-0645

Bratcher, Mike, EMNRD

From:	McCracken, Theresa <tmccracken@linnenergy.com></tmccracken@linnenergy.com>
Sent:	Monday, July 21, 2014 4:37 PM
То:	jlrobertson@blm.gov; Bratcher, Mike, EMNRD
Cc:	Callahan, Terry; Moreno, Laura; Butters, Thomas; Gonzales, EL; Wall, Fred; Hickert, Aaron;
	hconder@rice-ecs.com; lweinheimer@rice-ecs.com; jkamplain@rice-ecs.com
Subject:	Linn- H.E. West B #40 7-19-14
Attachments:	H.E. West B # 40 7-19-14.pdf

Please find attached the initial C-141 for the above referenced location.

Thank you,



NASDAQ:LINE NASDAQ:LINCO

Theresa McCracken

Field Administrator LINN Energy, LLC 2130 W Bender Hobbs. NM 88240 T: 575-738-1739 / F: 575-738-1740 tmccracken@linnenergy.com

This electronic message, together with any attachments, contains information from LINN Energy that may be confidential and intended solely for the use of the addressee only. If you are not the intended recipient, please note that any disclosure, dissemination, distribution or copying of this message, or any attachment, is strictly prohibited. Also, please notify the original sender by return e-mail and delete the message, along with any attachments, from your computer. Finally, the recipient should check this email and any attachments for the presence of viruses. The organization accepts no liability for any damage caused by any virus transmitted by this email.

1