

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB 14241049543

Name of Company: COG Operating LLC <i>229137</i>		Contact: Robert McNeill	<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Address: 600 West Illinois Avenue, Midland TX 79701		Telephone No. 432-230-0077		
Facility Name: Hambone Fee Com #1		Facility Type: Battery		

Surface Owner: Fee	Mineral Owner:	API No. 30-015-38980
--------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter M	Section 5	Township 26S	Range 29E	Feet from the 660'	North/South Line South	Feet from the 330'	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude N32°03.960 Longitude W104°00.830

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: Oil: 5 bbls ; PW: 33 bbls	Volume Recovered: Oil: 4 bbls ; PW: 25 bbls
Source of Release: Fiberglass Tank	Date and Hour of Occurrence: 8-25-2014 6:30 pm	Date and Hour of Discovery: 8-25-2014 8:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION

If a Watercourse was Impacted, Describe Fully.*

ARTESIA DISTRICT
SEP 02 2014

RECEIVED

Describe Cause of Problem and Remedial Action Taken.*
The release was caused by a newly set fiberglass water tank. As the water tank settled a crack formed causing the leak. A vacuum truck was dispatched to remove all standing fluids and a new tank set.

Describe Area Affected and Cleanup Action Taken.*
The release occurred within the lined bermed facility. Gravel was excavated and replaced. All recovered fluids were disposed of at an NMOCD approved facility.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Senior Environmental Coordinator	Approval Date: <i>9/3/14</i>	Expiration Date: <i>NIA</i>
E-mail Address: atrujillo@concho.com	Conditions of Approval: <i>Final</i> -	Attached <input type="checkbox"/>
Date: August 29, 2014	Phone: 575-748-6940	

* Attach Additional Sheets If Necessary

2RP-2468