

**NM OIL CONSERVATION**

ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

SEP 04 2014

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.  
**RECEIVED**

**Release Notification and Corrective Action**

*NA1424733253*

**OPERATOR**  Initial Report  Final Report

Name of Company – Devon Energy	<i>0137</i>	Contact – Trae Warcup
Address – 4134 Seven Rivers Highway		Telephone No. – (575) 748-3371
Facility Name – Arcturus 18 FED COM 8H		Facility Type – Oil/Gas Well Pad (Drilling)
Surface Owner - Federal	Mineral Owner - Federal	API No. - 3001542033

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	17	19S	31E	300	South	312	West	Eddy

Latitude 32° 39' 14.3" N Longitude 103° 53' 56.438" W

**NATURE OF RELEASE**

Type of Release – Drilling Fluid	Volume of Release – 8 bbls.	Volume Recovered – 6 bbls.
Source of Release – Solids Control Bin	Date and Hour of Occurrence – 082614, 7:00 pm	Date and Hour of Discovery - 082614, 7:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.*		
Solids control bin overflowed due to lack of communication of shutting the transfer pump off before the bin overflowed. There was discussion with all crews to be aware of communication and to watch the bin levels and turn the transfer pump off so that it does not run over the bin.		
Describe Area Affected and Cleanup Action Taken.*		
Area was approximately 2050 sq. ft. and clean was done by a vacuum truck.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Trae Warcup</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Trae Warcup	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: EHS Professional Drilling	Approval Date:	Expiration Date:
E-mail Address: <a href="mailto:trae.warcup@dmn.com">trae.warcup@dmn.com</a>	Conditions of Approval: Remediation per OCD Rule & Guidelines.	
Date: 09/03/2014 Phone: 575-628-2846	Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

**SUBMIT REMEDIATION PROPOSAL NO LATER THAN:** \_\_\_\_\_

*2RP-2472*