State of New Mexico **Energy Minerals and Natural Resources**

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT Form C-141 Revised August 8, 2011

AN 06 2015 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

NABIE	1200	7 22	Release Notification and Corrective Action										
NAB1501328737						OPERATOR Initial Repo						Final Report	
Name of Co	mpany: B	OPCO, L.P.	0737		Contact: Tony Savoie								
		oad, N.M. 88220 1ka PC 33 Fed#1		Telephone No. 575-887-7329 Facility Type: Exploration and Production									
			100011 (2										
Surface Ow	ner: Feder	wner:	: Federal API No. 30-015-36636										
						N OF REI	· · · · · · · · · · · · · · · · · · ·			r	_	· 	
			Range 30E	Feet from the 350	North/ Sou	South Line	Feet from the 350	East/West Line East		County Eddy	- ,		
Latitude_N 32.168137_Longitude_W 103.878424													
NATURE OF RELEASE													
Type of Relea		Volume of Release: 40 bbls. Volume Recovered: 20 bbls.											
Source of Rel	ease: 1" val		Date and Hour of Occurrence:Date and Hour of Discovery1/3/15 time unknown1/3/15 at 12:21 p.m.					overy:					
Was Immedia	te Notice G	quired	If YES, To Whom? NMOCD emergency #104 and the BLM										
By Whom? T Was a Watero		Date and Hour: 1/3/15 at 3:24 p.m. If YES, Volume Impacting the Watercourse.											
was a watere	Jourse read	in TES, voldine impacting the watercourse.											
If a Watercourse was Impacted, Describe Fully.*													
Describe Cause of Problem and Remedial Action Taken.*													
A 1" valve connected to the lact unit- truck load line header broke, the valve was replaced.													
Describe Area Affected and Cleanup Action Taken.* The spill impacted approximately 10,890 sq.ft. of caliche tank battery pad. A vacuum truck was dispatched to the site the same day but the oil had congealed to the point the vacuum truck could not pick up the fluid. The ground was frozen and covered with ice and snow. A temporary fence was built around the spill area. The next day a vacuum truck and a crew continued working on fluid recovery, a total of 40 bbls of melted snow and oil was recovered, the remainder of the oil soaked into the ground. The spill area was left as is pending final remediation. The spill area will be cleaned up in accordance to the NMOCD and BLM remediation guidelines.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
	· 		OIL CONSERVATION DIVISION										
Signature:	(ong			Signed By	A.	le Kra	a da seta						
Printed Name:		A	Approved by Environmental Specialist:										
			···· 0····	-1:			1/12/14	-		NIL			
Title: Waste M	anagement	and Remediat	ion Speci	alist	A	pproval Date	1/2/10		xpiration D	ate: 14/7/			
E-mail Address: tasavoie@basspet.com Conditions of Approval: Attached													
Remediation per O.C.D. Rules & Guidelines Date: 1/6/15 Phone: 432-556-8730 SUBMIT REMEDIATION PROPOSAL NO													
Attach Additional Sheets If Necessary LATER THAN:													
				•						•	, 1 ,		