NM OIL CONSERVATION

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

* Attach Additional Sheets If Necessary

State of New Mexico

ARTESIA DISTRICT

Form C-141 Revised August 8, 2011

ZRP-2981

Energy Minerals and Natural Resources APR 2 9 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr.

RECEIVED

Santa Fe NM 87505

Saina 1 C, NVI 67303												
Release Notification and Corrective Action												
NAB 15 12 437681						OPERATOR			Initial	Report	Final Report	
						Contact: Bradley Blevins						
							Telephone No. 575-887-7329					
Facility Name: JRU #36							Facility Type: Exploration and Production					
Surface Owner: Federal Mineral Owner:						Federal API No. 30-015-27686					-27686	
LOCATION OF RELEASE												
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County											County	
1 1 - 1 - 1						North	1860		East .	Eddy		
Latitude: N 32.336152° Longitude: W 103.831835°												
NATURE OF RELEASE												
Type of Release: oil							Volume of Release: 20 bbls Volume Recovered: 11 bbls					
Source of Release: An air eliminator failure on the circulating pump.							Date and Hour of Occurrence:			Date and Hour of Discovery:		
The air eliminator broke off at the valve due to vibration of the pump.						4/23/15 @	4/23/15 @ 8:24 am			4/23/15 @ 8:24 am		
Was Immediate Notice Given?							If YES, To Whom?					
✓ Yes ☐ No ☐ Not Required							Mike Bratcher, OCD; Jim Amos, BLM via email					
By Whom? Bradley Blevins						Date and Hour: 4/24/15 @ 2:55 pm						
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse: Not Applicable						
☐ Yes ☒ No							able					
If a Watercou	rse was Imp	acted, Descri	be Fully.*	Not Applicable			,					
The state of the s												
Describe Cause of Problem and Remedial Action Taken.*												
An air elimina	ator failure o	n the circulat	ling pump	. The air eliminat	tor brol	ce off at the va	lve due to vibration	on of the	e pump.			
	400 1	1.01										
Describe Area					ron Va	anne tenak ea	navered 11 bbls o	e ania -	The area w	ill he rame	diated in accordance	
The release impacted approximately 2,000 sq. ft. of containment area. Vacuum truck recovered 11 bbls of fluid. The area will be remediated in accordance with the NMOCD and BLM remediation guidelines.												
							knowledge and u					
							d perform correct					
							arked as "Final Re					
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other												
federal, state,				ance of a C-1471	cport d	ocs not reneve	the operator of the	Саронан	other tor co	mphanec	with any other	
					T		OIL CONS	SERV	ATION	DIVISI	914	
Signature: Ocally												
Printed Name: Bradley Blevins							Approved by Environmental Specialist:					
Title: Assistant Remediation Foreman A							Approval Date: 5415 Expiration Date:					
E-mail Addres	s: bblevins@	basspet.com	l			Conditions of	Approval:			 		
							per O.C.D. F	Rulas	& Guide	Attached	I []	
Date: 7-2	7-15		Phone:	132-214-3704			HEDIATION F					
HOOD Addition	nal bhaat-	It blooges	-					L		~ _		

LATER THAN: