

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB 1515451992

OPERATOR Initial Report Final Report

Name of Company Devon Energy Production <i>6137</i>	Contact Dan Suniga
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575.390.5850
Facility Name Black Jack 1 Fed 2 Battery	Facility Type Oil

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-31864
------------------------------	------------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter p	Section 1	Township 24S	Range 30E	Feet from the 660	North/South Line FSL	Feet from the 660	East/West Line FEL	County EDDY
------------------	--------------	-----------------	--------------	----------------------	-------------------------	----------------------	-----------------------	----------------

Latitude: 32.14425 **Longitude:** 103.49554

NATURE OF RELEASE

Type of Release Spill 14 BBL oil & 1 BBL produced water	Volume of Release 15 BBL	Volume Recovered 10
Source of Release The sight glass on production separator failed	Date and Hour of Occurrence 5/10/15 6:30 am	Date and Hour of Discovery 5/10/15 6:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM Jeff Robertson OCD left message	NM OIL CONSERVATION ARTESIA DISTRICT
By Whom? Leonard Aguilar	Date and Hour 5/10/15 7:00 am	JUN 8 2015
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	RECEIVED

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Black Jack Fed 2 Battery 5.10.15 at 6:45 am - The sight glass on production separator failed causing produced fluid to escape on to ground. Lease operator closed the 1/2 inch valve from vessel to sight glass fluid cock on the top and bottom, this stopped the loss of fluid.

Describe Area Affected and Cleanup Action Taken.*
14 BBL of oil and 1 BBL of produced water spilled on pad. A light mist went into the pasture on the east side of pad 10' X 15' area. 10 BBL of oil was recovered. An environmental group will be called out for cleanup.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jeanette Barron</i>	OIL CONSERVATION DIVISION	
Printed Name: Jeanette Barron	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Admin Support	Approval Date: <i>6/18/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: Jeanette.barron@dvn.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 5/12/15 Phone: 575.748.1813	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: *6/19/15* *2RP-3039*