

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Nagooltee Peak 5 Com #2	Facility Type	Production
Surface Owner	Mineral Owner	API No. 30-015-28074	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	5	22S	24E	1562	N	1202	W	Eddy County, NM

Latitude N 32.41777° Longitude W 104.51753°

**NATURE OF RELEASE**

Type of Release	Produced water	Volume of Release	10 bbls	Volume Recovered	0 bbls
Source of Release	Failure of 2 7/8" steel production line	Date and Hour of Occurrence	10/29/2012	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-OCD, Terry Gregston-BLM		
By Whom?	Christopher Jones	Date and Hour	11/7/2012 @ 6:59 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Failure of a 2 7/8" steel production line caused 10 bbls of produced water to spill onto the ground. 0 bbls of water were recovered.

Describe Area Affected and Cleanup Action Taken.\*

The area affected is approximately 200' x 40'. Failure of a 2 7/8" steel production line caused 10 bbls of produced water to spill onto the ground. 0 bbls of water were recovered. Remediation was completed in accordance with a remediation plan approved by Mike Bratcher of NMOCB via email on 04/08/2013 and by James Amos of BLM via email on 04/12/2013.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCB rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCB marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCB acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature:	OIL CONSERVATION DIVISION		
Printed Name: Christopher Jones	Approved by District Supervisor:		
Title: HES Specialist	Approval Date: 6/9/15	Expiration Date: N/A	
E-mail Address: Christopher.Jones@oxy.com	Conditions of Approval: Final	Attached <input type="checkbox"/>	
Date: 6-19-13	Phone: (575) 628-4121		

\* Attach Additional Sheets If Necessary

