

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

0AB1517455620

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Devon Energy Production	Contact	Rudy Zuniga
Address	6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No.	575-390-5435
Facility Name	Aquila 22 Fed Com 4H	Facility Type	Oil

Surface Owner	Federal	Mineral Owner	Federal	API No.	30-015-41159
---------------	---------	---------------	---------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	22	19S	31E	2030	FSL	225	FEL	Eddy

Latitude: 32.6442938790538

Longitude: -103.849275635804

NATURE OF RELEASE

Type of Release	Volume of Release	Volume Recovered
Spill	5.5bbl	2bbls
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
wellhead parted	June 16, 2015 9:33 AM	June 16, 2015 9:33 AM
Was Immediate Notice Given?	If YES, To Whom?	NM OIL CONSERVATION ARTESIA DISTRICT
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	Jim Amos, BLM Mike Bratcher, OCD	
By Whom?	Date and Hour	JUN 23 2015
Lynn Smith	Jim Amos, BLM June 16, 2015 10:28 AM Mike Bratcher, OCD June 16, 2015 10:32 AM	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse	RECEIVED
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

On June 16, 2015 9:33 AM at the Aquila 22 Fed Com 4H the well parted above the polish rod which caused the rods to then fall down thru the polish rod itself which in turn then caused a release on location of 5bbls oil and produce water mix on location and a .5bbl mist into pasture. Shut well in and a new valve and plug was installed.

Describe Area Affected and Cleanup Action Taken.*

The spill was located on the Southwest corner of location and into the pasture. A vac truck was able to recover 2bbls oil and produced water from location. The contaminated dirt will be removed and replaced with fresh dirt and the wellhead and pasture will be pressure washed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sheila Fisher

Printed Name: Sheila Fisher

Title: Field Admin Support

E-mail Address: Sheila.Fisher@dvn.com

Date: Phone: 575.748.1829

OIL CONSERVATION DIVISION

Approved by Environmental Specialist:

Approval Date: 6/23/15

Expiration Date: N/A

Conditions of Approval:

Remediation per O.C.D. Rules & Guidelines

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 7/24/15

* Attach Additional Sheets If Necessary

2RP-3045