Submit 1 Copy To Appropriate District Office		State of New Mexico			Form C-103			
<u>District I</u> – (575) 393-6161	Energy, Minerals a	Energy, Minerals and Natural Resources Revised Ju WELL API NO.		Revised July 18, 2013				
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	OIL CONSERVATION DIVISION				30-015-32821			
811 S. First St., Artesia, NM 88210					5. Indicate Type of Lease			
1000 Rio Brazos Rd., Aztec, NM 87410		IL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505  ID REPORTS ON WELLS DRILL OR TO DEEPEN OR PLUG BACK TO A OR PERMIT" (FORM C-101) FOR SUCH  II Other  RGY PRODUCTION COMPANY, LP.  ERIDAN AVENUE, OKC, OK 73102  Om the South line and 1780 fee Fownship 24S Range 29E evation (Show whether DR, RKB, RT, GR, etc. 3062' GR  Triate Box to Indicate Nature of Notice ION TO: SUE AND ABANDON REMEDIAL WOR GE PLANS COMMENCE DE CASING/CEMEN  OTHER:  Perations. (Clearly state all pertinent details, and E RULE 19.15.7.14 NMAC. For Multiple Compliance, until well can be evaluated.  LP respectfully requests to run an MIT on the r TA status on this well.  Ompliance, until well can be evaluated.  ACT (REW B) 2014  Ind Proposed Wellbore Schematics.  TITLE Regulatory Compliance.  TITLE Regulatory Compliance.			STATE S FEE			
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Samare	, INIVI O	7303	6. State C	oil & Gas Lease No.			
87505	CEC AND DEDODTE ON	IWELLO		7 Leggs	Name or Unit Agraement Name			
					Lease Name of Olit Agreement Name			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH								
1. Type of Well: Oil Well	Gas Well  Other			8. Well N	Jumber 4			
2. Name of Operator	9. OGRII	9. OGRID Number						
	Energy, Minerals and Natural Resources No. French D., Hobbs, MN 88240 nct. H. 1575 1984 123 No. French D., Hobbs, MN 88240 nct. H. 1575 1984 123 No. French D., Hobbs, MN 88240 nct. H. 1575 1984 123 No. H. 1575 1984 123							
	feet from the South	line and	l 1780 feet	t from the	West line			
	3062' GR							
12 Check	Annronriate Roy to Inc	licate N	ature of Notice	Report or	Other Data			
12. Check I	Appropriate box to fix	iicaic iv		•				
		_	l .					
<del></del>		=	ľ		<del></del>			
=					IS.[_] PANDA [_]			
<del>-</del>	MOLTH EL COMI E		OASING/OLIVILIA	1 300				
OTHER:	1. 1			1				
		1 1 1 1 1 1 1 2 1 1	o. Tor Multiple Cor	inpictions. 1	rituen wendore diagram of			
Nevan Energy Production (	omnany LP respectfully re	auests to	run an MIT on the re	eferenced we	all ner attached procedures			
			an an will on the re	erer erreed we	m per ununeu procedures.			
	•							
TA'ing well to bring well int	o OCD compliance, until w	ell can be	evaluated.					
	TA status may be gra	nted afte	ar a					
successful MIT test is performed.					NM OIL CONSERVATION			
TA'ing well to bring well into OCD compliance, until well can be evaluated.  TA status may be granted after a successful MIT test is performed.  Contact the OCD to schedule the test					ARTESIA DISTRICT			
			JUN 18 2015					
	INT DROW	ol.	10006					
	451 1100	911	12019		RECEIVED			
Attachad Procedures and (	Turrent and Proposed Walli	ara Saha	matics					
Attached. Trocedures and	Jurrent and Proposed Weni	Joi e Sche	matics.					
The makes a makife of the of the information	al	- 4- 41 1-		1 1 1: . 6				
Thereby certify that the information					•			
SIGNATURE / //	M DON TITL	E Reg	gulatory Compliance	e Associate	DATE06/12/2015			
	E-mail address: Rebe	cca.deal@	dvn.com	PHC	ONE: (405)228-8429			
For State Use Only	/				, <i>I</i>			
APPROVED BY: Dubano	Mas TITL	E_ <i>Co</i> n	plasmo o	DEG CÉS	2 DATE 6/19/15			
Conditions of Approval (if any):		_0,	v -		, , , , , , , , , , , , , , , , , , ,			

# DVN: H B 2 State 4

### API #30-015-32821

## SL: 860' FSL & 1,780 FWL Sec 2-T24S-R29E

Eddy County, NM 6/9/2015

WBS#

Purpose: Temporarily Abandon Wellbore

GLM: 3,062'

KBM: 3,080

KB:

18' AGL

Well spud – 7/27/2003

T.D. - 8,410'

Casing and Tubing Data:

Size	Wt. lb/ft	Grade	Interval	(80% S.F.) Collapse	(80% S.F.) Burst	Drift	Capacity (bbls/ft)
13-3/8"	48	H-40	0 – 542'	-	-	_	-
8-5/8"	32	J-55	0 – 3,100'	2,024	3,144	7.796	0.0609
5-1/2"	17/15.5	J-55	0 – 8,410'	3,232	3,848	4.767"	0.0236
2-7/8"	6.5	J-55	0 -8,149'	6,144	5,808	2.347"	0.0058

<sup>2-7/8&</sup>quot; x 5-1/2", 15.5# csg capacity: 0.01577 bbl/ft

5-1/2" csg - DV Tool @ 6,019'

TOC outside 5-1/2" csg @  $\sim 3,404$ ' (CBL confirmed 8/19/2003)

#### **Existing Production string (top down):**

249 Jt, 2-7/8", 6.5#, J-55 tbg

1, 2-7/8" tbg TAC (7,889')

8 jts, 2-7/8", 6.4#, J-55 tbg (253')

- 1, Blast Jt (3')
- 1, Seat Nipple (1.1')
- 1, 3-1/2" slotted jt (26')

Safety:

All personnel will wear hard hats, safety glasses with side shields, and steel toed boots while on location. Assess wellhead working height for safety. If needed, use work platform or man-lift for fall protection. Tailgate safety meetings are to be held each morning prior to beginning work and prior to change in operations.

### **H B 2 State 4 Recompletion**

Procedure:

- 1. Test and/or install and test anchors. MIRU WSU. Spot all necessary equipment. Record pressures on tbg and csg. Top kill tbg (if required) with 2% KCL
- 2. Install rod rams and TOOH w/ rods recording location and type of rod break. Fish remaining rods and pump.
- 3. ND wellhead. NU 5K BOPE with blind rams and 2-7/8" pipe rams. Test BOPE per Devon Guidelines
- 4. Release TAC (7,890') and TOOH w/ tbg. Record any wear and any paraffin/scale issues along with their location in the string.
- 5. Pick up 5-1/2" CIBP TIH to 7,955' (50' above top perf) and set CIBP. Sting out of CIBP and PU 1 jt, pressure test csg to 500 psi for 5 min to ensure CIBP is holding.

Note: Notify State representative and Devon Engineer prior to setting CIBP.

- 6. Rig up cement truck, break circulation and spot 30 sacks of Class "H" cement on top of CIBP. Pick up 10 stands, reverse circulate 1-1/2 times tubing volume. WOC
- 7. RIH and tag cement plug. Load and test casing to 500 psi for 10 min with chart recorder. Report back to State rep and Devon engineer with tag depth and pressure test.
- 8. Circulate/roll hole with corrosion inhibiter as per Baker's recommendation.
- 9. ND BOPE, NU wellhead, RDMO WSU



