

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

State of New Mexico
Energy Minerals and Natural Resources

JUL 14 2015

Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Release Notification and Corrective Action

NAB1519821410

OPERATOR

Initial Report Final Report

Name of Company Devon Energy Production <i>6137</i>	Contact Garry Michael
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575-513-4895
Facility Name Cotton Draw Unit 134 H	Facility Type Oil

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-38293
------------------------------	------------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	2	25S	31E	200	South	330	West	Eddy

Latitude: N 32°09'10.09"

Longitude: W 103°45'22.17"

NATURE OF RELEASE

Type of Release Spill Oil	Volume of Release 15 bbl	Volume Recovered 15 bbl
Source of Release Contractor was transferring oil and caused an overflow	Date and Hour of Occurrence 7.12.2015 @ 11:52 PM	Date and Hour of Discovery 7.12.2015 @ 11:52 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos BLM Mike Bratcher OCD	
By Whom? Lolo Martinez	Date and Hour 7.12.2015 2:49 AM 7.12.2015 2:55 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

On July 12, 2015 at 11:52 PM, TCS Trucking Driver was transferring oil from the Cotton Draw 89 SWD to the Cotton Draw Unit 134 H causing an overflow of 15 bbls of oil into containment. All 15 bbls were recovered, containment was checked for holes, none were found.

Describe Area Affected and Cleanup Action Taken.*

On July 12, 2015 as TCS Trucking employee was transferring oil from the Cotton Draw 89 SWD to the Cotton Draw Unit 134 H, there was an overflow of oil, this caused 15 bbls to spill into containment. All 15 bbls of oil were recovered immediately. Containment was checked for holes to make sure there was no leakage, none were found.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Corina Moya</i>	OIL CONSERVATION DIVISION	
Printed Name: Corina Moya	Signed By <i>Mike Bratcher</i>	
Title: Field Admin Support	Approved by Environmental Specialist:	Approval Date: <i>7/17/15</i> Expiration Date: <i>N/A</i>
E-mail Address: corina.moya@dvn.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: <i>7/14/2015</i> Phone: 575.746.5559		

* Attach Additional Sheets If Necessary

2RP-3121