rm 3160-5

IDJITED OTATES

RECEIVED

FORM APPROVED

(Scpt	tember 2001)	DEPARTMENT OF THE INTERIOR		NOV 0 9 2005		OMB No. 1004-0135 Expires January 31, 2004			
		BUREAU OF LAND	MANAGEMENT	600	MATERIA	5. Lease Se	erial No.		
SUNDRY NOTICES AND REPORTS ON WEL				WELLS	LS		NMNM112273		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.						6. If Indian, Allottee or Tribe Name			
	abandoned w	eii. Use rorm 3160-	S (APD) TOT SUCH	i proposais.	,				
							7. If Unit or CA/Agreement, Name and/or No.		
SUBMIT IN TRIPLICATE - Other instructions on reverse side									
1. Type of Well								_	
Oil Well Gas Well Other						8. Well Na			
2. Name of Operator							INSOSCOPY FEDERAL #1	<u>.</u>	
MARBOB ENERGY CORPORATION 3a Address 3b. Phone No. (include area code)						9. API Wel			
						30-015-33758 10. Field and Pool, or Exploratory Area			
PO BOX 227, ARTESIA, NM 88211-0227 (505) 748-3303 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)						BURTON FLAT; STRAWN, EAST			
4. LOCATION OF WELL (POOLUGE, Dec., 1., 1., 11., or but rey Description)						11. County or Parish, State			
						ii. county c	or rungil, butto		
	1095 FSL 430 FWL	., SEC. 7-T20S	-R30E, LOT	4	İ	EDDY	CO., NM		
		PPROPRIATE BOX(F NOTICE RE			-	
		The state of the s					COLLINE DILLI	-	
TYPE OF SUBMISSION TYPE OF ACTION								_	
		☐ Acidize	Deepen		Production (Start/I	Resume)	☐ Water Shut-Off		
	Notice of Intent	Alter Casing	☐ Fracture	e Treat	Reclamation		☐ Well Integrity		
\overline{\overline{\pi}}	Subsequent Report	Casing Repair	New Co	onstruction 🔯	Recomplete		Other		
•	Subsequent Report	Change Plans	Plug and		Temporarily Abar	ndon		-	
	Final Abandonment Notice	Convert to Injecti	on 🖾 Plug Ba	ick 🛄	Water Disposal		and the state of t	•	
	testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) RECOMPLETED TO THE STRAWN LIME AS FOLLOWS: 10/3/05 - SET CIBP + 35' CMT @ 11800'. 10/4/05 - PERF THE ATOKA SAND @ 11318'-11320' (12 SHOTS). 10/5/05 - ACDZ W/ 500 GAL CLAY SAFE H ACID. SWAB/FLOW TEST. 10/6/05 - SET CIBP + 35' CMT @ 11265'. 10/7/05 - PERF THE STRAWN LIME @ 10839'-11018' (18 SHOTS). 10/8/05 - ACDZ W/ 3500 GAL NEFE 15% HCL ACID. SWAB/FLOW TEST.								
	10/13/05- ACID FRAC @ 10839'-11018' W/ 200 TONS CO2, 1108 BBLS FLUID & 20000								
	GAL 15% NEFE ACID. AIR-38 BPM, AIP-3893#, MAX PRESS 7012#, ISIP 3893#.								
	10/20/05- SI FOR PRESSURE BUILD UP.								
	I hereby certify that the foregoin Names(Printed/Typed)	ng is true and correct		1					
		7000		Title DD					
	\ \QIANA J. BR	Acc 8		PR	ODUCTION A	NALYST			
	Signature J. M.	1 Dugo	لم	Date NO	VEMBER 8,	2005			
		THIS SI	E FOR FEDER	AL OR STATE	OFFICE USE				
			1						
	oved by			Title		Dat	te		
certif	litions of approval, if any, are a by that the applicant holds legal in would entitle the applicant to c	I or equitable title to thos	e rights in the subject	ct lease Office					

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.