Submit 3 Copies To Appropriate District Office			Form C-103
District I Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240			May 27, 2004 WELL API NO.
District II OIL CONSERVATION DIVISION		30-015-10820	
District III 1220 South St. Francis Dr.		5. Indicate Type of Lease STATE S FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505			B-1266
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			G-J West Coop Unit
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other			8. Well Number 22
2. Name of Operator		RECEIVED	9. OGRID Number
Mack Energy Corporation 3. Address of Operator		AUG 1 0 2005	013837 10. Pool name or Wildcat
· _ ·	0 Artesia, NM 88211-0960	UCU-ARTERIA	Grbg Jackson SR Q Grbg SA
4. Well Location			
Unit Letter N : 460 feet from the South line and 1980 feet from the West line			
Section 21	Township 17S 11. Elevation (Show whether	Range 29E	NMPM County Eddy
3550'GR			
Pit or Below-grade Tank Application or Closure			
			stance from nearest surface water
Pit Liner Thickness: mil			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WOR	RK ☐ ALTERING CASING ☐ ☐ RILLING OPNS.☐ P AND A
	MULTIPLE COMPL	CASING/CEMEN	
OTHER:		OTHER:	П
OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
of recompletion.			
7/21/05 Set 4-1/2" CIBP @ 2530', cap w/ 35' cmt. w/ bailer.			
7/22/05 Circ. hole w/ MLF. 7/22/05 Perf 4-holes @ 418', set pkr. @ 60', sqz. 40 sx. cmt., no tag.			
7/22/05 Sqz. 40 sx. cmt. @ 418'.			
7/25/05 Tag plug @ 300'. 7/25/05 Perf 4-holes @ 60', pump 25 sx. cmt. fron 60' to surf down 4-1/2 to surf out 8-5/8, leave 4-1/2 full of cmt.			
7/26/05 RDMO. Cut off wellhead & anchors, install dry hole marker, and clean location.			
			•
	:		
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-			
grade tank has been/will be constructed or closed according to NMOCD guidelines [], a general permit [] or an (attached) alternative OCD-approved plan [].			
SIGNATURE_	lun TITL	EAgent	DATE7/26/05
Type or print name Roger Mass	E-mail address:		Telephone No. 432-530-0907
For State Use Only	S address.		
APPROVED BY:	TITL	E	DATE MAR 0 8 2006
Conditions of Approval (if any):			55



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON Governor 9/A OK 10 Reloas 3/6/06

Joanna Prukop
Cabinet Secretary
Acting Director
Oil Conservation Division

PECEIVED

29 August 2005

Mack Energy Corp. P. O. Box 960

Artesia, New Mexico 88221-0960

RECEIVED

MAR 0 1 2006

CON-MATESIA

SEP 0 1 2005

Form C-103 Report of Plugging for your GJ West Coop Unit #22 N-21-17-29 API 30-015-10820 Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- 1. All pits have been closed as per Rule 50.
- X 2. Rat hole and cellar have been filled and leveled.
- 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- 5. The dead men and tie downs have been cut and removed.
- 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
- All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

Van Barton Field Rep. II

Production Clerk 2/28/2006

Leny W. Shewll