

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NOV 12 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1531740296

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: LPC Crude Oil Marketing, LLC 4137	Contact: Benjamin Aucoin
Address: 2501 Cedar Springs Rd. #100, Dallas, TX 75201	Telephone No. 225-313-1338
Facility Name: (Devon) Cotton Draw 172H	Facility Type:

Surface Owner FED	Mineral Owner FED	API No. 30-015-42426
-------------------	-------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section 01	Township T25S	Range R31E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------	------------	---------------	------------	---------------	------------------	---------------	----------------	-------------

Latitude N 32° 09' 9.41" Longitude W 103° 43' 38.37"

32-152614

NATURE OF RELEASE 103-727325

Type of Release: Crude Oil	Volume of Release: 67 bbl	Volume Recovered: 44 bbl
Source of Release: Transport Truck	Date and Hour of Occurrence 11/11/15 - 10:30 PM	Date and Hour of Discovery 11/11/15 - 10:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Randy Dade (via voicemail)	
By Whom? Benjamin Aucoin	Date and Hour: 11/12/15 11:00 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.

N/A



Describe Cause of Problem and Remedial Action Taken.*

Crude oil overflowed from a tank truck while driver was loading the truck from the LACT unit. The LACT unit was turned off upon discovery of the spill preventing more oil from being spilled. The root cause is being investigated.

Describe Area Affected and Cleanup Action Taken.*

67 barrels of crude oil were spilled onto the site, and all spilled material remained on the site. 44 barrels were recovered via vacuum truck. The impacted area has been barricaded to prevent traffic over the area. LPC is working with the pad owner to coordinate remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCID rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCID marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCID acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Benjamin Aucoin	Signed By  Approved by Environmental Specialist:	
Title: Lead Environmental Field Specialist	Approval Date: 11/13/15	Expiration Date: N/A
E-mail Address: Benjamin.Aucoin@enlink.com	Conditions of Approval: Attached <input type="checkbox"/>	
Date: 11/12/15 Phone: 225-313-1338	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 12/17/15	

* Attach Additional Sheets If Necessary

2RP-3390