

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received 7/17/15  
NMOCD Artesia

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1535129942		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company Devon Energy Production		Contact Daniel Suniga			
Address 6488 Seven Rivers Hwy Artesia, NM 88220		Telephone No. 575-390-5850			
Facility Name Todd 15 G Fed 7		Facility Type Oil			
Surface Owner Federal		Mineral Owner Federal		API No. 30-015-32659	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	15	23S	31E	1980	North	1980	East	Eddy

Latitude: N 32°18'22.8"

Longitude: W 103°45'48.6"

NATURE OF RELEASE

Type of Release Spill Produced Water and Oil	Volume of Release 150 bbls	Volume Recovered 150 bbls
Source of Release Lightning caused fire on tank	Date and Hour of Occurrence 7.15.15 @ 10:30 PM	Date and Hour of Discovery 7.15.2015 @ 10:30PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos @ BLM Mike Bratcher @ NMOCD	
By Whom? Jason Anderson	Date and Hour 7.16.2015 @ 1:23 AM 7.16.2015 @ 1:23 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

On July 15, 2015 at 10:30 PM severe lightning struck the tank at the Todd 15 G Fed 7 causing the battery to catch on fire. This caused the tank to explode and 150 bbl of produced water and oil was released into containment. All the fluid stayed in containment, but this was an earth containment and has holes in it. All 150 bbls of produced water and oil were recovered by PSI after it cooled down.

Describe Area Affected and Cleanup Action Taken.\*

The 150 bbls of produced water and oil that was leaked into the containment were all recovered. This is an earth containment and has holes. Day crew will assess for further cleanup.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Corina Moya	OIL CONSERVATION DIVISION	
Printed Name: Corina Moya	Approved by Environmental Specialist: 	
Title: Field Admin Support	Approval Date: 12/17/15	Expiration Date: N/A
E-mail Address: corina.moya@dmn.com	Conditions of Approval: C.D. Rules & Guidelines	
Date: 7.17.2015 Phone: 575.746.5559	SUBMIT REMEDIATION PROPOSAL NO. 11171116	

Remediation per O.C.D. Rules & Guidelines  
Attached ☐  
LATER THAN: 11/17/16

\* Attach Additional Sheets If Necessary

2RP-3454