Submit 3 Copies To Appropriate District Office	State of 1	New Mexic	0		Form C-103
<u>District</u> I	Energy, Minerals a	and Natural	Resources	WELLADIA	Revised March 25, 1999
25 N. French Dr., Hobbs, NM 87240 strict II				WELL API N	NO. 30-015-28906
811 South First, Artesia, NM 87210	OIL CONSERVATION DIVISION			5. Indicate T	
District III 1000 Rio Brazos Rd., Aztec, NM 87410	2040 South Pacheco				E X FEE
District IV		, NM 8750			l & Gas Lease No.
2040 South Facheco, Santa Fe, NW 87505				K-5017	
SUNDRY NOTICE (DO NOT USE THIS FORM FOR PROPOSAL DIFFERENT RESERVOIR. USE "APPLICAT PROPOSALS.) 1. Type of Well: Oil Well X Gas Well	ES AND REPORTS C LS TO DRILL OR TO DEI TION FOR PERMIT" (FOR	ON WELLS EPEN OR PLU M C-101) FO	UG.BACK-TO A RISUĈHO 11	7. Lease Nar Todd "2" St	me or Unit Agreement Name tate
Name of Operator Ricks Explora	tion Inc	17944	JUL 2003	8. Well No.	3
3. Address of Operator 550 W. Texas Ave., Suite 1300 ARTESIA 9. Pool name or Wildcat Ingle Wells; Delaware					
4. Well Location					
4. Well Location Unit Letter P : 660 feet from the South South 660 feet from the East line					
Section 2	Township 2	4 R	ange 31	NMPM	County Eddy
	10. Elevation (Show 3501' gr	whether DR	, RKB, RT, GR, etc.)		
11. Check Ap	propriate Box to Ir	dicate Na	ature of Notice.	Report or Oth	her Data
NOTICE OF INT	ENTION TO:				REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDO	N 🔲	REMEDIAL WOR	RK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DR	ILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST A	ND	ADAMOONMENT
OTHER: Add Delaware Sand Pay		X	OTHER:		
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach diagram of proposed completion or recompletion. Ricks Exploration, respectfully requests your approval, as follows:					
Proposed Perfs: 7220 - 7246'					
 POOH w/rods and pump. NU BOP. Pull tbg. OOH. Run BP & set @ 7300'. Circ. hole w/2% KCl and test csg to 3000#. Spot 500 gals 10% acetic acid on btm. POOH w/tbg. MIRU ELU. Perforate w/4" csg. gun 2 spf: 7220 - 7246'. Frac as designed. Clean out sand and return to production. Place SN @ 7150'. Run 1 1/2" pump with 10 of largest diameter rods in string on bottom. Finish out w/standard taper with existing rods. 					

I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNATURE DALMA	(offman	TITLE_	Regulatory Analyst		DATE 07/09/2003
Type or print name Brenda Coffman					Telephone No. (432) 685-
APPROVED BY Conditions of approval, if any:	w. Bum	TITLE_	Ristricts	igewison	DATE JUL 1120