Form 3160-5 (August 2007)

UNITED STATES OCD DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENTSTRICT SUNDRY NOTICES AND REPORTS ON WELLS 16 UNITED STATES

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

5. Lease Serial No.

NMNM33437

Do not use this form for proposals to drill of abandoned well. Use Form 3160-3 (APD) for	o. 11 mulan, Anon	7. If Unit of CA/Agreement, Name and/or No.				
SUBMIT IN TRIPLICATE - Other instructio	7. If Unit of CA/A					
1. Type of Well						
☑ Oil Well ☐ Gas Well ☐ Other	8. Well Name and	8. Well Name and No. PMS 8 FEDERAL # 8				
2. Name of Operator CHEVRON U.S.A. INC. monty.mo	ccarver@cjes.com	9. API Well No.	30-015-26957			
	e No. (include area code)	10. Field and Pool	10. Field and Pool or Exploratory Area			
	-7104 LEE ROAK		SHUGART NORTH			
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) SEC 8, T18S R31E MER NMP 1980 FNL 510 FEL		11. Country or Par	ish, State EDDY CO. NM.			
	DIDIGATE NATION OF	NOTION PERCENCE				
12. CHECK THE APPROPRIATE BOX(ES) TO	INDICATE NATURE OF	NOTICE, REPORT OR O	THER DATA			
TYPE OF SUBMISSION	TYPE C	F ACTION				
Notice of Intent	Deepen	Production (Start/Resume	·			
	Fracture Treat	Reclamation	Well Integrity			
Subsequent Report	New Construction	Recomplete	Other			
	Plug and Abandon Plug Back	☐ Temporarily Abandon ☐ Water Disposal				
Attach the Bond under which the work will be performed or provide the B following completion of the involved operations. If the operation results it testing has been completed. Final Abandonment Notices must be filed on determined that the site is ready for final inspection.) 13 3/8" 54.5# @ 422' TOC SURF', 8 5/8" 32# @ 2,162' TOC SURF, 5 1 P & A PROCEDURE; NOTIFY BLM 48 HOURS BEFORE MOVE IN. (1) ON OR ABOUT NOVEMBER 23, 2015 MOVE IN RIG & EQUIPMENT. PECH 5 22 Cont + Con 52 50 - \$ / 00' WOC MIX & SPOT 65 SX CL "C" CEMENT FROM 4,500'-4,000', WOC & TACKET 5 22 MIX & SPOT 175 SX CL "C" CEMENT FROM 3,650'-2,700', WOC & TACKET 5 22 PERF & CIR 115 SX CL "C" CEMENT FROM 2,225'-1,850', WOC & TACKET 5 22 PERF & CIR 265 SX CL "C" CEMENT FROM 2,225'-1,850', WOC & TACKET 5 22 PERF & CIR 265 SX CL "C" CEMENT FROM 650'-SURFACE ON BOT CUT OFF WELLHEAD 3' BGL, INSTALL REQUIRED DRY HOLE MAR BOND COVERAGE: 0329	in a multiple completion or ly after all requirements, inc 1/2" 17# @ 8,620' TOC 2, 575) 234-5909 CIBP @ 7,900' W/ 35 SX TAG G (DELAWARE, SAN AN AG (GRAYBURG, PENR AG (INT. SHOE, YATES	recompletion in a new intercluding reclamation, have belowing reclamation, have belowing reclamation, have belowed to the second of the second	rval, a Form 3160-4 must be filed once been completed and the operator has 482'. 600', WOC / TAG / TEST. CIR GEL S, 7 RIVERS) ATION. ATION.			
LPC COAs AHached 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)	RECLAMATION PR ATTACHE	D COI	NDITIONS OF APPROVA			
Monty L. McCarver	Title Agent for Ch	evron USA	Accepted for record			
Signature	Date 11/11/2015		LD 2/15/2016			
THIS SPACE FOR FE	EDERAL OR STATE	OFFICE USE				
Conditions of approval, if any, are attached. Approval of this notice does not warrar that the applicant holds legal or equitable title to those rights in the subject lease whin title the applicant to conduct operations thereon. Fitle 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for a section 1001 and 1111 and 11111 and 11111 and 11111 and 11111 are section 1001 and 11111 and 11111 and 11111 are section 1001 and 11111 and 11111 are section 1001 and 11111 and 11111 are section 1001 are section 1001 and 11111 are section 1001 and 11111 are section 1001 and 11111 are section 1001 are s	ch would Office	Ilfully to make to any depart	Date 1/29/16			

fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

CURRENT

Chevron U.S.A. Inc. Wellbore Diagram: PMS 8 FED 8



[Lease] OEU EUNICE FMT [Well No.] PMS 8 FEDERAL 8 8 [Field] SHUGART NORTH
[Location] 1980FNL510FEL [Sec.] N/A [Blk] _____ [Survey] N/A
[County] Eddy [St.] New Mexico [Refno] QU3027 [API] 3001526957 [Cost Center] UCT442400
[Section] 8 [Township] 18 S [Range] 31 E
[Current Status] ACTIVE [Dead Man Anchors Test Date] NONE
[Directions] _____

1.500 (1 1/2 in.) Spray Metal x 30 1.000 (1 in.) (Unknown) x 2 Rod Sub @(44-46) 1.000 (1 in.) (Unknown) x 4 Rod Sub @(46-50) 1.000 (1 in.) (Unknown) x 8 Rod Sub @(50-58) K-55 13.375 OD/ 54.50# Unknown Thread 12.615 ID 12.459 Drift @(14-421) Wellbore Hole OD-17.5000 @(14-422) Cement (behind Casing) 500sx @(14-422) Casing Shoe (13.375 OD Casing) @(421-422) 60 - 1.000 (1 in.) (Unknown) x 25 Rod 58 @(58-1558) K-40 8.625 OD/ 32.00# 7.921 ID 7.796 Drift @(14-2161) Casing Shoe (8.625 OD Casing) @(2161-2162) Cement (behind Casing) 1300sx @(14-2162) Wellbore Hole OD-12.2500 @(422-2162) 84 - 0.875 (7/8 in.) (Unknown) x 25 Rod @(1558-3658) 4242 J-55 2.875 OD/ 6.50# T&C External Upset 2.441 ID 2.347 Drift @(14-7913) Tubing Anchor/Catcher 2.875 @(7913-7916) 176 - 0.750 (3/4 in.) (Unknown) x 25 Rod @(3658-8058) 16 - 1,000 (1 in.) (Unknown) x 25 Rod @(8058-8458) J-55 2.875 OD/ 6.50# T&C External Upset 2.441 ID 2.347 Drift @(7916-8474) Seat Nipple - Standard (2.875) Cup Type @(8474) Rod Pump (Insert) (NON-SERIALIZED) - 25-150-R H BC -0-0 (Bore = 1.50) @(8458) Perforated Tubing Sub 2.875 @(8475-8479) Perforations - Bone Spring - 4spf @(7930-8482) Perforated Tubing Sub 2.875 @(8479-8485) Perforated Tubing Sub 2.875 @(8485-8489) Mud Anchor 2.875 @(8489-8519) Bull Plug (Unknown Type) - 2.875 @(8519-8520) K-55 5.500 OD/ 17.00# Unknown Thread 4.892 ID 4.767 Drift @(14-8619) Casing Shoe (5.500 OD Casing) @(8619-8620) Wellbore Hole OD- 7.8750 @(2162-8622) Cement (behind Casing) 1450sx @(2158-8622) Plug - Cement @(8560-8622)

P+A: Chevron U.S.A. Inc. Wellbore Diagram: PMS 8 FED 8



[Lease] OEU EUNICE FMT [Well No.] PMS 8 FEDERAL 8 8 [Field] SHUGART NORTH [Location] 1980FNL510FEL [Sec.] N/A [Blk] ____ [Survey] N/A [County] Eddy [St.] New Mexico [Refno] QU3027 [API] 3001526957 [Cost Center] UCT442400 [Section] 8 [Township] 18 S [Range] 31 E [Current Status] ACTIVE [Dead Man Anchors Test Date] NONE [Directions] CIR 265 SX 650- SURFACE h-00 13.375 OD/ 54.50# Unknown Thread 12.815 (TOS - 76) Wellbore Hole OD-17.5000 @(14-422)
Cement (behind Casing) 500sx @(14-422)
Casing Shoe (13.375 OD Casing) @(421-422) P/C/R,115 SX 2, 225-1850 NOC/TAG 60 - 1.000 (1 in.) (Unknown) x 25 Rod @(58-1558) K-40 8.625 OD/ 32.00# 7.921 ID 7.796 Drift @(14-2161) Casing Shoe (8.625 OD Casing) @(2161-2162) Cement (behind Casing) 1300sx @(14-2162) Wellbore Hole OD-12.2500 @(422-2162) Spot 1755X 3,650-2,700 WOC/TAG P/cir Spot 65 SX 4,500-4000 WOC TAG P/cir Cmt from 5250-5100 woc Tag

Casing Shoe (5.500 OD Casing) @(8018-0020) Wellbore Hole OD- 7.8750 @(2162-8622) Cement (behind Casing) 1450sx @(2158-8622) Plug - Cement @(8560-8622)

CIBPE 7,900 W/35 SX 7,600 NOC /TAG/ TEST Form 3160— (Nov. ember 1983) (formerly 9-330)

UN. FED STATES SUBMIT DEPARTMENT OF THE INTERIOR

· SUBMIT IN DUPL, PE+

Form approved. Budget Bureau No. 1004-0137 Expires August 31, 1985

BUREAU OF LAND MANAGEMENT

Expires August 31, 1985

Cuertons on Cyerse side: 5 LEASE DESIGNATION AND SERIAL

de i	.,	1. F.	181.	171.8	IC NA	TION	AND	SERIA	ΝI,	NO.
	:	NM	-33	43	7					
		. IF	IND	145.	., ALI.	OTTE	OR	TRIBE		NE

			OR RECOM		4 KEPORT	AN	D LO	G *		ALLUTTER OR TRIBE NAS		
(a. TYPE OF WEI	LL:	014. WELL	X weel.	DRY L	Other				7. UNIT AGRE	EMENT NAME		
b. TYPE OF COM				.	- -							
WEIT! X		FIN FOR FREE PARTY IN THE FREE	D BACK D	DIFF. RESVE. L.	Other	 -		!	N. FARM OIL I	EASE NAME		
2. NAME OF OPERA	TOR								PMS 8 F	ederal		
Amoco Prodi	uction	Compar	ny 🗸					}	9. WELL NO.			
3. ADDRESS OF OPE							7,	-i		<u> </u>		
P.O. Box 30									10. FIELD AND	D POOL, UB WILDCAT		
4. LOCATION OF WE	_			cordance with	i any State requ	irement	(a) =			Bone Springs,		
At some	1980'	FNL x 5	510' FEL						11. SEC., T., R OR AREA	., M., OR BLOCK AND BURY		
At top prod. int	terval tepo	orted below	r					:	Sec. 8,	T-18-S, R31E,		
At total depth									NMPM			
•			;	14. PERMIT	NO.	DATE	ISSU'ED		12. COUNTY O	R 13. STATE		
						<u> </u>			Eddy	NM NM		
	16. DAT	E T.D. REAC	THED ; 17. DATE (COMPL. (Read	ly to prod.)	S. ELEV	ATIONS (D	17. RKS. RT	. GB. ETC.) .	19. ELEV. CASINGHEAD		
3-7-92		8-92	5-22-				5.8' G					
. TOTAL DEPTH, MD	# TVD		BACK f.b., MD & TV		MULTIPLE COMPI		23. INTE	ERVALS LLED HY	ROTARY TOOL	S CABLE TOOLS :		
8622'		8560) 	N/A			->	Rotary			
. PRODUCING INTER					s (MU AND TVO)		, .,			25. WAS DIRECTIONAL SUBVEY MADE		
Top: 7930'	Botto	n: 8482	: Bone Sp	prings		ا ا مِ	c - 2			Yes		
TYPE ELECTRIC A	YD OFFI	1.000 200								27. WAS WELL CORED		
. Tire Electric /	AND OTHER	, LUMB RIT								No		
				0.550000	Danash all sasi							
CASING SIZE	WEIGH	RT, LB./FT.			Report all string	ja set 17 		ENTRNG RI	ECORD	AMODNE BULLE		
13 3/8"	54.		422'	——— I						AMOUNT PULLED		
8 5/8"	$-\frac{54}{32}$		2162'		7 1/2" 2 1/4"							
5 1/2"	$- \frac{34}{17}$		8620'		7 7/8"	1300 sx class "c" poz 1450 sx class "H"						
- +12	-	а			, ,,,,	-	50 SA					
	'	LI	NER RECORD			. 	30.	<u> </u>	BING RECO	RD		
SIZE	TOP (MI			ACKS CEMENT	r* SCREEN (S	103	SIZE		EPTH SET (MD			
		<u> </u>					2 7/8		7586'	7585'		
					_				/300	7383		
PERFORATION REC	OED (Inte	rval, size (and number)		32.	AC	ID. SHOT	FRACTU	RE. CEMENT	SQUEEZE, ETC.		
7930~84'	833	30- 6 0'			ļ	ACID, SHOT, FRACTURE, CEMENT SQUEEZE, ETC. H INTERVAL (MD) AMOUNT AND KIND OF MATERIAL US						
8008~16'		8-8426	, •		7930~8							
8044-60'		70-82'	W/4 SP	·F					00 gals 30# X- link gel O gals NEFE HCL			
8218-8306'			,	7/00-7802 600					TOO GUED HELL HOU			
•					7	7910		Retri	evable B	ridge Plug		
•	_			P.	RODUCTION							
TE FIRST PRODUCTI	ION	PRODUCT	ION METHOD (Flo	wing, gae lift	, pumping—size	and to	pe of pun	1p)	WELL S	TATUS (Producing or		
5/22/92		Flo	wing							Producing_		
TE OF TEST	HOURS T	ESTED	CHOKE SIZE	PROD'N, FOR			GAS-MC	F	WATER-BBL.	GAS-OIL RATIO		
5/24/92	24	hrs !	27/64		268		300)	13_	1119		
W. TUBING PRESS.	CABING E	PRESSURE	CALCULATED 24-BOUR RATE	OI!BBL	GAS-	-мс₽.		WATER H	IBL.	OIL GRAVITT-API (CORE.)		
225 PSI	0	ĺ	>	268	_	300	[13	i	35.4		
DISPOSITION OF G	AB (Sold, u	sed for fue	il, vented, etc.)						TEST WITNESS	ED BY		
Sold												
LIST OF ATTACHS	STKAL	_ 				<u> </u>						
Logs & devi	ation	survey										
I hereby certify		_		rmation is co	mplete and cor	rect as	determine	d from al	l avallable rec	rords		
		_										
SIGNED X	mid				Asst. A	dmin	Analı	·c+		5/28/92		

Form 3160 SELECTIVED UNITED STATES	FORM APPROVED
(June 1990) DEPARTMENT OF THE INTERIOR	Budget Bureau No. 1004-0135 Expires: March 31, 1993
DEPARTMENT OF THE INTERIOR	5. Lease Designation and Serial No. NM33437
Do not use this form for proposals to drill or to deepen or reentry to a different reservo	6. If Indian, Allottee or Tribe Name
Use "APPLICATION FOR PERMIT—" for such proposals	
SUBMIT IN TRIPLICATE	7. If Unit or CA. Agreement Designation
I. Type of Well Oil Gat Code Well Well Code One	8. Well Name and No.
2. Name of Operator	PMS 8 Federal #8
Amoco Producti n Sospany V	9. API Well No.
3. Address and Telephone No.	30-015-26957
P. O. Box 3092, Houston, TX 77253 Rm. 17.182	10. Field and Pool, or Exploratory Area
4 Location of Well (Foreign, Sec., T., P., M., or Survey Description)	Shugart Bone Springs, North
1980' FNL x 5:0' FLL (Unit H, SE/4, NE/4) Sec. 8, T-18-5, R-31E	Eddy, NM
CHECK APPRATE BOX(s) TO INDICATE NATURE OF NOTICE, REF	
TYPE OF SUMMISSION TYPE OF ACTION	<u> </u>
Abandonment Recompletion	Change of Plans New Construction
Subsequent Primary Plugging Back	Non-Routine Fracturing
Casing Repair	Water Shut-Off
Final Abande onen Stone Altering Casing	Conversion to Injection
☐ Other <u>Spud & set casing</u>	Dispose Water (Note: Report results of multiple completion on Well
13. Describe Proposed or Completed O ₃ stations (Clearly state all pertinent details, and give pertinent dates, including estimated date of stagive subsurface location and massered and true vertical depths for all markers and zones pertinent to this work.)*	Completion or Recompletion Report and Log form.) arting any proposed work. If well is directionally drilled,
Well spud 3/7/ 2	
Drilled to 422'. Fan 13.625", 54.5# casing. Cemented with 500 S and 2% CACL2. Circulated 95 sxs cmt to pit. WOC 20 hrs.	SX class 'C' cmt
Drilled to 216. '. Ran 50 joints 8.625", 32#, K-55, LT&C casing. Cemented casin; w/ 1100 sx class "C" poz at 65:35 w/ 2% gel, 12. 0.25#/sk ceilollate. 200 sx class "C" w/2% CACL. Circulated 12 Tagged cmt at 4020'. Tested csg to 1000# for 30 min test 0K.	.5#/sk salt, 2% CACL, ?9 sx cmt. NOC 18½ hrs.
TD at 8620° . Tan 202 joints $17\#$, K-55, LT&C casing. Casing set casing with $12\%0$:x class 'H' at $65:35$ poz. Tail in with 350 sy	C Class 'H'.
Rig released 3 29 92.	<u></u>
14. I hereby certify that the force this is true and correct	
Signed Kim A. Tallu Title Asst. Administrative Anal	yst Date 4/3/92
(This space for Federal or State office use)	
Approved by Title Title Title Total and the conditions of approval, if an Title Total and Total and Title Total and	Date
Title 18 U.S.C. Section 1001, modes is a crime for any person knowingly and willfully to make to any department or agency of the U or representations as to any control within its periodiction.	nited States any false. Fictitious or fraudulent statements



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
 Operations must include adequate measures for stabilization and reclamation of disturbed lands.
 Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
 process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.

- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.
- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Linda Denniston
Environmental Protection Specialist
575-234-5974

Henryetta Price Environmental Protection Specialist 575-234-5951

Dara Glass
Environmental Protection Specialist
575-234-5924

Shelly Tucker Environmental Protection Specialist 575-234-5979

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

- 7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:</u>
From March 1st through June 15th annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted