District 1
1625 N. French Dr., Hubbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action												
NAB1412454732						OPERA	X	🔀 Initial Report 🔲 Final Repor				
						Contaci	Leslie Garvis					
				it 9, Fort Worth, TX	Telephone No. 817-583-8730							
Facility Nar			neny or on									
					Pacility Type Tank Battery							
Surface Owner BLM Mineral Owner						BLM	A	API No. 30-015-38373				
LOCATION OF RELEASE												
Unit Letter	Section	Township	Range	Feet from the		South Line	Feet from the	East/West	Line (County		
м	13	175	30E	1219	Sou	lh	54'	West	West Eddy			
LatitudeLongitude												
NATURE OF RELEASE												
Type of Release Oil/Water Volume of Release 1 BO/ 3 BW Volume Recovered 0 BO/ 0 BW												
Source of Re			•				lour of Occurrence			our of Dis		And the second se
Was Immediate Notice Given?						If YES, To Whom?						
By Whom? Johnny Titsworth						Date and H	lour 4/23/16	1005 & 1010)			
Was a Water				······································			lume Impacting	he Waterco	urse.			
			Yes 🗴	} No								
If a Watercon	irse was Im	pacied, Deser	ibe Fully.*	,		/			VM Ou			
NA OIL CONSERVATION											1	
									AR	TESIA DI	STO.	ATION
									M.	AV a		.т
Deceritie Cou	co of Broble	m and Pama	dial Antin	Talaa é				<u> </u>		<u>. UZ</u>	-2016	<u> </u>
Describe Cause of Problem and Remedial Action Taken." Poly flowline ruptured before the header. Line was repair and returned to service.												
Poly towine ruptured before the neader. Line was repair and returned to service.												
Neresthe Are	A Disease of		A									
Describe Area Affected and Cleanup Action Taken.* 30' x 50' area in pasture was affected as well as 10' x 10' overspray area on the pad. Area will be remediated to regulatory standards.												
	•							•				
I hereby certi	ify that the i	information g	iven above	is true and comp	dete to th	te best of my	knowledge and i	Inderstand U	hai pursu	ant to NM	OCD	rules and
regulations a	li operators	are required (o report a	nd/or file certain i ce of a C-141 repo	elease no	SUMPER D	nd periorm correction	crive actions	not celies	ses which	may e	noanger Gliability
public nearli	of the crivi	noniment. Inc	adaoustely	investigate and f	on by the	: NIWOCD III	ion that nose a th	reat lo proju	al water.	surface w	ater, h	uman health
or the enviro	nment. In a	addition. NM(DCD accer	ptance of a C-141	report de	oes not reliev	e the operator of	responsibili	ty for cor	mpliance v	vith ar	ny other
federal, state	. or local la	ws and/or reg	ulations.							<u>•</u>		
The second secon			7				OIL CON	SERVA [*]	<u>רוסא ו</u>	DIVISIO	NC	
	10.11	is below	PIG		1				:1			
Signature: Jeans Num					Approved by Environmental Specialist							
Printed Name:						Approved by	Environmental S	specialist	rf/	IL	\sim	
Desule	tan Coordia		•				EIELICO			N//	2	
Title: Regulatory Coordinator					+-	Approval Da		Exp	uration D	ate: N/	<u> </u>	
E-mail Address: Igarvis@burnettoil.com						Conditions of Approval: Remediation per O.C.D. Rules & Guidaling&						
						بمالين ا		D. Rules		LINGUINUHER LIN	υ	
Date: 5/2/16			Phone	817-583-8730		SUBMIT	REMEDIATIC	N PHUP	USAL	<u></u>		<u> </u>
' Attach Addi	itional She	ets If Neces	sary			LATER T	HAN:	<u>ין או</u> רי	<u> </u>		うる	P-3676
$=$ $\qquad =$ $\qquad \qquad \qquad$												