NM OIL CONSERVATION

ARTESIA DISTRICT

SEP 28 2016

Form C-141 Revised August 8, 2011

SREEFERED appropriate District Office in accordance with 19.15.29 NMAC.

District | 1625 N. French Dr., Hobbs, NM 88240 **Energy Minerals and Natural Resources** District III 1000 Rio Brazos Road, Aztec, NM 87410

District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

District II 811 S. First St., Artesia, NM 88210

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

State of New Mexico

Release Notification and Corrective Action													
NAB1627447992						OPERATOR			Initia	al Report	П	Final Report	
Name of Company Oxy Permian Ltd. 1000						OPERATOR Initial Report Final Report							
						Telephone No. (575) 513-8289							
Facility Name Federal 12 #004						Facility Type Well							
Surface Owner BLM Mineral Owner							API No. 30-015-26859						
LOCATION OF RELEASE													
Unit Letter	Section	Township	Range	Feet from the	North/	South Line	Feet from the	East/West	West Line County				
E 12 22S 31E						······································	-,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			Eddy Cou	nty. NA	4	
Latitude <u>N 32.40783</u> ° Longitude <u>W 103.73890</u> °													
NATURE OF RELEASE													
Type of Release Oil and Produced water						Volume of Release 2 bbls oil, Volume Recovered 5 bbls 13 bbls produced water							
Source of Release Over pressure caused the stuffing box packing to blow out						Date and H 06/06/2016	Date and Hour of Occurrence Date and Hour of Discovery 6/06/2016						
Was Immediate Notice Given?						If YES, To Whom? Mike Bratcher, Heather Patterson- NMOCD; Shelly Tucker- BLM							
By Whom?	Kathy@ B	BC Internatio	nal, Inc.			Date and Hour 06/07/2016 @ 9:15 am							
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.							
If a Watercourse was Impacted, Describe Fully.*													
Describe Cause of Problem and Remedial Action Taken.*													
Over pressure caused the stuffing box packing to blow out and release 2 bbls of oil and 13 bbls of produced water. A vacuum truck recovered 5 bbls and the packing was replaced.													
	-												
Describe Are	a Affected	and Cleanup.	Action Ta	ken.*									
The affected area is approximately 40' x 25' on location around the well head. Remediation will be completed in accordance with a plan approved by both NMOCD and the BLM.													
NMUCD and													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability													
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
Teuerai, state	<u>h</u>	wp aller of reg					OIL CON	SERVA	TION	DIVISI	ON		
Signature:					Approved by Environmental Specialist & Brander								
Printed Name: Casey Summers						Approved by Environmental Apeciansi:							
Title: NM Environmental Advisor						Approval Date: 9/29/11 Expiration Date: N/A							
E-mail Address: Casey_Summers@oxy.com							Conditions of Approval:						
						Remediation per O.C.D. Rules & Guidelines 🗀							
Date: $(0 - 2) - (0 - 10)$ Phone: (575) 513-8289						SUBMIT REMEDIATION PROPOSAL NO							
Attach Additional Sheets If Necessary LATER THAN: 114110 2RP-3918													