istrict II 11 S. First St., Artesia, NM 88210	tate of New Mexico Inerals and Natural Resources OCT 07 2016 Revised August 8, 20
istrict III 100 Rio Brazos Road, Aztec, NM 87410 1220 1220	Conservation Division 0 South St. Francis Dr. Submit 1 Copy to appropriate District Office RECEIVED <sup>accordance</sup> with 19.15.29 NMA
<u>an an a</u>	Santa Fe, NM 87505
	ication and Corrective Action
NAB1628631827	OPERATOR Initial Report I Final Re
Name of Company: COG Operating LLC 229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701 Facility Name: SUPERFORTRESS 29 FEDERAL #003H	Telephone No. 432-230-0077 Facility Type: Battery
Surface Owner: Federal Mineral (	Owner: Federal   API No. 30-015-38642
LOC	ATION OF RELEASE
Unit Letter Section Township Range Feet from the <u>C</u> 29 19S 31E 330	North/South Line Feet from the 2200 East/West Line County Eddy
32	2.6377373,-103.8928909
	TURE OF RELEASE
Type of Release: Produced Water	Volume of Release: Volume Recovered: 10 bbls Produced Water 7 bbls Produced Water
Source of Release:	Date and Hour of Occurrence: Date and Hour of Discovery:
Vas Immediate Notice Given?	9/30/2016 unknown 9/30/2016 12:01 PM 1f YES, To Whom?
Yes IN No X Not R	
By Whom?	Date and Hour:
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.
· 이상, 영상, 영양, 동안, 영양, 영양, 영양, 영양, 영양, 영양, 영양, 영양, 영양, 영양	
Describe Cause of Problem and Remedial Action Taken.* This release was caused by a hole in a check valve. The damage	ed check valve was replaced to prevent incident from occurring again.
This release was caused by a hole in a check valve. The damage Describe Area Affected and Cleanup Action Taken.* This battery occurred within a lined facility. Vacuum trucks were	re immediately dispatched to recover standing fluid and the contaminated gravel has been cted for any possible contamination from the release and we will present a remediation
This release was caused by a hole in a check valve. The damage Describe Area Affected and Cleanup Action Taken.* This battery occurred within a lined facility. Vacuum trucks were eplaced with fresh gravel. Concho will have the spill site inspect work plan to the NMOCD for approval prior to any significant re hereby certify that the information given above is true and comp egulations all operators are required to report and/or file certain bublic health or the environment. The acceptance of a C-141 rep hould their operations have failed to adequately investigate and the	re immediately dispatched to recover standing fluid and the contaminated gravel has been cted for any possible contamination from the release and we will present a remediation
This release was caused by a hole in a check valve. The damage Describe Area Affected and Cleanup Action Taken.* This battery occurred within a lined facility. Vacuum trucks were eplaced with fresh gravel. Concho will have the spill site inspect vork plan to the NMOCD for approval prior to any significant re hereby certify that the information given above is true and comp egulations all operators are required to report and/or file certain bublic health or the environment. The acceptance of a C-141 rep hould their operations have failed to adequately investigate and to r the environment. In addition, NMOCD acceptance of a C-141	re immediately dispatched to recover standing fluid and the contaminated gravel has been cted for any possible contamination from the release and we will present a remediation emediation work. The best of my knowledge and understand that pursuant to NMOCD rules and release notifications and perform corrective actions for releases which may endanger port by the NMOCD marked as "Final Report" does not relieve the operator of liability remediate contamination that pose a threat to ground water, surface water, human health
This release was caused by a hole in a check valve. The damage Describe Area Affected and Cleanup Action Taken.* This battery occurred within a lined facility. Vacuum trucks were eplaced with fresh gravel. Concho will have the spill site inspect work plan to the NMOCD for approval prior to any significant re hereby certify that the information given above is true and comp egulations all operators are required to report and/or file certain bublic health or the environment. The acceptance of a C-141 rep hould their operations have failed to adequately investigate and to re the environment. In addition, NMOCD acceptance of a C-141	re immediately dispatched to recover standing fluid and the contaminated gravel has been cted for any possible contamination from the release and we will present a remediation emediation work. The plete to the best of my knowledge and understand that pursuant to NMOCD rules and release notifications and perform corrective actions for releases which may endanger port by the NMOCD marked as "Final Report" does not relieve the operator of liability remediate contamination that pose a threat to ground water, surface water, human health 1 report does not relieve the operator of responsibility for compliance with any other
This release was caused by a hole in a check valve. The damage Describe Area Affected and Cleanup Action Taken.* This battery occurred within a lined facility. Vacuum trucks were eplaced with fresh gravel. Concho will have the spill site inspect vork plan to the NMOCD for approval prior to any significant re hereby certify that the information given above is true and comp egulations all operators are required to report and/or file certain bublic health or the environment. The acceptance of a C-141 rep hould their operations have failed to adequately investigate and to r the environment. In addition, NMOCD acceptance of a C-141 ederal, state, or local laws and/or regulations.	re immediately dispatched to recover standing fluid and the contaminated gravel has been cted for any possible contamination from the release and we will present a remediation emediation work. The plete to the best of my knowledge and understand that pursuant to NMOCD rules and release notifications and perform corrective actions for releases which may endanger port by the NMOCD marked as "Final Report" does not relieve the operator of liability remediate contamination that pose a threat to ground water, surface water, human health 1 report does not relieve the operator of responsibility for compliance with any other
This release was caused by a hole in a check valve. The damage Describe Area Affected and Cleanup Action Taken.* This battery occurred within a lined facility. Vacuum trucks were eplaced with fresh gravel. Concho will have the spill site inspect vork plan to the NMOCD for approval prior to any significant re hereby certify that the information given above is true and comp egulations all operators are required to report and/or file certain bublic health or the environment. The acceptance of a C-141 rep hould their operations have failed to adequately investigate and to ir the environment. In addition, NMOCD acceptance of a C-141 ederal, state. or local laws and/or regulations. Printed Name: Dakota Neel	re immediately dispatched to recover standing fluid and the contaminated gravel has been cted for any possible contamination from the release and we will present a remediation emediation work.
This release was caused by a hole in a check valve. The damage Describe Area Affected and Cleanup Action Taken.* This battery occurred within a lined facility. Vacuum trucks were eplaced with fresh gravel. Concho will have the spill site inspect work plan to the NMOCD for approval prior to any significant re hereby certify that the information given above is true and comp egulations all operators are required to report and/or file certain to bublic health or the environment. The acceptance of a C-141 rep hould their operations have failed to adequately investigate and to r the environment. In addition, NMOCD acceptance of a C-141 ederal, state. or local laws and/or regulations.	re immediately dispatched to recover standing fluid and the contaminated gravel has been cited for any possible contamination from the release and we will present a remediation emediation work.