B	DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT				ATORS CORMAPPROVED OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Serial No.		
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					NMNM0557371 6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No. 8910138010 NM 70945 x		
I. Type of Well					8. Well Name and No.		
Contact: ISABEL HUDSON					9. API Well No.		
APACHE CORPORATION - E-Mail: Isabel.Hudson@apachecorp.com					9. APT well No. 30-015-01215-0	00-51	
3a. Address 303 VETERANS AIRPARK L/ MIDLAND, TX 79705	3b. Phone N Ph: 432-8	o. (include area code) 18-1142)	10. Field and Pool, or Exploratory EMPIRE			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, and State		
Sec 1 T18S R27E NENE 667FNL 666FEL					EDDY COUNTY, NM		
12. CHECK APP	ROPRIATE BOX(ES) TO	O INDICATI	E NATURE OF 1	NOTICE, R	EPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
	Acidize	D e	🗋 Deepen		tion (Start/Resume)	U Water Shut-Off	
Notice of Intent	Alter Casing	🖸 Fra	Fracture Treat		ation	Well Integrity	
Subsequent Report	🗖 Casing Repair	🗖 Ne	New Construction		Recomplete Other		
Final Abandonment Notice	Change Plans	🗖 Plu	g and Abandon	🔀 Temporarily Abandon			
	Convert to Injection	🖸 Plu	Plug Back Water Dispo		Disposal		
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involvec testing has been completed. Final Al determined that the site is ready for f Apache would like to perform	rk will be performed or provide i operations. If the operation re bandonment Notices shall be fil inal inspection.)	e the Bond No. o	n file with BLM/BIA	 Required su 	bsequent reports shall be	filed within 30 days	
Objective: Isolate open perfs	and TA wellbore		SIA DISTRICT	ION			
Procedure: 1. POOH with rods and tbg 2. Set CIBP @ 5,740? and du 3. Fill casing with fluid and pre-	DEC 16 2016			Apache Corp			
4. Record the test on a chart and submit for approval RECEIVED SE					EE ATTACHED FOR		
PLEASE SEE ATTACHMENT	·s	ccented	tor record	CONDI	FIONS OF AP	PROVAL	
FLEAGE GLE ATTACHMENT	5.		CORE 12	19/16			
14. I hereby certify that the foregoing is	# Electronic Submission For APACH	E CORPORAT	10N. sent to the	Carlsbad	-		
Committed to AFMSS for processing by PRISCILLA F Name (Printed/Typed) ISABEL HUDSON Title				NALYST			
Signature (Electronic S	Date 10/13/2		and a state of the				
	THIS SPACE FO	OR FEDER	AL OR STATE	OFFCE U	SEAPPRO	VFD	
05							
Approved By Conditions of approval, if any, are attached. Approval of this notice does not warrant o			Title			Date	
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to condu- te the applicant to condu-	Office		NOV 29	2016			
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a statements or representations as	crime for any p to any matter v	erson knowingly and vithin its jurisdiction.	l willfully to m	RUREALL OF LAND		
** BLM REV	ISED ** BLM REVISEI	D ** BLM R	EVISED ** BLN	REVISE		D_OFFICE	

≮*:

,

October 12, 2016

٠.


r'

Empire ABO Unit # I-20 API # 30-015-01215 Eddy County, NM Surface Casing: 8-5/8" 24# Set @ 1,483' Production Casing: 4-1/2" 9.5# Set @ 6,114' Producing Interval: 5,783-6,064'

Objective: Isolate open perfs and TA wellbore

Procedure:

- 1. POOH with rods and tbg
- 2. Set CIBP @ 5,740' and dump bail 35' of cmt
- 3. Fill casing with fluid and pressure test to 500 psi.
- 4. Record the test on a chart and submit for approval



J

<u>Conditions of Approval</u> Apache Corporation Empire Abo Unit 1 - 20, API 3001501215 T18S-R27E, Sec 01, 667FNL & 666FEL November 29, 2016

Operator is to have the BLM approved NOI procedure with applicable conditions of approval on location for this workover operation.

No record of the braden head squeeze claimed by the Apache wellbore diagram of 10/12/2016 has been found. Submit a dated record of that workover as a BLM sundry.

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well.

Temporary Abandonment (TA) BLM Status Approval Requires:

...

- 1. A Notice of Intent (NOI) Sundry (Form 3160-5) requesting approval to prepare the wellbore for a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A subsequent sundry report that describes compliance with:
 - a. All downhole production artificial lift equipment (tubing, rods, etc.) removed from the casing. A wellbore with a packer set just above producing or injection perforations with annulus integrity above the packer, and loaded with corrosion inhibiting fluid may be considered for TA status by passing a Mechanical Integrity Test.
 - b. The wellbore below all potential production is to be plugged back per permanent plugging procedures. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. A CIBP set above the top perforations to be permanently abandoned is to be capped with a minimum of 25 sacks cement and placed with tubing, or if the perforations are to be reopened 35 feet of cement may be bailed on the CIBP.
 - c. The wellbore filled with corrosion inhibited fluid.
 - d. At least 24 hours prior to conducting the Mechanical Integrity Test, contact the appropriate BLM office. Eddy County call Carlsbad 575-361-2822.
 - e. Documentation of a 500psig minimum BLM witnessed Mechanical Integrity Test on a one hour full rotation calibrated (within 6 months) recorder chart registering within 35 to 75 per cent of its full range. Greater than 10% pressure leakoff will be viewed as a failed MIT. Verify all annular casing vents are plumbed to surface and those valves open to the surface during this pressure test. Pressure leakoff will be evaluated site specifically and affect approvals.

- 3. Submit a Subsequent Sundry Notice (Form 3160-5) requesting TA approval with a description of the preparation for temporary abandonment approval, a clear copy or the original Mechanical Integrity Test chart, a current wellbore diagram, and **justification** for not plugging. Justification is listing the proposed beneficial use and reasonable expected dated events to initiate a conversion to beneficial use. Often overlooked is a backlog of wells that have no potential beneficial use (should have been plugged and abandoned) that create a status surplus.
- 4. This BLM TA NOI Approval is for WELLBORE PREPARATION ONLY. BLM IS NOT APPROVING TA Status FOR THIS WELL. If warranted, TA approval status for a specified time limit will be noted with BLM acceptance of the subsequent report of preparations and justification.
- 5. Workover approval is good for 90 days (completion to be within 90 days of approval).

.

6. Should Mechanical Integrity Test not prove wellbore integrity or not be conducted submit a procedure to repair or plug and abandon the well for BLM approval within 30 days of the MIT.