Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB NO. 1004-0137

	Expires:	January	
Lease Se	rial No.		

BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS						auary 31, 2010		
					5. Lease Serial No. NMLC065478B			
Do not use this form for proposals to drill or to re- abandoned well. Use form 3160-3 (APD) for such p					6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No. NMNM70945X			
1. Type of Well					8. Well Name and No. EMPIRE ABO UN	T 11A		
☑ Oil Well ☐ Gas Well ☐ Oth		ISABEL HUD	2001					
2. Name of Operator APACHE CORP	orbicow DION		9. API Weil No. 30-015-00748					
3a. Address 303 VETERANS AIRPARK LA MIDLAND, TX 79705	. (include area code) 8.1142		10. Field and Pool or Exploratory Area EMPIRE; ABO (22040)					
4. Location of Well (Foolage, Sec., T			11. County or Parish, State					
Sec 3 T18S R27E 2310FNL 1			EDDY COUNTY, NM					
12. CHECK THE AL	PROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	ER DATA		
TYPE OF SUBMISSION		TYPE OF ACTION						
⊠ Notice of Intent	☐ Acidize	□ Dce	pen	☐ Product	ion (Start/Resume)	☐ Water S	hut-Off	
_	Alter Casing	☐ Hyd	raulic Fracturing	☐ Reclam	ation	☐ Well Int	egrity	
☐ Subsequent Report	□ Casing Repair	☐ Nev	Construction	☐ Recomplete		☐ Other		
☐ Final Abandonment Notice	☐ Change Plans	🗀 Piug	g and Abandon	☐ Tempore	☐ Temporarily Abandon			
	☐ Convert to Injection	☐ Plug	_		•			
13. Describe Proposed or Completed Op If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for the Apache would like to perform Producing Interval: 5,492-548	the following work. Pleas 7; 5,620-64?		nents.	epted f	Or record NA	/ OIL 60	ed once rhas NSERVATO DISTRICT	
Production Casing: 4-1/2? 9.5	# @ 5,735?		NMOCD ET			FFR 1	L 0 2017	
Objective: TA wellbore. Curre require time to gather and ana	ntly evaluating the upper Blyze reservoir data in the	ABO for re-co field.	ompletion in the a	area. We	2/13/17	140)	10 2017	
Procedure: 1. POOH with rods and pump 2. Release TAC and POOH scanning tbg and mark junk pipe 3. MIRU wireline			SEE ATTACHED FOR RECI			EIVED		
			CONDITIONS OF APPROVAL					
14. I hereby certify that the foregoing is	# Electronic Submission For AP	ache corp,	sent to the Carls	bad	_			
Name (Bristod/Broad) ICADEL L	Committed to AFMSS for	processing by						
Name (Printed/Typed) ISABEL H	IODSON		THE REGUL	ATORY AN	ALTSI			
Signature (Electronic	Submission)	Date 11/21/2016						
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE U	SE			
Approved By	Q.Como	···· — —	Title 5	PET		Z- Date	7-17	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office C	10				

Operator Copy

Title [8 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any relate, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #358548 that would not fit on the form

32. Additional remarks, continued

- 4. RIH with CIBP and set @ 5,488? w/ 35? of cmt
 5. Circulate fluid in the well
 6. Pressure test casing to 500 psi
 7. Record chart and submit for approval



November 18, 2016

Empire ABO Unit # J-11 API # 30-015-00748

Legal Name: Empire ABO Unit #011A

Eddy County, NM

Producing Interval: 5,492-548'; 5,620-64' Production Casing: 4-1/2" 9.5# @ 5,735'

<u>Objective</u>: TA wellbore. Currently evaluating the upper ABO for re-completion in the area. We require time to gather and analyze reservoir data in the field.

Procedure:

- 1. POOH with rods and pump
- 2. Release TAC and POOH scanning tbg and mark junk pipe
- 3. MIRU wireline
- 4. RIH with CIBP and set @ 5,488' w/ 35' of cmt
- 5. Circulate fluid in the well
- 6. Pressure test casing to 500 psi
- 7. Record chart and submit for approval

Apache Corp. Actual LEASE/UNIT: Empire Abo Unit DATE: Nov. 08, 2016 WELL: #J-11A (#011A) BY: HJG API NUMBER: 30-015-00748 COUNTY: Eddy LEGAL DESCRIPTION: Sec 3, T18S, R27E STATE: New Mexico FIELD: Empire (BP) KB = 3565'Spud: 8/4/59 GL ≈ Rig Release: 8/24/59 12 1/4" 8-5/8" 24# J-55 Set @ 1486' CMT 700 SX TOC @ ?? 4-1/2" 9.5# J-55 Set @ 5735' CMT W/ 850 SX TOC @ ??? 6/77: Bradenhead to surface 7-7/8" 2 3/8 TBG TAC @ 5437' SN @ 5630' ABO (3/96) Perf: 5492-5548' (2 SPF; 112 holes) ABO (8/59) Perf: 5620-64' (2 SPF) 3/96: Az w/ 2000 gal 50/50 & BS Formation Tops: Queen -Grayburg -TD = 5720' San Andres - 1610 PBTD = 5685' Glorieta - 3020 Abo - 5360

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. The bridge plug is to be capped with 35 feet of cement (if bailed) or 25 sacks (if placed with tubing). If a cement plug is used, the top of the cement must be verified by tagging.
 - b. The wellbore must be filled with corrosion inhibited fluld and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass-the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

- Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Well Name: Submit Subsequent Report and well bore diagram with all Perforations and CIBP with tops of cement. Well may be approved to be TA for a period of 1 year after successful MIT and subsequent report is submitted.