Form 3160-5 (June 2015)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Operator Copy

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

BUREAU OF LAND MANAGEMENT  SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				5. Lease Serial No. NMLC065478B  6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Agreement, Name and/or No. NMNM70945X			
Type of Well	er				8. Well Name and No. EMPIRE ABO UN		-
2. Name of Operator	Contact:	ISABEL HU	DSON		9. API Well No.		
APACHE CORP	E-Mail: (sabel.Hud				30-015-22833		
3a. Address 303 VETERANS AIRPARK LANE SUITE 1000 MIDLAND, TX 79705  3b. Phone No. Ph: 432.81			o. (include area code) 18.1142	-	10. Field and Pool or Exploratory Area EMPIRE; ABO (22040)		
4. Location of Well (Footage, Sec., T	, R., M., or Survey Description	)			11. County or Parish,	State	
Sec 11 T18S R27E 450FNL 1	175FWL .				EDDY COUNT	Y, NM	
12. CHECK THE A	PROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OT	HER DA	TA
TYPE OF SUBMISSION			TYPE OF	ACTION			,
Notice of Intent	☐ Acidize	□ D∝	pen	☐ Producti	on (Start/Resume)	□ Wa	ter Shut-Off
_	☐ Alter Casing	□ Ну	draulic Fracturing	☐ Reclama	ation	□ We	ll Integrity
☐ Subsequent Report	Casing Repair	_	w Construction	☐ Recomp		Oth	er
☐ Final Abandonment Notice	Change Plans		g and Abandon		arily Abandon		
	Convert to Injection		g Back	☐ Water D		<del></del>	
13. Describe Proposed or Completed Op If the proposal is to deepen directions Attach the Bond under which the wo following completion of the involved testing has been completed. Final At determined that the site is ready for fi	andonment Notices must be fil inal inspection.	suits in a miliop led only after all	requirements, includ	empletion in a r ling reclamation	rtical depths of all perti- sequent reports must b new interval, a Form 31: n, have been completed	and the ope	erator has
Apache would like to perform	ine following work. Please	e see attachr	nents.		CDA	ARTESIA	DISTRICT
Production Casing: 5-1/2? 15.5# K-55 Set @ 6,225? Producing Interval: 5,966-6,064?				NIVIO &	113/17	FEB 1 0 2017	
Objective: Isolate open perfs a	and TA wellbore. Well bel	ng evaluated	for recompletion	potential	•	1	. 0 ==
Procedure: 1. POOH with rods and tbg 2. Scan tbg and mark junk pip 3. Set CIBP @ 5,940? and du	e mp bail 35? of cmt				EE ATTACHE ONDITIONS		
14. I hereby certify that the foregoing is	Electronic Submission #	358642 verifie	d by the BLM Wel	l Information	System '		
•	For APA Committed to AFMSS for a	ACHE CORP, processing by	sent to the Carlsi DEBORAH MCKI	bad NNEY on 12/	13/2016 ()		
Name (Printed/Typed) ISABEL H	UDSON		Title REGUL	ATORY ANA	ALYST		
Signature (Electronic S	ubmission)		Date 11/21/20	016			
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE US	SE		
Approved By	a. am	2	Title 5%	PET		i	2.7-17 alc
Conditions of approval, if any, are attached certify that the applicant holds legal or equ which would enjoid the applicant to condu	itable title to those rights in the	not warrant or subject lease	Office	0			<u>-</u>

Tile 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictilious or fraudulent statements or representations as to any matter within its jurisdiction.

# Additional data for EC transaction #358642 that would not fit on the form

- 32. Additional remarks, continued
- Fill casing with fluid and pressure test to 500 psi
   Record the test on a chart and submit for approval



November 21, 2016

Empire ABO Unit # M-133 Legal Name: Empire ABO Unit #1338 API # 30-015-22833 Eddy County, NM

Production Casing: 5-1/2" 15.5# K-55 Set @ 6,225'

Producing Interval: 5,966-6,064'

Objective: Isolate open perfs and TA wellbore. Well being evaluated for recompletion potential

## Procedure:

- 1. POOH with rods and tbg
- 2. Scan tbg and mark junk pipe
- 3. Set CIBP @ 5,940' and dump bail 35' of cmt
- 4. Fill casing with fluid and pressure test to 500 psi
- 5. Record the test on a chart and submit for approval

Apache Corp. Actual					
LEASE/UNIT: WELL: API NUMBER: LEGAL DESCRIPTION: FIELD:	Empire Abo Unit M-133 30-015-22833 Sec 11, T18S, R27E Empire (BP)	DATE: BY: COUNTY: STATE:	Nov. 18, 2016 HJG Eddy New Mexico		
Spud: 5/23/79 Rig Release:		KB = GL =			
11"	8-5/8" 24# K-55 Set @ 1000 CMT 500 SX CIRC SURF				
7-7/8"	5-1/2" 15.5# K-55 Set @ 622 CMT W/ 1400 SX CIRC SU				
	DV tool @ 3995'		·		
	ABO (5/92) Perf: 5966-76' (2 SPF) 5/92; Az w/ 1500 ga)				
	ABO (5/92) Perf: 5998-6010' (2 SPF) 5/92: Az w/ 1400 gal				
	ABO (6/79) Perf: 6044-64' (2 SPF) 6/79: 150 gal 15%, 1000 gal 1	0# gelled CaCl wtr, 1500 g	Formation Tops:		
TD = 6225' PBTD = 6180'			Queen - Grayburg - San Andres - Glorieta -		

#### BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

### Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
  - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. The bridge plug is to be capped with 35 feet of cement (if bailed) or 25 sacks (if placed with tubing). If a cement plug is used, the top of the cement must be verified by tagging.
  - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
  - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
  - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
  - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- Provides justification why the well should be temporarily abandoned rather than
  permanently plugged and abandoned and an estimated date that the well will be returned
  to beneficial use or plugged and abandoned.

Wells that successfully pass-the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

- Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram.
- Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Well Name: Submit Subsequent Report and well bore diagram with all Perforations and CIBP with tops of cement. Well may be approved to be TA for a period of 1 year after successful MIT and subsequent report is submitted.