Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District I = (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N French Dr., Hobbs, NM 88240		WELL API NO. 30-015-22657
<u>District II</u> - (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III (505) 334-6178	1220 South St. Francis Dr.	STATE FEE
1000 Rio Brazos Rd , Aztec, NM 87410 District IV - (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S St. Francis Dr., Santa Fe, NM	·	
87505	ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
	CATION FOR PERMIT* (FORM C-101) FOR SUCH	EMPIRE ABO UNIT [309164]
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other	8. Well Number #K-193 (193)
2. Name of Operator	Odd Well Oller	9. OGRID Number
Apache Corporation		873
3. Address of Operator		10. Pool name or Wildcat
303 Veterans Airpark Lane, Suite 10	000 Midland, TX 79705	[22040] EMPIRE; ABO
4. Well Location		4 (10)
Unit Letter J:	2490 feet from the FSL line and 220	00 feet from the FEL line
Section 1	Township 18S Range 27E	NMPM County EDDY
The same of the sa	11. Elevation (Show whether DR, RKB, RT, GR, etc.	
	3642.7' GR	(1965) (1
12. Check A	Appropriate Box to Indicate Nature of Notice,	Report or Other Data
		•
NOTICE OF IN		SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WOR	
TEMPORARILY ABANDON		ILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEMEN	T JOB
DOWNHOLE COMMINGLE		
CLOSED-LOOP SYSTEM OTHER:	□ OTHER:	П
	leted operations. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date
of starting any proposed wo	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Co	mpletions: Attach wellbore diagram of
proposed completion or rec	ompletion.	•
Apache completed the following work:		
Producing Interval 5,676-6,160'		
Objective: TA Wellbore: Currently per bring it back to production.	forming geological & petrophysical studies to determine	feasibility for recompletion. Evaluating wellbore to
Procedure:		
1. POOH with rods & pump	NM O	IL CONSERVATION
2. Scan tbg & mark junk pipe		ARTESIA DISTRICT
 Set CIBP@5,626' & dump bail 35' o Circ fluid & pressure test casing to ! 	// Citt	
5. Record the test on a chart & submit		MAR 0 8 2017
	TA status may be granted after a	RECEIVED
	successful MIT test is performed.	
	Contact the OCD to schedule the test	
Spud Date:	so it may be witnessed.	
	LAST PROP 3/1/2016	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
	0.4	
SICNATURE TAG	TITLE Reg Analyst	n . mm 03/03/2017
SIGNATURE / K	TILE Reg Allalyst	DATE 03/03/2017
Type or print name Emily follis	E-mail address: Emily follis@apach	ecorp.com PHONE: (432) 818-1801
For State Use Only	L-man addiess.	THUNE, (100)
	NGE TITLE COMPLIANCES	OFFICERLDATE 3/10/17
Conditions of Approval (if any):		

Apache Corp. Current FIELD: Empire (BP) DATE: Mar. 02, 2017 LEASE/UNIT: **Empire ABO Unit** BY: MM COUNTY: Eddy WELL: 193 API: 30-015-22657 **New Mexico** STATE: Spud Date: 9/29/1978 GR Elevation = 3,642' Completion Date: 10/26/1978 Conv. To Injection Date: J-01-185-27E, 2490 FSL & 2200 FEL 8-5/8" 24# @ 1,006' w/ 525 sxs 5,676-774' (4/30/97) 5,799-808'; 5,818-22'; 5,826-39'; 5,846-65'; 5,890-904'; 5,911-23' - (6/17/02) 5,930-31'; 5,934-38'; 5,950-54'; 5,963-71'; 5,978-81'; 5,984-87' - (6/17/02) 6,061-78'; 6,101-18' - (6/17/02) 6,003-30' (4/23/97) CIBP @ 6,140' (4/23/97) 6,150-60' (10/26/78) 5-1/2" 15.5# K-55 @ 6,225' w/ 1,170 sxs TD 6225' PBTD 6200' NOTE: wellbore diagram not to scale

State of the state

March 2, 2017

Empire ABO Unit # K-193 Legal Name: Empire ABO Unit #193 API # 30-015-22657 Eddy County, NM Producing Interval: 5,676-6,160'

<u>Objective</u>: TA Wellbore. Empire Abo Unit is a former gas injection project. We are actively exploring feasibility of re-pressuring for water flood purposes. This evaluation involves extensive geology and engineering review of the entire unit. Without the proper geological analysis, we stand a chance to lose valuable resources by prematurely plugging the well at this time.

Procedure:

- 1. POOH with rods and pump
- 2. Scan tbg and mark junk pipe
- 3. Set a CIBP @ 5,626' and dump bail 35' of cmt
- 4. Circulate fluid and pressure test casing to 500 psi
- 5. Record the test on a chart and submit to OCD for approval